



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL Ref : CS/AGI18011529/Kvd3n2

(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 10-09-2018



Code : AGI

### 1. Policy Particulars :- OWN DAMAGE

<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SKS 6408M
<b>Policy No.</b>	P100054898R00	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10001700/JM	<b>Excess (\$)</b>	600.00
<b>Assign From</b>	JULIE MANGUBAT	<b>Assign Date</b>	25/06/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 3 (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JM6BM42A8F0165443	<b>Colour</b>	METALLIC RED
<b>Odometer</b>	35524	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	TOYO	8 mm
<b>L/H Front Tyre</b>	205/60 R16	TOYO	8 mm
<b>R/H Rear Tyre</b>	205/60 R16	TOYO	8 mm
<b>L/H Rear Tyre</b>	205/60 R16	TOYO	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	21/06/2018	<b>Inspection Date</b>	26/06/2018
<b>Survey held at</b>	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE MARKET VALUE IS S\$56,000.00 (EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**