

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 6349E

MAKE :

MODEL : HYUNDAI SONATA

Westlake

DATE 25/6/2018 14:56

Tokio Marine - US IS

LKK Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✓			\$ 1,349.50	
	Boot Lid Lock Upper ✕			\$ 132.10	
	Boot Lid Lock Lower ✕			\$ 30.30	
	Boot Lid Sonata Plate ✓			\$ 43.60	
	Boot Lid Hyundai Plate ✓			\$ 24.20	
	Boot Lid 'H' Emblem ✓			\$ 26.10	
	Boot Lid CRDI Plate ✓			\$ 22.70	
	Rear Bumper ✓			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ✕			\$ 185.80	
	Rear Bumper Protector (LH/RH) ✕		\$ 38.00	\$ 76.00	
	Rear Panel ✕			\$ 391.80	
	Rear Panel Garnish ✕			\$ 95.80	
	SUB TOTAL			\$ 3,599.00	
	LESS 20%			\$ 719.80	
	DISCOUNTED TOTAL			\$ 2,879.20	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Boot Lid Advertisement Logo ✓			\$ 100.00	Nett
	Rear Bumper Reverse Sensor ✕			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 515.70	
	Labour Charge				
	Panel Beating			\$ 850.00 400	
	Spray Painting Charge			\$ 750.00 400	
	Wiring Charge			\$ 50.00 ✕	
	Tuff Kote			\$ 50.00 20	
	Remove/Refix Reverse Sensor			\$ 120.00 ✕	
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 5,214.90	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Kalvin LKK
 25/6/18 15:45h.
 3072
 LKK
 After Repair pLk