



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLU 1063 J

Parts	(a) Cost / List Price Items	\$	1,514.85
	Plus/Less 25%	\$	378.71
	Total of Cost / List	\$	1,136.14
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	1,136.14
Labour		\$	1,850.00
Total		\$	2,986.14

*Not Authorised*

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is
- Supplementary item(s) is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

*Henner*

*LKK*

*22/6/18*

*Lc*

Date: *22/6/18*



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : SLU 1063 J Submit By : Carmen Lim  
Make & Model : TOYOTA PRIUS Year Manufacture : 2017  
Chassis No : JTDKB3FU103579738 Engine No. :   
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door	1	\$1,211.40		X
2	RHR door glass outer moulding	1	\$107.80		X
3	RH rear hub cab	1	\$195.65		✓
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

