



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR NG CHIH CHONG, ALVIN (WU) ZHIZHONG, ALVIN) BLK 213B PUNGGOL WALK #14-771 SINGAPORE 822213 Contact No Mobile: 98809330	Cust No/Name	/MR NG CHIH CHONG, ALVIN (WU ZHI
	Reg No/Reg Date	SLR3097P / 10/08/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5729890
	Engine No	G4FGGH672530
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No					
CSM00081	Cash	22/06/2018/ 14:10	QUD	247 / DonBong	30477					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount		
E PNT88000								825 2200.00		
RENEW ACCIDENT DAMAGED PARTS ON FRONT BODY KITS, LH HEADLAMP ASSY, FRONT BUMPER, REPAIR LH FRONT FENDER										
E PNT98000								1260 1680.00		
PAINT WORK SPRAY FRONT BUMPER FACE, FRONT BODY KIT, LH FRONT FENDER AND AFFECTED PORTION										
A 54900099								30 50.00		
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM										
E PNT88000								60 80.00		
REMOVE AND INSTALL FRONT PARKING ASSIST										
A 10028901								200.00		
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST										
M SUNDRY								180 250.00		
TO SEAL FRONT AIR DAM KIT										
M SUNDRY								20 50.00		
SUNDRIES										
M	NEW K3 TEMPTATION RED K3R		1.00	1177.00	00.00			CRA 1177.00		
M	LAMP ASSY-HEAD,LH		1.00	2209.00	00.00			SC 2209.00		
M	COVER-FR BUMPER		1.00	633.00	00.00			CRA 633.00		
M	BRACKET-FR BUMPER SIDE MTG,LH		1.00	12.00	00.00			? 12.00		
M	BRACKET-FR BUMPER SIDE MTG,RH		1.00	12.00	00.00			? 12.00		
M	LAMP ASSY-FRONT FOG,LH		1.00	241.00	00.00			? 241.00		
SURVEYOR NAME: Rasul - 4p 90010068										
SURVEYOR SIGNATURE: [Signature]										
DATE: 02/07/18 p 1610										
REMARKS: 4 days Resurvey 54 paint										
<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation</div> <div>Confirm & accepted by <ul style="list-style-type: none">• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</div> <div>Acknowledged by Repairer Signature: _____</div> <div>Authorized signatory and company stamp _____</div>					7% GST on				Nett 8794.00	8,794.00 615.58 9,409.58
					Total Payable					

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.