



REF:

Assignment

## ASSIGNMENT

CofE May 2019

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 98 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 3406 TYr Regn: 2011 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Hyundai SantaCC: 1991Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 575002

T/Radio: Insured / Std / NI / NA

Eng/No: D4EAD319037C/No: KMHET41VMB A811353Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: (Ni) / S/Rim / STD A/Rim orTyre Size: F: 215/60 R16R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 21/08/2018D.O.I. 25/06/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front y O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
03/08/18	III SHD 1571 B Jmrsal L/S 8000/- with 9 days. (Rev: 2,782.56 / 61%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



**SHA 3406T**

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (RH) <i>h/c</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (RH) <i>h/c</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>h/c</i>			\$ 100.00	Nett ✓
	Rear Door Advertisement Logo (RH) <i>h/c</i>			\$ 100.00	Nett ✓
	Rear Door Tel No. Sticker (RH) <i>h/c</i>			\$ 10.00	Nett ✓
	Front Windscreen Sealant <i>h/c</i>			\$ 46.00	Nett ✓
	Front Tyre (RH) <i>h/c</i>			\$ 207.00	Nett X
	Rear Fender Advertisement Logo (RH) <i>h/c</i>			\$ 100.00	Nett ✓
			531.00		
				\$ 738.00	
	<b>Labour Charge</b>				
	Panel Beating			\$ 2,000.00	800/-
	Spray Painting Charge			\$ 1,750.00	800/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	h/c
	Transfer of Door	\$	120.00	\$ 240.00	60/-
	Remove/Refix Undercarriage (FRT)			\$ 400.00	150/-
	FRT Wheel Alignment			\$ 120.00	60/-
	Remove/Refix Dashboard			\$ 450.00	h/c
	Remove/Refix Front Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	h/c
			2020/-		
	<b>TOTAL LABOUR</b>			\$ 5,370.00	
	<b>ESTIMATE TOTAL</b>			\$ 20,752.56	
				12073.72	
				7/58ax/-	
				vehicle wpt 89	
				months	
	<p>25/06/2018 @ 1430h</p> <p>Not Author</p> <p>L/KK Auto</p> <p>9 days</p> <p>R/gar</p> <p>LKK Auto</p>				
	<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
	<p><b>LKK Auto</b></p> <p>the Repairer of</p> <ul style="list-style-type: none"> <li>To resurvey</li> <li>To display</li> <li>Parts prices</li> <li>Third party</li> <li>No illegal</li> <li>Supplementary</li> </ul> <p>is subject</p> <p>Acknowledged by</p> <p>Signature:</p> <p>Date:</p>				

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Thursday, 30 August, 2018 10:06 AM  
**To:** Chunni Motor Work Pte Ltd  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** Your Ref: SHA 3406T\_ACCIDENT INVOLVING VEHICLES SHC 1571B AND SHA 3406T ON 21/06/2018 LKK REF CC4/III18011538/Dha3  
**Attachments:** III GIRO FORM.pdf; DV.pdf

Without Prejudice

Dear William,

ACCIDENT INVOLVING VEHICLES SHC 1571B AND SHA 3406T ON 21/06/2018

We refer to the subject matter and we confirmed in receipt of your LOD.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we confirmed acceptance of your offer of **\$10,495.50** (all in) to settle your client's claim.

Kindly chop and sign the attached DV and GIRO form and **forward back to us (LKK) the original signed copy** for payment processing.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Print Received Message

This mail is associated with :

**\*SHA3406T (MCT18060658)**  
**[SHC1571B]**

TP  
COMFORT TRANSPORTATION PTE LTD  
Jun 21 2018 9:00PM

[-]  
Chunni Motor Work Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 29/08/2018 11:13 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10495.50) - SHA3406T - Claim Handler: Zuhaidah Bte Samsuri

Approved:10495.50.

CHUNNI MOTOR WORK  
PTE LTD

Our Ref : SHA 3406 T (210618)

Your Ref : CC4/iii18011538/Dha3

Date : 30 August 2018

M/s LKK Auto Consultants Pte Ltd  
Blk 51 Paya Ubi Industrial Park  
#02-25  
Ubi Avenue 1  
Singapore 039190

**WITHOUT PREJUDICE**

Attention : Vic Alpeh

Dear Sir/Madam

**ACCIDENT INVOLVING SHA 3406 T AND SHC 1571 B ALONG BENCOOLEN STREET ON 21 June 2018**

Your email of 30-08-2018 refers.

Strictly on without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of rental & income during the period of repair) for the sum of \$10,495.50.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHA 3406 T, Ho Wee Cheong's rights to claim damage for his injury against your principal, M/s India International Insurance Pte Ltd and /or their insured, if any.

As requested, we return the attached Discharge Voucher duly executed together with the original documents for your onward transmission.

Please be informed that we have GIRO arrangement with M/s India International Insurance Pte Ltd for all our cases.

Kindly expedite to process payment.

Thank you.

Yours faithfully,

For **CHUNNI MOTOR WORK PTE LTD**

Claims Department

Enc



Your Ref : SHD 1571B

Our Ref : SHA 3406T

**Chan Teck Chua c/o**

**CHUNNI MOTOR WORK PTE LTD**

Blk 10 Ang Mo Kio Industrial Park 2A

#03-19 AMK AutoPoint

Singapore 568047

Date : 10/08/18

The Motor Claims Department

*India Go LKK Auto Consultants Pte Ltd*  
51 Ubi Ave 1 #01-25  
Paya Ubi Ind Park  
Singapore 408933

**WITHOUT PREJUDICE**

Dear Sir / Madam,

**RE: ACCIDENT INVOLVING SHA 3406T/SHC 1571B On 21.06.2018**

**ALONG Bencoolen St**

I am the owner/hirer of motor vehicle/taxi, SHA 3406T, which was involved in the above-mentioned accident.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/S CHUNNI MOTOR WORK PTE LTD. The accident was caused by your insured's negligent driving and or management of his vehicle. Therefore, I am claiming damages and losses sustained by me against you in connection with the accident based on the appraiser's recommendation.

Our claim is as follows:

1) Cost of Repair	SS	8,560.00
2) Loss of Rental	SS	1,375.50 ( \$98.25 x 14 DAYS )
3) Loss of Income	SS	560.00 ( \$40 x 14 DAYS )
4) GIA Report Fee	SS	
5) LTA Search Fee	SS	
6) Survey Report Fee	SS	
	SS	<u>10,495.50</u>

We enclose herewith the following relevant supporting documents :

- a) Authorisation Letter
- b) Final repair bill(s)
- c) LTA Search
- d) GIA report(s)
- e) Insurance Certificate

Kindly look into the matter and revert as soon as possible. Thank you.

Yours faithfully





## LETTER OF AUTHORITY

To Whom It May Concern :

ACCIDENT INVOLVING **SHA 3406T/SHC 1571B**

ALONG Bencoolen St ON 21.06.2018

I, Chan Teck Chua, NRIC NO. S 1647473H of

Blk 417 Hougang Ave 8 # 06-980 (S) 530417

Owner/hirer of motor vehicle Registration No **SHA 3406T**, insured by

Ms First Capital Insurance Ltd under Policy No. D-18088936 MFSH

do hereby authorize M/s **Chunni Motor Work Pte Ltd** as my authorized representative to write,

negotiate and settle claim on my behalf in my claim against the owner and/or Motor Vehicle

Registration No. **SHC 1571B** in respect of the above mentioned accident. I also

hereby authorize that the agreed settlement sum ( cost of repair, loss of use, earnings and rental,


Survey report fee, LTA fee & GIA report fee ) be made in favour of my representative, M/s

**Chunni Motor Work Pte Ltd** and that the said payment be forwarded to them as full and final

discharge of my claim.

Dated : 21.06.2018

Signature :

  
( Company's chop if necessary )

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18060658  
Claimant Ref: SHA 3406T

We/I, CHUNNI MOTOR WORK PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd, LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 8,560.00 (repair cost), S\$ 1,935.50 (loss of use/rental), S\$ --- (search fee), vehicle no. SHA3406T that was damaged pursuant to the accident which occurred on 21/06/2018 (date) at BENCOOLEN STREET (location) involving vehicle no. SHC1571B (insured vehicle). This is pursuant to the inspection conducted on 25/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHA3406T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHA3406T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 10,495.50 to CHUNNI MOTOR WORK PTE LTD

Dated this 30 day of August, 2018.

#### CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

Chunni Motor Work Pte Ltd  
Blk 10 Ang Mo Kio Industrial Park 2A  
AMK A10 point #03-9  
Singapore 569647  
Tel: 6542-7162 Fax: 6542-8039  
Co. Reg. No: 200923111D

#### WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

CHUNNI MOTOR WORK  
PTE LTD

**TAX INVOICE**

CHAN TECK CHUA APT BLK 417 HOUGANG AVENUE 8 #06-980 SINGAPORE 530417	VEHICLE NO SHA 3406 T	DATE 06.08.2018
	MAKE HYUNDAI	INVOICE NO <b>8327</b>
	MODEL SONATA	ACC DATE/TIME 21.06.2018 @ 21:25 HRS

Cost of Repair	\$ 8,000.00
<b>Sub-total</b>	<b>\$ 8,000.00</b>
<b>Add : 7 % - GST</b>	<b>\$ 560.00</b>
<b>Total</b>	<b>\$ 8,560.00</b>

(SINGAPORE DOLLARS: EIGHT THOUSAND FIVE HUNDRED AND SIXTY ONLY)



Our Ref: CT18060659

Date: 28 June 2018



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 21/06/2018 @ 21:25 hrs  
ALONG BENCOOLEN ST  
INVOLVING SHC1571B

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA3406T** (the "Taxi"). The Taxi was hired to **CHAN TECK CHUA IC NO S1647473H** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$98.25** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

54A 24061

[illegible]

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2018 <a href="#">Edit Reg</a>		25 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$8,000.00</b> <a href="#">Edit Estimates</a>	<b>\$8,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA3406T	Date of Loss:	21/06/2018 21:00 - :59 [84 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060658	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC1571B	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by <b>Zuhaidah Bte Samsuri</b> - 6347 6070]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 04/07/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (29/08/2018): Alert - Adj Mandate Approved (\$10495.50) - SHA3406T - Claim Handler: Zuhaidah B...</li> <li>III_SG (13/07/2018): Alert - Adj Mandate Approved (\$0.00) - SHA3406T - Claim Handler: Zuhaidah Bte S...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















































## Claim Documents

\*SHA3406T (MCT18060658)  
[SHC15718]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Jun 21 2018 9:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Chunni Motor Work Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Photos/Images									3 per page		<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	20/08/18 15:17	Front View Left							<div>1</div>	Load JPG	<div></div>
2	20/08/18 15:17	Front View Right							<div>2</div>	Load JPG	<div></div>
3	20/08/18 15:17	General View							<div>3</div>	Load JPG	<div></div>
4	20/08/18 15:17	General View							<div>4</div>	Load JPG	<div></div>
5	20/08/18 15:17	General View							<div>5</div>	Load JPG	<div></div>
6	20/08/18 15:17	General View							<div>6</div>	Load JPG	<div></div>
7	20/08/18 15:17	General View							<div>7</div>	Load JPG	<div></div>
8	20/08/18 15:17	General View							<div>8</div>	Load JPG	<div></div>
9	20/08/18 15:17	General View							<div>9</div>	Load JPG	<div></div>
10	20/08/18 15:17	General View							<div>10</div>	Load JPG	<div></div>
11	20/08/18 15:17	General View							<div>11</div>	Load JPG	<div></div>
12	20/08/18 15:17	General View							<div>12</div>	Load JPG	<div></div>
13	20/08/18 15:17	General View							<div>13</div>	Load JPG	<div></div>
14	20/08/18 15:17	General View							<div>14</div>	Load JPG	<div></div>
15	20/08/18 15:17	General View							<div>15</div>	Load JPG	<div></div>
16	20/08/18 15:17	General View							<div>16</div>	Load JPG	<div></div>
17	20/08/18 15:17	General View							<div>17</div>	Load JPG	<div></div>
18	20/08/18 15:17	General View							<div>18</div>	Load JPG	<div></div>
19	20/08/18 15:17	General View							<div>19</div>	Load JPG	<div></div>
20	20/08/18 15:17	General View							<div>20</div>	Load JPG	<div></div>
21	20/08/18 15:17	General View							<div>21</div>	Load JPG	<div></div>
22	20/08/18 15:17	General View							<div>22</div>	Load JPG	<div></div>
23	20/08/18 15:17	General View							<div>23</div>	Load JPG	<div></div>
24	20/08/18 15:17	General View							<div>24</div>	Load JPG	<div></div>
25	20/08/18 15:17	General View							<div>25</div>	Load JPG	<div></div>
26	20/08/18 15:17	General View							<div>26</div>	Load JPG	<div></div>
27	20/08/18 15:17	General View							<div>27</div>	Load JPG	<div></div>
28	20/08/18 15:17	General View							<div>28</div>	Load JPG	<div></div>
29	20/08/18 15:17	General View							<div>29</div>	Load JPG	<div></div>
30	20/08/18 15:17	General View							<div>30</div>	Load JPG	<div></div>
31	20/08/18 15:17	General View							<div>31</div>	Load JPG	<div></div>
32	20/08/18 15:17	General View							<div>32</div>	Load JPG	<div></div>
33	20/08/18 15:17	General View							<div>33</div>	Load JPG	<div></div>
34	20/08/18 15:17	General View							<div>34</div>	Load JPG	<div></div>
35	20/08/18 15:17	General View							<div>35</div>	Load JPG	<div></div>
36	20/08/18 15:17	General View							<div>36</div>	Load JPG	<div></div>
37	20/08/18 15:17	General View							<div>37</div>	Load JPG	<div></div>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/08/18 15:17	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/08/18 15:17	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
54	20/08/18 15:17	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
55	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/08/18 15:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	20/08/18 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	20/08/18 15:20	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
130	20/08/18 15:20	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
131	20/08/18 15:20	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/18 18:26	TP ESTIMATE + TP GIA REPORT	 Load PDF	
2	25/06/18 18:26	EMAIL FROM III DD 25.06.2018	 Load PDF	
3	02/07/18 19:56	TP ESTIMATE - MARKED	 Load PDF	
4	28/08/18 10:22	WORKSHOP INVOICE	 Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
5	12/09/18 11:21	AUTHORISATION TO ACT FORM		Load PDF	
6	12/09/18 11:21	DISCHARGE VOUCHER		Load PDF	
7	12/09/18 11:21	RENTAL RECEIPT		Load PDF	
8	12/09/18 11:21	LOD		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	26/06/18 08:46	Singapore Accident Statement		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18011538/DHA3Q2

Date: 12/09/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SHA3406T

Insured Vehicle No: SHC1571B

Date of Loss: 21/06/2018

Nature of Claim: TP

Claim No: MCT18060658

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA3406T**

Make & Model: HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)

Engine No: D4EAD319037

Reg. Date: 31/05/2011 (Man. Year: 2011)

Chassis No: KMHET41VMBA811353

Colour: Blue

Odometer: 575002 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: Maxxis 5 mm

Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,382.56	10,053.72	5,328.84	34.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	2,020.00	3,350.00	62.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,752.56</b>	<b>12,073.72</b>	<b>8,678.84</b>	<b>41.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,000.00</b>		
(S\$)	20,752.56	8,000.00	12,752.56	61.45
<b>+ GST 7.00/7.00% (S\$)</b>	1,452.68	560.00	892.68	61.45
<b>Nett Amount (S\$)</b>	<b>22,205.24</b>	<b>8,560.00</b>	<b>13,645.24</b>	<b>61.45</b>
<b>+ Loss of Use (14.0 x S\$40.00/day) (S\$)</b>		560.00		
<b>+ Car Rental (14.0 x S\$98.25/day) (S\$)</b>		1,375.50		
<b>Nett Liability (S\$)</b>		<b>10,495.50</b>		

### INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 25/06/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A, #03-

19 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 9.0 days

---

**Adjuster:** BRYAN TANI

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2018)
<b>Parts:</b>	143	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA3406T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	538.80 FL	*- FL
2	1		*FRONT BUMPER BRACKET (RH)	Serviceable	20.10 FL	*- FL
3	1		*HEADLAMP (RH)	Mtg Cracked	797.90 FL	*797.90 FL
4	1		*FRONT FENDER (RH)	Buckled	593.00 FL	*593.00 FL
5	1		*FRONT FENDER SHIELD (RH)	Deformed	86.00 FL	*86.00 FL
6	1		*FRONT FENDER MUDFLAP (RH)	Serviceable	15.50 FL	*- FL
7	1		*FRONT FENDER SIGNAL LAMP (RH)	Broken	45.40 FL	*45.40 FL
8	1		*FRONT DOOR (RH)	Dented	1,345.00 FL	*1,345.00 FL
9	1		*FRONT DOOR RUBBER	Necessary	110.40 FL	*110.40 FL
10	1		*FRONT DOOR GEAR /REGULATOR (RH)	Bent	625.00 FL	*625.00 FL
11	1		*FRONT DOOR HINGE UPPER (RH)	Not Necessary	51.10 FL	*- FL
12	1		*FRONT DOOR HINGE LOWER (RH)	Not Necessary	51.10 FL	*- FL
13	1		*FRONT DOOR CHECK (RH)	Not Necessary	105.50 FL	*- FL
14	1		*FRONT DOOR POWER MOTOR	Not Necessary	425.00 FL	*- FL
15	1		*FRONT DOOR TRIM BOARD (RH)	Mtg Cracked	1,147.00 FL	*1,147.00 FL
16	1		*FRONT DOOR PROTECTOR (RH)	Bent	74.90 FL	*74.90 FL
17	1		*ROCKER PANEL OUTER GARNISH	Bent	463.40 FL	*463.40 FL
18	1		*REAR DOOR (RH)	Repair	1,294.70 FL	*- FL
19	1		*REAR DOOR PROTECTOR (RH)	Repair	54.50 FL	*- FL
20	1		*FRONT WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
21	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,766.20 FL	*1,766.20 FL
22	1		*FRONT WHEEL RIM (RH)	Distorted	284.70 FL	*284.70 FL
23	1		*FRONT WHEEL HUB CAP (RH)	Distorted	145.00 FL	*145.00 FL
24	1		*FRONT WHEEL BEARING	Damaged	258.50 FL	*258.50 FL
25	1		*FRONT SHOCK ABSORBER (ASSY) (RH)	Distorted	203.70 FL	*203.70 FL
26	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	72.00 FL	*- FL
27	1		*FRONT SHOCK ABSORBER FORK (RH)	Distorted	203.30 FL	*203.30 FL
28	1		*FRONT SUSPENSION UPPER ARM (RH)	Distorted	240.00 FL	*240.00 FL
29	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	1,025.00 FL	*- FL
30	1		*RACK & PINION ASSY	Not Necessary	2,093.00 FL	*- FL
31	1		*STG TIE END	Distorted	66.50 FL	*66.50 FL
32	1		*STABILIZER BAR	Not Necessary	213.20 FL	*- FL
33	1		*STABILIZER BAR BUSH (RH)	Not Necessary	12.80 FL	*- FL
34	1		*STABILIZER BAR LINK	Not Necessary	78.30 FL	*- FL
35	1		*STABILIZER BRACKET	Not Necessary	23.00 FL	*- FL
36	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	685.20 FL	*685.20 FL
37	1		*KNUCKLE ARM (RH)	Distorted	558.60 FL	*558.60 FL
38	1		*ENGINE UNDER COVER	Not Necessary	328.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*ENGINE CROSSMEMBER	Distorted	2,143.70 FL	*2,143.70 FL
40	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
41	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
42	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
43	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
44	1		*REAR DOOR TEL NO.STICKER (RH)	Necessary	10.00 FS	*10.00 FS
45	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
46	1		*FRONT TYRE (RH)	Serviceable	207.00 FS	*- FS
47	1		*REAR FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	19,043.70	12,434.40
				- List Item Discount on L Items 20.00/20.00% (\$\$)	3,661.14	2,380.68
				Total Parts (\$\$)	15,382.56	10,053.72

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	800.00
2	SPRAY PAINTING CHARGE	New	1,750.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	TRANSFER OF DOOR	New	240.00	60.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE /REFIX DASHBOARD	New	450.00	0.00
10	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
11	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
Gross Labour Cost (S\$)			<b>5,370.00</b>	<b>2,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >