

to survey by (LKK)

REPAIR ESTIMATE*

VEHICLE NO : SHA 3406T

DATE : 22.06.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>ren</i>		\$ 538.80	X ✓
	Front Bumper Bracket (RH) <i>Svc</i>		\$ 20.10	X ✓
	Headlamp (RH) <i>crack mounting</i>		\$ 797.90	✓
	Front Fender (RH) <i>Bnc</i>		\$ 593.00	✓
	Front Fender Shield (RH) <i>deformed</i>		\$ 86.00	✓
	Front Fender Mudflap (RH) <i>sve</i>		\$ 15.50	X
	Front Fender Signal Lamp (RH) <i>broken</i>		\$ 45.40	✓
	Front Door (RH) <i>Dented</i>		\$ 1,345.00	✓
	Front Door Rubber <i>nuc</i>		\$ 110.40	✓
	Front Door Gear / Regulator (RH) <i>& VSA</i>		\$ 625.00	# L
	Front Door Hinge Upper (RH) # NH		\$ 51.10	# X
	Front Door Hinge Lower (RH) # NH		\$ 51.10	# X
	Front Door Check (RH) # NNE		\$ 105.50	# X
	Front Door Power Motor NH		\$ 425.00	X
	Front Door Trim Board (RH) # CRACK MOUNTING		\$ 1,147.00	# ✓
	Front Door Protector (RH) St		\$ 74.90	✓
	Rocker Panel Outer Garnish <i>VSA</i>		\$ 463.40	* L
	Rear Door (RH) ren		\$ 1,294.70	X
	Rear Door Protector (RH) ren		\$ 54.50	X
	Front Windscreen Moulding <i>NEL</i>		\$ 60.00	# ✓
	Front Windscreen Pillar Outer(RH) <i>dented</i>		\$ 1,766.20	* ✓
	Front Wheel Rim (RH) distorted		\$ 284.70	✓
	Front Wheel Hub Cap (RH) damaged		\$ 145.00	✓
	Front Wheel Bearing # DOM		\$ 258.50	# ✓
	Front Shock Absorber (Assy) (RH) # DISTORTED		\$ 203.70	# ✓
	Front Shock Absorber Mounting (RH) NH		\$ 72.00	X
	Front Shock Absorber Fork (RH) # DISTORTED		\$ 203.30	# ✓
	Front Suspension Upper Arm (RH) # DISTORTED		\$ 240.00	# ✓
	Front Drive Shaft (RH) NH		\$ 1,025.00	X
	Rack & Pinion Assy NH		\$ 2,093.00	X
	STG Tie End # DISTORTED		\$ 66.50	# ✓
	Stabilizer Bar # DISTORTED NN		\$ 213.20	# X
	Stabilizer Bar Bush (RH) YH		\$ 12.80	X
	Stabilizer Bar Link # NH		\$ 78.30	# X
	Stabilizer Bracket # NH		\$ 23.00	# X
	Front Suspension Lower Arm (RH) # DISTORTED		\$ 685.20	# ✓
	Knuckle Arm (RH) # DISTORTED		\$ 558.60	# ✓
	Engine Under Cover NH		\$ 328.70	X
	Engine Crossmember NH		\$ 2,143.70	X
SUB TOTAL				\$ 18,305.70
LESS 20%				\$ 3,661.14
DISCOUNTED TOTAL				\$ 14,644.56

SHA 3406T

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (RH) <i>Nec</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (RH) <i>Nec</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>Nec</i>			\$ 100.00	Nett ✓
	Rear Door Advertisement Logo (RH) <i>Nec</i>			\$ 100.00	Nett ✓
	Rear Door Tel No. Sticker (RH) <i>Nec</i>			\$ 10.00	Nett ✓
	Front Windscreen Sealant Wax <i>Nec</i>			\$ 46.00	Nett Wax ✓
	Front Tyre (RH) <i>Sw</i>			\$ 207.00	Nett X
	Rear Fender Advertisement Logo (RH) <i>Nec</i>			\$ 100.00	Nett ✓
				\$ 738.00	
	Labour Charge				
	Panel Beating			\$ 2,000.00	800/-
	Spray Painting Charge			\$ 1,750.00	800/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	10/-
	Transfer of Door		\$ 120.00	\$ 240.00	60/-
	Remove/Refix Undercarriage (FRT)			\$ 400.00	150/-
	FRT Wheel Alignment			\$ 120.00	60/-
	Remove/Refix Dashboard			\$ 450.00	40/-
	Remove/Refix Front Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	40/-
	TOTAL LABOUR			\$ 5,370.00	
	ESTIMATE TOTAL			\$ 20,752.56	
25/06/2018 @ 1430h Not Antenna 2/5mm 8 days R. Ryan LKK Auto <i>[Signature]</i>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					