

Please arrange to survey vehicle at  
 8 KAKI BUKIT AVENUE 4 - GATE 2  
 #07-48 PREMIER @ KAKI BUKIT  
 SINGAPORE 415875

*Not Attached*  
*wh photo Attached*

**ABWIN** 諭輝

Date : 13/08/2018  
 TP Vehicle No. : SLR-8004-A  
 To : AIG ASIA PACIFIC INSURANCE PTE LTD  
 Attn : Motor Claim Department

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

*3dy*  
*2/3*  
*13/8/18*

Owner : SENTOSA DEVELOPMENT CORPORATION  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5084105925-01  
 Vehicle No. : RU -4649-D  
 Make & Model : MITSUBISHI L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL

Accident Date: 05/05/2018

**ESTIMATED REPAIR COST DETAILS**

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE <i>n</i>	\$3,500.60	X
1	TAILGATE LOCK CATCH RH <i>n n</i>	\$295.60	X
1	TAILGATE LOCK CATCH LH <i>n n</i>	\$295.60	X
1	TAILGATE EMBLEM "L200"	\$120.30	—
1	TAILGATE EMBLEM "MITSUBISHI" <i>rec rec</i>	\$200.60	—
1	TAILGATE STOPPER RH <i>n n</i>	\$165.60	X
1	TAILGATE STOPPER LH <i>n n</i>	\$165.60	X
1	TAILLAMP RH <i>n n</i>	\$450.60	X
1	TAILLAMP LH <i>n n</i>	\$450.60	X
<b>Sub Total</b>		<b>\$5,645.10</b>	
<b>Discount 30% on Parts</b>		<b>(\$1,693.53)</b>	
		<b>\$3,951.57</b>	

Special Nett

1	TAILGATE ADVERTISEMENT STICKER <i>rec</i>	\$1,200.00	200
1	TAILGATE STEP PANEL <i>sent / twi</i>	\$3,500.00	1500
1	TAILGATE NUMBER PLATE LAMP <i>n n</i>	\$250.60	X
1	REAR NUMBER PLATE <i>rec</i>	\$65.00	50
1	REAR NUMBER PLATE SEAL <i>rec</i>	\$15.00	—
<b>Sub Total</b>		<b>\$5,030.60</b>	

Labour & Misc

	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00	600
	TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	500
	TOWING FEE	\$250.00	160
	TO TRANSFER ALL REAR TAILGATE FITTING <i>n n</i>	\$250.00	X
	TO CHECK LIGHTING AND FOCUS TAILLAMP <i>n n</i>	\$250.00	X
	TO TRANSFER TAILGATE STEP PANEL COMPONENTS <i>n n</i>	\$250.00	X
	TO APPLY FROM LTA TO REMOVE & RENEW FRONT NUMBER PLATE SEAL	\$150.00	80

Date : 13/08/2018  
 TP Vehicle No. : SLR-8004-A  
 To : **AIG ASIA PACIFIC INSURANCE PTE LTD**  
 Attn : **Motor Claim Department**

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Owner : SENTOSA DEVELOPMENT CORPORATION  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5084105925-01  
 Vehicle No. : RU -4649-D  
 Make & Model : MITSUBISHI L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL

Accident Date: 05/05/2018

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$4,450.00	

Sub Total \$13,432.17  
 GST 7% \$940.25  
 Total \$14,372.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: