

M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claim Department

ESTIMATE

DATE : 25/6/2018
ACC DATE : 21/06/2018
REF NO : VFIX-TP20180492
POLICY NO :

RE : VEHICLE NO : GBB2996D OPEL COMBO

DESCRIPTION	AMOUNT S\$
1 1 FRONT BONNET <i>n</i>	1,198.00 X
2 2 FRONT BONNET HINGE R+L <i>11</i>	198.00 396.00 X
3 1 FRONT BONNET LOCK <i>11</i>	325.00 X
4 1 HEADLAMP LH <i>one</i>	598.00
5 1 HEADLAMP CROSS BEAM	210.00 ?
6 1 HEADLAMP TOP BEAM	98.00 ?
7 2 FRONT FENDER R+L <i>n</i>	440.00 880.00 X
8 2 FRONT FENDER LINER R+L <i>n/s to 11</i>	189.00 378.00 <i>inc</i>
9 1 FRONT BUMPER <i>For 11</i>	1,150.00
10 1 FRONT BUMPER CUSHION PACT	288.00 ?
11 1 FRONT BUMPER RE-INFORCEMENT	780.00 ?
12 1 FRONT BUMPER LOWER BAR <i>de</i>	322.00
13 1 FRONT BUMPER SPONGE	320.00 ?
14 2 FRONT BUMPER SIDE BRACKET R+L <i>n/s sup</i>	98.00 196.00 <i>inc</i>
15 1 FRONT BUMPER TOP GRILLE	485.00 ?
16 1 FRONT BUMPER TOP GRILLE LOGO	120.00 ?
17 1 FRONT BUMPER LOWER GRILLE	298.00 ?
18 1 NUMBER PLATE BASE <i>11</i>	98.00 X
19 1 FRONT SUPPORT PANEL <i>n</i>	650.00 X
	\$ 8,790.00
LESS 10%	\$ 879.00
	\$ 7,911.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot work where necessary straighten repair dented panel	<i>500</i> 1,000.00
2 To spray paint replaced/repainted parts inclusive of preparatory works and painting materials	<i>600</i> 1,000.00
3 To conduct headlamp alignment	<i>20</i> 30.00
4 To remove,refit air con condenser with all necessary components vacuum system recharge gas	<i>11X</i> 250.00
	\$ 2,280.00

GRAND TOTAL : \$ 10,191.00

SINGAPORE DOLLARS : TEN THOUSAND ONE HUNDRED & NINETY ONE ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: