

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0446/2018  
DATE : 25-JUN-2018

AXA INSURANCE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
S(068811)  
TEL : 68804741  
FAX : 68804838  
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR GOH TEE LIAN  
ADDRESS : BLK 506 SERANGOON NORTH AVE 4  
#07-442  
S(550506)  
TELEPHONE NO : 98212656

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-~~SKP6230Z~~  
VEHICLE NO : SKP6230Z  
MODEL CODE : FDRARBZJ11EWAFJJ-  
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014  
ENGINE NO : MR20451891W  
CHASSIS NO : SJNFB AJ11U1912352  
MILEAGE : 1 KM  
DATE IN : 25/06/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 16/06/2018

**DIRECT SETTLEMENT**

**OWNER CLAIMING LOSS OF USE / RENTAL**

**CAR AT WORKSHOP / CAR NOT AT WORKSHOP**

**KINDLY REVERT TO ME ASAP**

**EMAIL : lawrenceteo@tanchong.com**

**H/P : 94568832**

**FAX : 64697472**

*1226*

*25/06/18*

*LICK*  
*attention*

*67418434*

*Wang*  
*not*  
*10pm*

*SKP 857SD*

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKP6230Z

| S/NO                 | JOB CODE | NATURE OF JOB                                                                       | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|-------------------------------------------------------------------------------------|-------------------|---------------------------|
| 1                    | RPI      | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03               | 360.00            | 100 240                   |
| 2                    | RS       | SUPPLY & INSTALL REVERSE SENSOR                                                     | 110.00            | /                         |
| 3                    | SEALI    | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03 | 300.00            | X                         |
| 4                    | ZZ/001   | REPAIR END PANEL, LH REAR FENDER AND RENEW REAR BUMPER                              | 1000.00           | 625                       |
| 5                    | ZZ/002   | S/PAINT REAR BUMPER (2 TONE), END PANEL AND LH REAR FENDER                          | 1000.00           | 700                       |
| 6                    | ZZ/003   | CHECK LIGHTING                                                                      | 48.00             | /                         |
| TOTAL LABOUR CHARGES |          |                                                                                     | 2818.00           |                           |

## TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKP6230Z

|                                                       |               | DAMAGED PARTS & PRICES |      |                |
|-------------------------------------------------------|---------------|------------------------|------|----------------|
| S/NO PARTS DESCRIPTION                                | PARTS NUMBER  | NETT                   | LIST | S/NETT REMARKS |
| 1 STAY ASSY-REAR RH                                   | H5210-4EAMA   | 126.00 ?               |      |                |
| 2 STAY ASSY-REAR LH                                   | H5211-4EAMA   | 126.00 ?               |      |                |
| 3 REINF-BUMPER RR                                     | H5030-4EAMA   | 619.20 PH ✓            |      |                |
| 4 ENERGY ABSORBER                                     | 85090-4EA0B   | 126.40 ?               |      |                |
| 5 CLIP BUMPER \$1.20 EA X 04                          | 01553-05933   | 4.80 ne ✓              |      |                |
| 6 CANOE RIVET BUMPER \$6.50 EA X 02                   | 76882-0M000   | 13.00 ne ✓             |      |                |
| 7 RETAINER-BUMPER RH                                  | 79184-4EA0A   | 23.80 X                |      |                |
| 8 CLIP BUMPER \$7.40 EA X 03                          | 85284-JD00A   | 22.20 ne ✓             |      |                |
| 9 BRACKET-BUMPER LH                                   | 85221-4EA0A   | 35.90 ne ✓             |      |                |
| 10 RETAINER-BUMPER LH                                 | 79185-4EA0A   | 23.80 ne ✓             |      |                |
| 11 FINISHER-REAR BUMPER TOW                           | 85071-4EA0A   | 16.80 su ✓             |      |                |
| 12 FASCIA-RR BUMP                                     | 85022-4EA0H   | 717.00 DG ✓            |      |                |
| 13 FENDER LH REAR ARC                                 | 93829-4EA0A   | 483.00 ?               |      |                |
| 14 C/LAMP \$25.70 EA X 02                             | 76848-83P00   | 51.40 ?                |      |                |
| 15 ORNAMENT ASSY LH BUMPER REAR                       | 26565-JJ90A   | 55.00 ?                |      |                |
| 16 LAMP COMB RR,LH                                    | 26555-4EA0A   | 323.70 ?               |      |                |
| 17 SUNDRIES                                           | NPN           |                        |      | 100.00 20      |
| 18 REVERSE SENSOR(J11 & T32)                          | SENSOR-TE5140 |                        |      | 210.00 ne ✓    |
| SUB TOTAL                                             |               | 2768.00                | 0.00 | 310.00         |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |               | 553.60                 | 0.00 | 0.00           |
| GRAND TOTAL                                           |               | 2214.40                | 0.00 | 310.00         |
| OVERALL TOTAL                                         |               | 2524.40                |      |                |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKP6230Z

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 2818.00   |
| TOTAL SPARE PARTS CHARGES | 2524.40   |
| GRAND TOTAL               | 5342.40 * |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |   |                     |
|-----------------|---|---------------------|
| NAME            | : | Rasul - 4p 90010068 |
| SURVEYED DATE   | : | 02/07/18 @ 1020 hrs |
| AUTHORIZED DATE | : | 4 days              |
| EXCESS CLAUSE   | : | 0.00                |
| LIABILITY       | : | 0.00                |
| REMARKS         | : | Resurvey by paint   |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: