

ASS. REC. BY:

REF:

CS/CT118011573/Ksd391

Special Instructions:

Surveyor  
Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boongen

of

CTI

Date/Time:

26/6/18 @ 9.22am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 7695 G

Insured:

SKM 881A

at Workshop m/s

Esteem Performance

Tel:

6484 1221

of BLK 5033, AMK Ind. Park 2 # 01-259

Policy No:

DMPCSN 3054411703

Claim No:

SNM18D03064C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/06/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

11:03am @ 26/6/18

Person Contacted:

Jenny

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKG 7695 G - X

SKM 881A - X

30/7 11 Day @ 4100 Confirm

ASS. REC. BY:

REF: CTZ1

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Soon:

Consistent?: Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

WLBAT %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKG 76856

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Wages

Make:

BMW X3

c.c

Colour:

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

22029

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA EV 420706492783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper? / Jammed / Leaked / Burnt or

Brake: Inoper? / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

255/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Continental

Front

R/Bal.

7

mm

Rear

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

20/6/18

D.O.I.

26/6/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rm o/s

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

27/6 File pass to Catherine, unable to chase you of Reg.

(45.715.30 Red - 58%)

RECEIVED 30 JUL 2018

Date/Time, File Pass to?

30/07/18

1) Tyast

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Fixtures

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

4,100.00 4/5

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		26 Jun 2018 09:22 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YIN WAI MUN SPENCER, ID: S7223652A			
Main Claimant:	WANG LIN			
Vehicle Reg. No.:	SKG7695G	Date of Loss:	20/06/2018 12:00 - :59	
Claim Type:	TP / SNM18D03064C02	Policy/Cover Note No.:	DMPCSN3054411703 (Comprehensive)	
Vehicle Reg. No. (Insured):	SKM881A	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2018]			
Adj Asg. Remarks:	EST \$1930, ASSIGN KENNETH KONG AS SJE.			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	22/06/2018 21:10
Date Of Accident	20/06/2018 12:55
Exact Location Of Accident	CARPARK OF SOPHIA RESIDENCES 5 SOPHIA RD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG7695G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WANG LIN
NRIC No	S8087085Z
Email Address	JASONWANG1007@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91168305
Alternative Phone No	OFFICE-91168305

#### Vehicle Particulars

Manufacturer	BMW
Model	X5 3.0 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10615091
Cover Note Number	

#### Driver

Name of Driver	WANG LIN
NRIC No	S8087085Z
Date Of Birth	14/11/1980
Occupation	INDOOR
Date Of Driving Pass	30/08/2013
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91168305
Fax Number	
Contact Number	OFFICE-91168305
Email Address	JASONWANG1007@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

My vehicle was parked in the car park lot within my residences. Vehicle B had drove into the car park and while making a turn, the front portion of vehicle B had collided onto the front right portion of my vehicle. The impact had left the axis of my front tires to be shifted a certain angle after the collision. No injuries were involved.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM881A
Vehicle Make/Model/Colour	BMW/528i
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YIN WAI MUN SPENCER
NRIC/Passport Number	
Contact Number	90114336
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if/when.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Ammar Hamizan Bin  
Khairudin

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan



**ACCIDENT STATEMENT (2000 characters)**

My vehicle was parked in the carpark lot within my residences. Vehicle B had drove into the carpark and while making a turn, the front portion of vehicle B had collided onto the front right portion of my vehicle. The impact had left the axis of my front tyres to be shifted a certain angle after the collision. No injuries were involved.


Taxi Voucher No.:

**DECLARATION**

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
AMMAR HAMIZAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

22 June 2018 7:20 pm

Date/Time:





## ESTEEM PERFORMANCE PTE LTD


Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SKG 7695 G

Parts	(a) Cost / List Price Items	\$	8,767.00
	Plus/Less 10%	\$	876.70
	Total of Cost / List	\$	7,890.30
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	7,935.30
Labour		\$	1,930.00
Total		\$	9,865.30

The above total will be subjected to 7% G.S.T.



Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 26/6/18 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : [Signature] Date: 26/6/18





## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SKG 7695 G**  
Make & Model : **BMW X5**  
Chassis No. : **WBAZV42070L492793**

Submit By : **Carmen Lim**  
Year Manufacture :  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>N-C (RM)</i>	1	\$45.00	S.N	X
2	Front number plate garnish <i>Sm</i>	1	\$80.00		X
3	Headlamp RH <i>CM</i>	1	\$2,825.00		✓
4	Front bumper <i>Bu</i>	1	\$1,730.00		✓
5	Front bumper clip <i>nu</i>	10	\$70.00		✓
6	Front bumper reinforcement <i>R</i>	1	\$720.00		X
7	Front bumper side retainer LH <i>h</i>	1	\$250.00		X
8	Front bumper side retainer RH <i>h</i>	1	\$250.00		X
9	Front bumper bracket LH <i>R</i>	1	\$195.00		X
10	Front bumper bracket RH <i>R</i>	1	\$195.00		X
11	Front bumper sponge <i>h</i>	1	\$150.00		X
12	Front bumper lower garnish	1	WITH NO.4		X
13	Front bumper lower garnish centre cover	1	WITH NO.4		X
14	Front bumper sensor <i>Sm</i>	4	\$310.00		X
15	Fog lamp RH <i>Sm</i>	1	\$295.00		X
16	RH front fender <i>R</i>	1	\$1,400.00		X
17	RH front fender undershield <i>Sm</i>	1	\$257.00		X
18	RH front fender undershield clip <i>nu</i>	10	\$40.00		X
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2018		26 Jun 2018 09:22 <a href="#">Edit Adj Rpt</a>	<b>S\$4,100.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,100.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured:	<b>YIN WAI MUN SPENCER</b> , ID: S7223652A								
Main Claimant:	<b>WANG LIN</b>								
Vehicle Reg. No.:	<b>SKG7695G</b>	Date of Loss:	20/06/2018 12:00 - :59						
Claim Type:	<b>TP / SNM18D03064C02</b>	Policy/Cover Note No.:	DMPCSN3054411703 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKM881A</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Esteem Performance Pte Ltd (HQ)</b> Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 05/07/2018]								
Adj Asg. Remarks:	EST \$1930, ASSIGN KENNETH KONG AS SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SKG7695G (SNM18D03064C02)  
[SKM881A]  
TP  
WANG LIN  
Jun 20 2018 12:00PM  
[YIN WAI MUN SPENCER]  
Esteem Performance Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/06/18 18:03	Accident Statement	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/06/18 18:03	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 18:03	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 18:03	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 18:03	CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
<b>Relabel/Reorder</b> LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	30/07/18 11:58	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
3	30/07/18 11:58	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
4	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
5	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
6	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
7	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
8	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
9	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
10	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
11	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
12	30/07/18 11:58	General View	Load JPG	<input checked="" type="checkbox"/>
13	30/07/18 11:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
14	30/07/18 11:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/06/18 17:01	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	20/06/18 17:01	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
3	20/06/18 17:01	DRIVER'S NRIC & DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	
<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b>			Thumbnail	Print
1	26/06/18 09:21	REPAIR EST WITH TP GIA	Load PDF	
2	26/06/18 09:21	OI GIA	Load PDF	

## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/06/18 18:03	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/06/18 18:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 18:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 18:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 18:03	CHASSIS NUMBER	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/06/18 17:01	Sketch Plan	 Load TIF	
2	20/06/18 17:01	CERTIFICATE OF INSURANCE	 Load TIF	
3	20/06/18 17:01	DRIVER'S NRIC & DRIVING LICENCE	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011573/KSD3Q2

Date: 01/08/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3054411703

Claimant Vehicle  
No: SKG7695GInsured Vehicle  
No: SKM881A

Date of Loss: 20/06/2018

Nature of Claim: TP

Claim  
No: SNM18D03064C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKG7695G**

Make &amp; Model: BMW X5, 3.0 (A)

Reg. Date: (Man. Year: 1900)

Colour: Metallic Brown

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HIDDEN

Chassis No: WBAZV42070L492793

Odometer: 22029 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	255/55R18	Rear Tyre Size:	255/55R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,935.30	4,162.50	3,772.80	47.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	980.00	950.00	49.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,865.30</b>	<b>5,142.50</b>	<b>4,722.80</b>	<b>47.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
(S\$)	9,865.30	4,100.00	5,765.30	58.44
<b>+ GST 7.00/7.00% (S\$)</b>	690.57	287.00	403.57	58.44
<b>Nett Amount (S\$)</b>	<b>10,555.87</b>	<b>4,387.00</b>	<b>6,168.87</b>	<b>58.44</b>

## INSPECTION

Date of Assignment: 26/06/2018

Date Inspected: 26/06/2018 Inspected At:

Esteem Performance Pte Ltd (HQ)  
Blk 5033 Ang Mo Kio Ind Park 2, #01-259  
Singapore 569536

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
<b>Parts:</b> M1-SUV	BMW X5 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKG7695G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE (DENTED)	Not Consistent With The Impact	45.00 FS	*- FS
2	1		*FRONT NUMBER PLATE GARNISH	Serviceable	80.00 FL	*- FL
3	1		*HEADLAMP RH	Cracked	2,825.00 FL	*2,825.00 FL
4	10		*FRONT BUMPER CLIP	Necessary	70.00 FL	*70.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	720.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	250.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	250.00 FL	*- FL
8	1		*FRONT BUMPER BRACKET LH	Repair	195.00 FL	*- FL
9	1		*FRONT BUMPER BRACKET RH	Repair	195.00 FL	*- FL
10	1		*FRONT BUMPER }	Buckled	1,730.00 FL	*1,730.00 FL
11	1		*FRONT BUMPER LOWER GARNISH }		0.00 FL	*- FL
12	1		*FRONT BUMPER LOWER GARNISH CENTRE COVER }		0.00 FL	*- FL
13	4		*FRONT BUMPER SENSOR	Serviceable	310.00 FL	*- FL
14	1		*FOG LAMP RH	Serviceable	295.00 FL	*- FL
15	1		*RH FRONT FENDER	Repair	1,400.00 FL	*- FL
16	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	257.00 FL	*- FL
17	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	40.00 FL	*- FL
18	1		*FRONT BUMPER SPONGE	Serviceable	150.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,812.00</b>	<b>4,625.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>876.70</b>	<b>462.50</b>
<b>Total Parts (S\$)</b>	<b>7,935.30</b>	<b>4,162.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER)	New	800.00	400.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER)	New	800.00	500.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	20.00
4	TO REMOVE & REFIT FRONT BUMPER SENSOR	New	180.00	60.00
5	TO TUFF COAT	New	100.00	0.00
Gross Labour Cost (S\$)			<b>1,930.00</b>	<b>980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >