

22/03/2002

ASS. REC. BY:

REF: CS3/ III 18011588/G24d321 Special Instruction: ✓

Surveyor:
Maimen

Gao Biny

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

25/6/18 @ 5:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 1728H

Insured:

SHC 1795Y

at Workshop m/s

Tek Soon Motor Repair

Tel:

6747 5484

of

1 Kaki Bukit Ave 6 Bldg # 01-93

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/05/2018

CA / REV / REP. / REV 24 HRS (up)

27/06/2018

H.O.D. Endorsement:

Date/Time:

10:23am @ 26/6/18

Person Contacted:

Mr. Ng

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

GBD 1728H - CC4/ASM 18000336/Ueb3s2 DOA: 2/01/2018

SHC 1795Y - CC3/LCR17015016/Klpb3s2 DOA: 1/8/2017

(08/11/13) wef

ASS. REG. BY:

REF:

III

B 8841w

ASSIGNMENT

From: Date: 27/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 1728 H

at Workshop m/s Tek Soon Motor

of Ikaki Bukit Ave 6 # 01-93

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GBD1728H

Yr Regn:

17 Jun 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dugna

c.c

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

127431

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ITFAT 35Y 00 K 203171

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Rear

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

27-06-18

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/6/18

Submit PRS Report.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

80

10

90




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18011588/Gz4d3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 26-06-2018		
		Code : III2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHC 1795Y	Veh. Inspected	GBD 1728H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	GABRIEL WEE	Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/05/2018	Inspection Date	27/06/2018	
Survey held at	TEK SOON MOTOR REPAIR & SPRAY PAINTING AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 BLK D #01-93 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 25 June 2018 5:09 PM
To: 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini; Tek Soon Motor
Subject: RE: Accident on 30/5/2018 involving your insured's vehicle SHC1795Y and our client's vehicle GBD1728H along 13 and 5 Kallang Sector

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBD1728H and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: lmng.dawn@gmail.com [mailto:lmng.dawn@gmail.com] **On Behalf Of** Tek Soon Motor
Sent: 25 June, 2018 5:05 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Accident on 30/5/2018 involving your insured's vehicle SHC1795Y and our client's vehicle GBD1728H along 13 and 5 Kallang Sector

Hi Gabriel,

Thanks much for the reply. Please allocate LKK.

On Mon, Jun 25, 2018 at 5:03 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: lmng.dawn@gmail.com [mailto:lmng.dawn@gmail.com] **On Behalf Of** Tek Soon Motor

Sent: 25 June, 2018 4:59 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Accident on 30/5/2018 involving your insured's vehicle SHC1795Y and our client's vehicle GBD1728H along 13 and 5 Kallang Sector

Dear Sir,

I refer to the above mentioned subject.

Kindly look into the matter and arrange for a survey as soon as possible. In the event of pre repair inspection, kindly contact Ah Qing at 81232600 or Ah Lek at 97613530.

Thanks much.

--

TEK SOON MOTOR REPAIR AND SPRAY PAINTING (AUTOBAY @ KAKI BUKIT)

TEL: 67475484

FAX: 67466822

EMAIL: teksoonmotor@gmail.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--

TEK SOON MOTOR REPAIR AND SPRAY PAINTING (AUTOBAY @ KAKI BUKIT)

TEL: 67475484

FAX: 67466822

EMAIL: teksoonmotor@gmail.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8841W
Vehicle Details	
Vehicle No.:	GBD1728H
Vehicle to be Exported:	No
Intended De-registration Date:	28 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2411363
Chassis No.:	JTFAT35Y00K203171
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	17 Jul 2014
First Registration Date:	17 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$13,878.00
COE Rebate Amount:	\$8,394.00
Total Rebate Amount:	\$8,394.00

The information contained herein is correct as at 28 Jun 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jun 2018 Edit Reg		25 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																																				
<div style="border: 1px solid black; padding: 5px;"> <div style="display: flex; justify-content: space-between;"> <div> CLAIM SUBFOLDER DETAILS </div> <div>[Created by adjuster]</div> </div> <div style="margin-top: 5px;"> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Insured:</td> <td colspan="3">-, Co. Reg. No.: -</td> </tr> <tr> <td>Main Claimant:</td> <td colspan="3">-</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td style="width: 30%;">GBD1728H</td> <td style="width: 15%;">Date of Loss:</td> <td>30/05/2018 00:00 - :59 [46 Months and 13 Days From LTA Reg Date (Man Yr)]</td> </tr> <tr> <td>Claim Type:</td> <td>TP</td> <td>Policy/Cover Note No.:</td> <td></td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td>SHC1795Y</td> <td>Policy No. (Claimant):</td> <td></td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td></td> </tr> <tr> <td>Repairer:</td> <td colspan="3">TEK SOON MOTOR REPAIR & SPRAY PAINTING (HQ) 1 KAKI BUKIT AVE 6, BLK D #01-93,, AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67475484</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="3">India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]</td> </tr> <tr> <td>Adjuster:</td> <td colspan="3">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/07/2018]</td> </tr> </table> </div> </div>					Insured:	-, Co. Reg. No.: -			Main Claimant:	-			Vehicle Reg. No.:	GBD1728H	Date of Loss:	30/05/2018 00:00 - :59 [46 Months and 13 Days From LTA Reg Date (Man Yr)]	Claim Type:	TP	Policy/Cover Note No.:		Vehicle Reg. No. (Insured):	SHC1795Y	Policy No. (Claimant):				Excess:		Repairer:	TEK SOON MOTOR REPAIR & SPRAY PAINTING (HQ) 1 KAKI BUKIT AVE 6, BLK D #01-93,, AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67475484			Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]			Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/07/2018]		
Insured:	-, Co. Reg. No.: -																																							
Main Claimant:	-																																							
Vehicle Reg. No.:	GBD1728H	Date of Loss:	30/05/2018 00:00 - :59 [46 Months and 13 Days From LTA Reg Date (Man Yr)]																																					
Claim Type:	TP	Policy/Cover Note No.:																																						
Vehicle Reg. No. (Insured):	SHC1795Y	Policy No. (Claimant):																																						
		Excess:																																						
Repairer:	TEK SOON MOTOR REPAIR & SPRAY PAINTING (HQ) 1 KAKI BUKIT AVE 6, BLK D #01-93,, AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67475484																																							
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]																																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/07/2018]																																							
<div style="border: 1px solid black; padding: 5px;"> ASSOCIATED MAIL RECEIVED <div style="float: right;"> View All Compose Case Mail </div> <div style="clear: both;"></div> <p>There are no mail for this case.</p> </div>																																								
<div style="border: 1px solid black; padding: 5px;"> ALL ASSOCIATED TASKS <div style="float: right;"> View All Search Tasks Create New Task Complete </div> <div style="clear: both;"></div> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																															
No results.																																								

Claim Documents

*GBD1728H
[SHC1795Y]



TP

-

May 30 2018 12:00AM

[-]

TEK SOON MOTOR REPAIR & SPRAY PAINTING

Upload Documents			Upload Photos			Compose New Letter			View View in Browser <input type="button" value="v"/>		
Documentation									1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	29/06/18 15:16	LKKPhotosIn6-1.pdf							 Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	29/06/18 14:46	Singapore Accident Statement-IV							 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div><div></div><div>^</div><div>v</div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18011588/GZ4D3E2

Date: 02/07/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : GBD1728H

Insured Vehicle No : SHC1795Y

Date of Loss: 30/05/2018

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD1728H

Make & Model: TOYOTA DYNA, 3.0 D (M)

Engine No: 1KD2411363

Reg. Date: 17/07/2014 (Man. Year: 2014)

Chassis No: JTFAT35Y00K203171

Colour: Silver

Odometer: 127431 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R12

Front Left Side: Michelin 5 mm

Rear Left Side: Firestone 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Firestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 27/06/2018 Inspected At:

TEK SOON MOTOR REPAIR & SPRAY
PAINTING (HQ)
1 KAKI BUKIT AVE 6, BLK D #01-93,,
AUTOBAY@KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jul 2018)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD1728H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >