

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 497P

MAKE :

MODEL : HYUNDAI SONATA

DATE 25/6/2018 11:36

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>x rpe</i>			\$ 1,349.50
	Boot Lid Lock Upper <i>x</i>			\$ 132.10
	Boot Lid Lock Lower <i>x</i>			\$ 30.30
	Boot Lid Sonata Plate <i>-</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>-</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>-</i>			\$ 26.10
	Boot Lid CRDI Plate <i>-</i>			\$ 22.70
	Rear Bumper <i>-</i>			\$ 578.40
	Rear Bumper Reinforcement <i>-</i>			\$ 483.30
	Rear Bumper Clip <i>-</i>			\$ 22.00
	Rear Bumper Sponge <i>-</i>			\$ 137.40
	Rear Bumper Under Cover <i>x</i>			\$ 185.80
	Rear Bumper Protector (LH) <i>x rpe</i>			\$ 38.00
	Tail Lamp (LH) <i>-</i>			\$ 344.00
	Rear Panel <i>x rpe</i>			\$ 391.80
	Rear Panel Garnish <i>?</i>			\$ 95.80
	Rear Fender (LH) <i>-</i>			\$ 1,935.90
	Rear Fender Inner Lining (LH) <i>-</i>			\$ 74.10
	Rear Windscreen Moulding <i>-</i>			\$ 60.00
	SUB TOTAL			\$ 5,975.00
	LESS 20%			\$ 1,195.00
	DISCOUNTED TOTAL			\$ 4,780.00
	Boot Lid Comfort Logo & Tel No. Sticker <i>-</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>x</i>			\$ 135.70
	Rear Windscreen Sealant <i>-</i>			\$ 46.00
				\$ 211.70
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>600</i>
	Spray Painting Charge			\$ 800.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>x</i>
	TOTAL LABOUR			\$ 2,020.00
	ESTIMATE TOTAL			\$ 7,011.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 497P

DATE 25/6/2018 11:39

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Reinforcement ?			\$ 504.10
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) ?			\$ 29.20
	Front Fender (RH) X			\$ 593.00
	Front Fender Shield (RH) X			\$ 86.00
	Front Fender Retainer X			\$ 9.20
	SUB TOTAL			\$ 1,919.00
	LESS 20%			\$ 383.80
	DISCOUNTED TOTAL			\$ 1,535.20
	Labour Charge			
	Panel Beating			\$ 560.00 ^{20%}
	Spray Painting Charge			\$ 400.00 ^{20%}
	Tuff Kote			\$ 50.00 X
	TOTAL LABOUR			\$ 1,010.00
	ESTIMATE TOTAL			\$ 2,545.20
<i>Kalvin LKK</i> <i>25/6/18 1510 hrs.</i> <i>4 Days.</i> <i>L/S</i> <i>After Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				