

Attn. Mr Kenneth

OK

SLJ3787Z

TP/AIG

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department
WS Ref: TP AIG
Claim Type: Third Party
Accident Date: 25/06/2018
TP Veh Reg No: SJQ424C

FAX: 64153727

Not Authorised
L.B.1
Resurvey By paint
@ 8715-60

Estimate No: ES1890700/WS
Date: 26 Jun 2018
Policy No: DI7MTPV01017199
Veh Reg No: SLJ3787Z
Make/Model: KIA FIA FORTE K3
Chassis No: KNAFX411MH5668966
Engine No:
Reg. Date: 08/12/2016

8 days

Estimate Repair Cost to Vehicle No :SLJ3787Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	398.00	1 PC	<i>RM</i> 398.00	✓
2 REAR BUMPER LOWER SKIRT	380.00	1 PC	<i>Not by</i> 380.00	✓
3 REAR BUMPER REINFORCEMENT	323.00	1 PC	<i>RM</i> 323.00	✓
4 REAR BUMPER SIDE RETAINER RH	28.00	1 PC	<i>RM</i> 28.00	X
5 REAR BUMPER CLIP	3.50	6 PCS	<i>RM</i> 21.00	✓
6 REAR BOOT	1,297.00	1 PC	<i>RM</i> 1,297.00	✓
7 REAR BOOT LOGO	31.00	1 PC	<i>RM</i> 31.00	✓
8 REAR BOOT EMBLEM - FORTE KB/CERTO	38.00	1 PC	<i>RM</i> 38.00	✓
9 REAR BOOT INNER LOCK	98.00	1 PC	<i>RM</i> 98.00	✓
10 REAR BOOT INNER RUBBER	95.00	1 PC	<i>RM</i> 95.00	✓
11 REAR PANEL	289.00	1 PC	<i>RM</i> 289.00	X
12 REAR PANEL INNER TOP GARNISH	49.00	1 PC	<i>RM</i> 49.00	X
13 FRONT BUMPER	631.00	1 PC	<i>RM</i> 631.00	✓
14 FRONT BUMPER REINFORCEMENT	496.00	1 PC	<i>RM</i> 496.00	X
15 FRONT BUMPER SIDE RETAINER RH	18.00	1 PC	<i>RM</i> 18.00	X
16 FRONT BUMPER SPONGE	84.00	1 PC	<i>CRP</i> 84.00	✓
17 FRONT BUMPER CLIP	3.50	6 PC	<i>RM</i> 21.00	✓
18 FRONT GRILLE	328.00	1 PC	<i>CRP</i> 328.00	✓
19 FRONT GRILLE TOP COVER	48.00	1 PCS	<i>RM</i> 48.00	X
20 FRONT GRILLE TOP COVER LOGO	49.00	1 PC	<i>RM</i> 49.00	✓
21 HEADLAMP RH	1,528.00	1 PC	<i>my car</i> 1,528.00	✓
22 FRT SUPPORT PANEL	662.00	1 PC	<i>alt</i> 662.00	✓
23 FRONT SUPPORT PANEL <i>L/H head lamp</i>	1,528.00	1 PC	<i>RM</i> 1,528.00	X
			8,440.00	
		Less 10%	844.00	7,596.00
Special Net				
24 REVERSE SENSOR	200.00	1 SET	<i>shot</i> 200.00	✓
25 FRONT CAMERA	380.00	1 PC	<i>shot</i> 380.00	350.00
			580.00	580.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP AIG
 Claim Type: Third Party
 Accident Date: 25/06/2018
 TP Veh Reg No: SJQ424C

Estimate No: ES1890700/WS
 Date: 26 Jun 2018
 Policy No: D17MTPV01017199
 Veh Reg No: SLJ3787Z
 Make/Model: KIA FIA FORTE K3
 Chassis No: KNAFX411MH5668966
 Engine No:
 Reg. Date: 08/12/2016

Estimate Repair Cost to Vehicle No :SLJ3787Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
26 REMOVE AND REFIX RR BUMPER ASSY, TAIL LAMPS, REAR BOOT AND ATTACHMENT. TO CUTTING, WELDING AND RENEW REAR END PANEL. KNOCK AND REPAIR REAR SPARE TYRE COMPARTMENT, BOOT HINGES AND REALIGN THE SAME	850.00	1 LA	850.00	700
27 PUTTY AND RESPRAY ON REAR BUMPER, REAR PANEL, REAR SPARE TYRE COMPARTMENT BOOT, HINGES AND REAR AFFECTED AREA	850.00	1 LA	850.00	720
28 REMOVE AND REFIX FRONT BUMPER ASSY, FOG LAMPS, HEAD LAMPS, GRILLE, SUPPORT PANEL, RADIATER AND MOOR AND REALIGN THE SAME.	700.00	1 LA	700.00	600
29 PUTTY AND RESPRAY ON FRONT BUMPER, FRONT GRILLE TOP PANEL, SUPPORT PANEL, BONNET, FRONT LH FENDER AND FRONT AFFECTED AREA	750.00	1 LA	750.00	600
30 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
31 RUSTPROOFING	90.00	1 LA	90.00	60
			3,340.00	3,340.00
			Total	S\$ 11,516.00
			Add GST @ 7%	806.12
			Total Amount Payable	S\$ 12,322.12

For Cheng Hoe Motor Pte Ltd


 AUTHORISED SIGNATURE