

ASS. REC. BY:

REF:

CS/EGT18011595/Ksd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

26/6/18 @ 10:45am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 7913Y

Insured:

SGQ 9002M

at Workshop m/s

Optima Werkz

Tel:

6484 9919

of

9A Serangoon North Ave 5

Policy No:

Claim No:

DMSPC1801206

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10:49am @ 26/6/18

Person Contacted:

Riza

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 7913Y - x

SGQ 9002M - x

24/06/18

@ 17:09 p.m revised PA to Pei Li via email.

85133-20 email

ASS. REC. BY:

REF:

ERT/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 79134

Yr Regn: 031 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c. 1496

Colour:

M. P. White

A/C: Insured / Std / Nil / NA

Sp. Reading

36833

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

R41 1104321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/6/18

D.O.I.

26/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/6 File pass to Catherine

05286-81 Carbur

17/09/13

Confirmed P/P \$5286-81 @ 6 days with Kenneth.
(\$1,624.71 Red - 24%)

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

17/09/13

☐ : Prel. Report

1) Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - R.S. \$

Fuels

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 5,286.81 P/P

250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SGQ9002M/SL/pl

Date: 27 June 2018

Our Ref: CS/EG118011595/Ksd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 7913Y

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/06/2018 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,911.52</u>
Revised Estimate Amount	: S\$ <u>3,302.32</u>
"Check" Items Amount	: S\$ <u>923.60</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 26 June 2018 10:45 AM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : SGQ9002M / TP : SLA7913Y/LKK / DOA : 22/06/2018
Attachments: SGQ9002M - SAS.pdf; SLA7913Y - SAS.pdf; SLA7913Y - PRS FORM.pdf; SLA7913Y - estimate.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **OPTIMA WERKZ PTE LTD.**

ADDRESS : 9A SERANGOON NORTH AVE 5 (PLEASE AVOID 1 – 2PM)
SINGAPORE 554500

PERSON TO CONTACT : MS RIZA @ 6484 9919 EXT 105

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 26.06.2018
Our Reference: SGQ 9002M/SL/pl
Your Reference: SLA 7913Y

To: OPTIMA WERKZ PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLA 7913Y
Insured's Vehicle: SGQ 9002M
Date Of Accident: 22.06.2018


We acknowledge receipt of your request for PRS on: 22.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shirley Hiew (LKK Auto)

From: Lily.loi@ow.sg
Sent: Monday, 17 September 2018 10:02 AM
To: 'Shirley Hiew (LKK Auto)'; 'Kenneth Kong (LKKAuto)'
Cc: 'WINSON'; 'Riza'; 'Adeline Lim'; 'LKK - Main'
Subject: RE: To finalize for vehicle SLA7913Y Honda Vezel DOA 22 June 2018

Dear Shirley,

We confirm and accept COR PP \$5286.81 and 6 days.

--
Thanks & Best Regards,

Lily Loi (Ms)
Motor Claims Department
Serangoon Branch

OPTIMA WERKZ PTE LTD
6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 | 9A Serangoon North Avenue 5
Singapore 554500 | Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011 |
551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 | www.ow.sg
www.facebook.com/optimawerkz

-----Original Message-----

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 17 September, 2018 10:00 AM
To: 'Lily Loi' <Lily.Loi@ow.sg>; 'Kenneth Kong (LKKAuto)' <KennethKong@lkkauto.com>
Cc: 'WINSON' <winson@ow.sg>; 'Riza' <riza@ow.sg>; 'Adeline Lim' <adeline@ow.sg>; 'LKK - Main' <sur@lkkauto.com>
Subject: RE: To finalize for vehicle SLA7913Y Honda Vezel DOA 22 June 2018

Dear Lily,

Please confirm final fig \$5,286.81 (part by part) @ 6 days of repairs before GST.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Lily Loi [<mailto:Lily.Loi@ow.sg>]
Sent: Thursday, 19 July 2018 3:00 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Cc: WINSON <winson@ow.sg>; Riza <riza@ow.sg>; Adeline Lim <adeline@ow.sg>; LKK - Main <sur@lkkauto.com>
Subject: Re: To finalize for vehicle SLA7913Y Honda Vezel DOA 22 June 2018

Dear Kenneth,

Kindly confirm the finalise amount COR P/P \$5,701.20 and 8 days.

Thanks & Best Regards,

Lily Loi (Ms)
Claims Executive
Tel: +65 6484-9919 (ext.107)
Fax: +65 6481-1011

OPTIMA WERKZ PTE LTD
6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 | 9A Serangoon North Avenue 5
Singapore 554500 | Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011 |
551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 | www.ow.sg
www.facebook.com/optimawerkz

On 11/7/2018 11:24 AM, Lily Loi wrote:

> Dear Kenneth,
>
> TP Claims - SLA7913Y Honda Vezel DOA 22 June 2018
>
> As spoken to you with regard to the finalize case.
>
> Attached are the surveyed estimate repair, resurvey photos and after
> repair photos for your perusal.
>
> Please advise to be finalize for this case soonest possible.
>
> Your assistance would be much appreciated.
>
> Thank you.
>
>
> Thanks & Best Regards,
>
> Lily Loi (Ms)
> Claims Executive
> Tel: +65 6484-9919 (ext.107)
> Fax: +65 6481-1011
>
> OPTIMA WERKZ PTE LTD
> 6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65)
> 6472 2112 |
> 9A Serangoon North Avenue 5 Singapore 554500 | Tel: (+65) 6484 9919 |
> Fax: (+65) 6481 1011 |
> 551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax:
> (+65) 6452 9223 |
> www.ow.sg
> www.facebook.com/optimawerkz
>
> On 4/7/2018 8:00 PM, WINSON wrote:
>> Dear Kenneth,
>>

>> TP Claims - SLA7913Y Honda Vezel DOA 22 June 2018

>>

>> As spoken to you with regard to the finalize case.

>>

>> Attached are the surveyed estimate repair, resurvey photos and after
>> repair photos for your perusal.

>>

>> Please advise to be finalize for this case soonest possible.

>>

>> Your assistance would be much appreciated.

>>

>> Thank you.

>>

>

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 27 June 2018 5:09 PM
To: 'Nivitha (LKK Auto)'; 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments@lkkauto.com
Cc: ASSIGNMENTS@LKKAUTO.COM; sur@lkkauto.com
Subject: RE: SGQ9002M / TP : SLA7913Y/LKK / DOA : 22/06/2018
Attachments: SLA 7913Y - Preli Advise.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SLA 7913Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 26 June 2018 10:59 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments@lkkauto.com
Cc: ASSIGNMENTS@LKKAUTO.COM; sur@lkkauto.com
Subject: RE: SGQ9002M / TP : SLA7913Y/LKK / DOA : 22/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 26 June 2018 10:45 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : SGQ9002M / TP : SLA7913Y/LKK / DOA : 22/06/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **OPTIMA WERKZ PTE LTD**.

ADDRESS : 9A SERANGOON NORTH AVE 5 (PLEASE AVOID 1 – 2PM)
SINGAPORE 554500

PERSON TO CONTACT : MS RIZA @ 6484 9919 EXT 105

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4087G
Vehicle Details	
Vehicle No.:	SLA7913Y
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5S CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4024324
Chassis No.:	RU11104321
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,847.00
Original Registration Date:	17 Mar 2016
First Registration Date:	17 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$16,186.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Mar 2026
PARF Rebate Amount:	\$12,139.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$33,215.00
Total Rebate Amount:	\$45,354.00

The information contained herein is correct as at 23 Jun 2018

OK

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 June 2018

Third Party Insurer: ERGO

Vehicle No: SLA7913Y

Third Party Veh No: SGQ9002M

Model: HONDA VEZEL

Date of Accident: 22 June 2018

Chassis: RU11104321

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		<i>Bz</i> \$953.30
1	REAR TAILGATE WINDSCREEN MOULDING		<i>m</i> \$120.00
1	REAR TAILGATE "VEZEL" EMBLEM		<i>m</i> \$32.90
1	REAR TAILGATE INNER TRIM BOARD		<i>Sm</i> \$153.40
1	REAR TAILGATE REFLECTOR LAMP LH		<i>Sm</i> \$264.60
1	REAR TAILGATE MECHANISM LOCK		<i>Per</i> \$216.20
1	REAR TAILGATE WEATHERSTRIP		<i>Gr</i> \$198.00
1	REAR TAILLAMP LH		<i>Gr</i> \$487.50
1	REAR BUMPER CENTER		<i>Bz</i> \$528.30
1	REAR BUMPER REFLECTOR LH		<i>Sm</i> \$151.40
8	REAR BUMPER CLIP	\$3.90	<i>m</i> \$31.20
2	REAR BUMPER SIDE RETAINER LH/RH	\$14.50	<i>Sm</i> \$29.00
1	REAR SIDE BUMPER LH		<i>Sm</i> \$195.00
1	REAR END PANEL		<i>Bz</i> \$470.30
1	REAR END PANEL TAILGATE ANTENA SENSOR BUZZER		<i>CM</i> \$85.00
1	REAR END PANEL INNER TOP GARNISH		<i>Per</i> \$98.00
1	REAR FENDER ARCH GARNISH LH		<i>Sm</i> \$192.00
1	REAR WELL PANEL LOWER UNDER COVER		<i>CM</i> \$213.20
2	REAR WELL PANEL LOWER UNDER COVER CLIP	\$8.80	<i>m</i> \$17.60
1	REAR WELL PANEL INNER TOP TOOLS SPONGE		<i>CM</i> \$215.00
SUB TOTAL			\$4,651.90
Less 20%			-\$930.38
PARTS TOTAL			\$3,721.52

*Not Authorised
1-Bz
Repair B4 pain
6 days*

\$5133.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 June 2018

Third Party Insurer: ERGO

Vehicle No: SLA7913Y

Third Party Veh No: SGQ9002M

Model: HONDA VEZEL

Date of Accident: 22 June 2018

Chassis: RU11104321

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		<i>Per</i> \$100.00
1	REAR BUMPER REVERSE SENSOR		<i>Per</i> \$280.00
		S/N TOTAL	\$380.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	<i>800</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,000.00	<i>800</i>
TO TUFF KOTE / ANTI-RUST	\$80.00	<i>60</i>
TO CHECK WIRING WITH WATER LEAKAGE TEST	\$60.00	<i>20</i>
TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA	\$80.00	<i>50</i>
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00	<i>50</i>
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	\$150.00	<i>120</i>
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$360.00	<i>60</i>

LABOUR TOTAL \$2,810.00

WINSON TOTAL \$6,911.52

Ks

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 June 2018

Third Party Insurer: ERGO

Vehicle No: SLA7913Y

Third Party Veh No: SGQ9002M

Model: HONDA VEZEL

Date of Accident: 22 June 2018

Chassis: RU11104321

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		<i>Bz</i> \$953.30
1	REAR TAILGATE WINDSCREEN MOULDING		<i>m</i> \$120.00
1	REAR TAILGATE "VEZEL" EMBLEM		<i>m</i> \$32.90
1	REAR TAILGATE INNER TRIM BOARD		<i>Sm</i> \$153.40
1	REAR TAILGATE REFLECTOR LAMP LH		<i>Sm</i> \$264.60
1	REAR TAILGATE MECHANISM LOCK		<i>Net</i> \$216.20
1	REAR TAILGATE WEATHERSTRIP		<i>Gr</i> \$198.00
1	REAR TAILLAMP LH		<i>Gr</i> \$487.50
1	REAR BUMPER CENTER		<i>Bz</i> \$528.30
1	REAR BUMPER REFLECTOR LH		<i>Sm</i> \$151.40
8	REAR BUMPER CLIP	\$3.90	<i>m</i> \$31.20
2	REAR BUMPER SIDE RETAINER LH/RH	\$14.50	<i>Sm</i> \$29.00
1	REAR SIDE BUMPER LH		<i>Sm</i> \$195.00
1	REAR END PANEL		<i>Bz</i> \$470.30
1	REAR END PANEL TAILGATE ANTENA SENSOR BUZZER		<i>CM</i> \$85.00
1	REAR END PANEL INNER TOP GARNISH		<i>Net</i> \$98.00
1	REAR FENDER ARCH GARNISH LH		<i>mj.m</i> \$192.00
1	REAR WELL PANEL LOWER UNDER COVER		<i>CM</i> \$213.20
2	REAR WELL PANEL LOWER UNDER COVER CLIP	\$8.80	<i>m</i> \$17.60
1	REAR WELL PANEL INNER TOP TOOLS SPONGE		<i>CM</i> \$215.00

SUB TOTAL	\$4,651.90	4226.51
Less 20%	-\$930.38	355.30
PARTS TOTAL	\$3,721.52	3421.20

Not Authorized
1-B,
Purvey Bepany
85286.81
- 6 days

LKK Auto Consultants hence no
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Page 1
Signature: _____
Date: _____

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500

Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 June 2018

Vehicle No: SLA7913Y

Third Party Insurer:

ERGO

Model: HONDA VEZEL

Third Party Veh No:

SGQ9002M

Chassis: RU11104321

Date of Accident:

22 June 2018

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		\$100.00
1	REAR BUMPER REVERSE SENSOR		\$280.00
S/N TOTAL			\$380.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

800 \$1,000.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

800 \$1,000.00

TO TUFF KOTE / ANTI-RUST

601 \$80.00

TO CHECK WIRING WITH WATER LEAKAGE TEST

\$60.00

TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA

\$80.00

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$80.00

TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST

\$150.00

TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR

\$360.00

LABOUR TOTAL \$2,810.00

WINSON

TOTAL \$6,911.52

P - \$ 3421.20

S - \$ 240.00

L - \$ 2040.00

\$ 5701.20 +/P 87445



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG118011595/Ksd3n2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 17-09-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGQ 9002M	Veh. Inspected	SLA 7913Y
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1801206	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	26/06/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11104321	Colour	METALLIC PEARL WHITE
Odometer	36833	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/06/2018	Inspection Date	26/06/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7913Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	953.30	953.30
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	120.00	120.00
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	32.90	32.90
1	REAR TAILGATE INNER TRIM BOARD	SERVICEABLE	153.40	-
1	REAR TAILGATE REFLECTOR LAMP LH	SERVICEABLE	264.60	-
1	REAR TAILGATE MECHANISM LOCK	DENTED	216.20	216.20
1	REAR TAILGATE WEATHERSTRIP	CUT	198.00	198.00
1	REAR TAILLAMP LH	CUT	487.50	487.50
1	REAR BUMPER CENTER	BENT	528.30	528.30
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	151.40	-
8	REAR BUMPER CLIP @\$3.90	NECESSARY	31.20	31.20
2	REAR BUMPER SIDE RETAINER LH/RH @\$14.50	SERVICEABLE	29.00	-
1	REAR SIDE BUMPER LH	SERVICEABLE	195.00	-
1	REAR END PANEL	BENT	470.30	470.30
1	REAR END PANEL TAILGATE ANTENA SENSOR BUZZER	CRACKED	85.00	85.00
1	REAR END PANEL INNER TOP GARNISH	DENTED	98.00	98.00
1	REAR FENDER ARCH GARNISH LH	MTG CRACKED	192.00	192.00
1	REAR WELL PANEL LOWER UNDER COVER	CRACKED	213.20	213.20
2	REAR WELL PANEL LOWER UNDER COVER CLIP @\$8.80	NECESSARY	17.60	17.60
1	REAR WELL PANEL INNER TOP TOOLS SPONGE	CRACKED	215.00	215.00
	LESS 20% DISCOUNT		-930.38	-771.69
			3,721.52	3,086.81
SPECIAL NETT ITEMS				
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER (SN)	NECESSARY	100.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED	280.00	200.00
			380.00	240.00
LABOUR				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.		1,000.00	800.00

Report Ref No. CS/EG18011595/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		1,000.00	800.00
	TO TUFF KOTE/ANTI-RUST.		80.00	60.00
	TO CHECK WIRING WITH WATER LEAKAGE TEST.		60.00	20.00
	TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA.		80.00	50.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR.		80.00	50.00
	TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST.		150.00	120.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		360.00	60.00
			2,810.00	1,960.00
GRAND TOTAL			6,911.52	5,286.81
RECOMMENDED COST OF REPAIRS				5,286.81

Report Ref No. CS/EG18011595/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.