

SMA 126L

\$ 120.00

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

25 JUN 2018

Estimate No. : b1 47422 Page No. : 1 of 5  
Date Estimated : 25/06/2018  
Prepared By : Han Kwan Yong

<p><b>- ESTIMATE REPAIR FOR -</b> Yeo Meow Im, Karen 5, Kovan Road #04-20  Singapore 544894</p>	<p><b>- ACCOUNT - 40000</b> Cash Sales - Service Singapore</p>
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA126L	EG21717	26/04/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace rear bumper & attachments, boot lid including to knock out tail panel and dented area caused by the accident	2125 2,975.00
To respray rear bumper, boot lid and tail panel ?	1800 2,749.00
To carry out body cavity preservation. (Per panel).	100 118.00
To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.	561? 661.00
To conduct water leak tests.	63 75.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 150.00

Total Labour 1: **6,905.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,200.50	1,200.50
REAR LH BUMPER MOUNT	1	142.55	? 142.55
REAR RH BUMPER MOUNT	1	142.55	? 142.55
# RR BUMPER CARRIER	1	456.90	? 456.90
MOUNTING SMART OPENER	1	36.60	? 36.60
REAR TRIM UNDERRIDE PROTECTION (X L	1	99.85	? 99.85
RR BUMPER LH CORNER MOUNTING	1	142.55	? 142.55
RR BUMPER RH CORNER MOUNTING	1	142.55	? 142.55
# REAR BUMPER PANEL PRIMED	1	723.45	de 723.45
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	227.90	aut 227.90
REAR BUMPER TRIM BOTTOM (LINES)	1	217.05	de 217.05
EMBLEM GROMMET	2	0.80	neu 1.60
BMW PLAQUE WITH ADHESIVE FILM	1	69.50	neu 69.50

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 47422**  
Date Estimated : **25/06/2018**  
Prepared By : **Han Kwan Yong**Page No. : **2 of 5**REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE  
**SMA126L EG21717 26/04/2018 X1 sDrive18i 0**

DESCRIPTION	QTY	PRIC	VALUE
LETTERING X1	1	62.55	all ✓ 62.55
REAR BUMPER TOWING EYE COVER	1	35.55	X 35.55
REAR BUMPER HEAT INSULATION	1	67.85	? 67.85
CLIP	10	1.30	all ✓ 13.00
PLUG BLACK D=5MM	10	0.90	all ✓ 9.00
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	? 42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	? 40.50
REAR LH REFLECTOR	1	36.25	X 36.25
REAR RH REFLECTOR	1	36.25	Y 36.25
ULTRASONIC SENSOR BLACK	2	248.70	? 497.40
DECOUPLING RING PDC TORQUE CONVERTER	2	5.05	? 10.10

Total Parts : **4,454.10**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date/Time 19/7/18 Excess S\$ \_\_\_\_\_

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97445744 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail tanjiah@thekambon.com

No. of Working Days Recommend 5 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Labour 1	:	<b>6,905.00</b>
Parts	:	<b>4,454.10</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>795.14</b>
<b>Grand Total</b>	:	<b>12,154.24</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*****\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***