

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX6960X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR EXHAUST COVER	1680.00	560.00
2	ZZ/002	TO RESPRAY REAR BUMPER ASSY	880.00	440.00
3	ZZ/003	TO REMOVE AND CHECK REVERSE SENSOR CONDITION	60.00	40.00
4	ZZ/004	SUNDRIES	50.00	20.00
5	ZZ/005	TO REPAIR REAR END PANEL (SUPP)	560.00	560.00 (A) rec ✓
6	ZZ/006	TO RESPRAY END PANEL (SUPP)	440.00	440.00 (A) rec ✓
TOTAL LABOUR CHARGES			3670.00	2060.00