

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7407

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0355/18
DATE : 20-JUN-2018

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : ONG SIONG KHIM
ADDRESS : 30 ONAN ROAD
#16-04
S(424482)
TELEPHONE NO : 96661001

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SLL6653X
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2334610A
CHASSIS NO : SJNFEAJ11U1772834
MILEAGE : 23911 KM
DATE IN : 20/06/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 20/06/2018

*Not Authorised
allow repairs
take photo before & after
27/6/18
2 days*

- 67038691

elmer@fanchong.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL6653X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW REAR BUMPER & REAR END PANEL.	800.00	390
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	500.00	250
3	ZZ/003	REMOVE AND INSTALL REVERSE SENSOR.	55.00	✓
4	ZZ/004	APPLY SEALANT TO REAR END PANEL	<i>11</i> 150.00	X
TOTAL LABOUR CHARGES			1505.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL6653X

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REAR LICENCE PLATE	RLP		11	80.00	X
2	PLATE-LUGGAGE REAR	84992-4EA0A	11	63.50		X
3	WEATHERSTRIP TAIL GATE	90830-4EA0B	11	158.70		X
4	BACK TAIL GATE LOCK	90502-4EA0D	11	116.70		X
5	STRIKER-TAIL GATE	90570-4EA0A	11	31.70		X
6	REAR END PANEL	G9110-4EAMA	11	482.60		X
7	REINFORCEMENT REAR BUMPER	H5030-4EAMA	11	619.20		X
8	ENERGY ABSORBER REAR BUMPER	85090-4EA0B		126.40		?
9	TOW HOOK COVER REAR	85071-4EA0A	11	16.80		✓
10	BRACKET-REAR BUMPER SIDE RH	85220-4EA0A		35.90		?
11	BRACKET-REAR BUMPER LH	85221-4EA0A		35.90		?
12	CLIP REAR BUMPER @1.20 EACH	01553-05933	11	7.20		✓
13	REAR BUMPER	85022-4EA0H	11	717.00		✓
SUB TOTAL			2411.60	0.00	80.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			482.32	0.00	0.00	
GRAND TOTAL			1929.28	0.00	80.00	
OVERALL TOTAL			2009.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL6653X

TOTAL LABOUR CHARGES 1505.00
TOTAL SPARE PARTS CHARGES 2009.28

GRAND TOTAL 3514.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.