

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 5988S

DATE 25/6/2018

MAKE :

MODEL : HYUNDAI i40

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>Des</i>			\$ 1,681.40	
	Boot Lid 'H' Emblem <i>me</i>			\$ 27.20	
	Boot Lid CRDI Plate <i>me</i>			\$ 41.00	
	Bootlid Moulding <i>X su</i>			\$ 85.00	
	Bootlid i40 Emblem <i>me</i>			\$ 41.00	
	Bootlid Lower Garnish <i>X report</i>			\$ 398.00	
	Rear Bumper <i>Des</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>me</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Des</i>			\$ 360.00	
	Rear Bumper Side Bracket <i>X su</i>			\$ 98.00	
	Rear Bumper Clips <i>me</i>			\$ 22.00	
	Rear Bumper Sponge <i>X su</i>			\$ 143.40	
	Rear Bumper Under Cover <i>cl</i>			\$ 225.00	
	Rear Panel <i>X report</i>			\$ 592.30	
	Rear Panel Garnish <i>X su</i>			\$ 57.70	
	Rear Panel Lower Panel <i>X report</i>			\$ 495.50	
	SUB TOTAL			\$ 5,375.45	
	LESS 20%			\$ 1,075.09	
	DISCOUNTED TOTAL			\$ 4,300.36	
	Boot Lid Comfort Logo & Tel No. Sticker <i>me</i>			\$ 30.00	Nett
	Rear Bumper Reverse Sensor <i>sketch</i>			\$ 135.70	Nett
				\$ 165.70	
	Labour Charge				
	Panel Beating			\$ 850.00	
	Spray Painting Charge			\$ 750.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 50.00	
	Remove/Refix Reverse Sensor			\$ 120.00	
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 6,286.06	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by the Insurance Company

TOTAL LABOUR

Acknowledged by Repairer

ESTIMATE TOTAL

Date:

Kalvin 16/11/14

25/6/18 11:00h

3 Pys

LIS

After Repair photo