



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 02.07.2018

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01/02

AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Let's Auto Consultants, hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2729C PRIUS HYBRID 1.5EX A (2011)

### To supply

|         |                                 |    |                      |
|---------|---------------------------------|----|----------------------|
| 1 ) 1pc | Front bumper                    | \$ | 482.00 <i>cl</i>     |
| 2 ) 1pc | Front bumper clip               | \$ | 30.00 <i>me</i>      |
| 3 ) 1pc | Front bumper left side retainer | \$ | 122.00 ?             |
| 4 ) 1pc | Left side mirror assy           | \$ | 556.84 <i>repair</i> |
| 5 ) 1pc | Left side mirror cover          | \$ | 105.20 <i>repair</i> |

---

 \$ 1,296.04

Sub total parts \$ (324.01)

Less: 25% discount \$ 972.03

### To Supply S.nett parts

|          |                                         |    |                   |
|----------|-----------------------------------------|----|-------------------|
| 1 ) 1 pc | Left front fender advertisement sticker | \$ | 180.00 <i>rec</i> |
|----------|-----------------------------------------|----|-------------------|

---

 Sub total S.Nett Parts \$ 180.00

### L/charges

|                                                                                                           |    |                       |
|-----------------------------------------------------------------------------------------------------------|----|-----------------------|
| 1 ) To tuff kote.                                                                                         | \$ | 50.00                 |
| 2 ) To remove front bumper & left side mirror. Knock & repair left front fender. Replace the above parts. | \$ | <del>350.00</del> 300 |
| 3 ) To putty, respray painting left side mirror cover, left front fender & front bumper. To polish.       | \$ | <del>350.00</del> 300 |

---

 Sub total L/charges \$ 750.00

---

 Estimated Total \$ 1,902.03

*Resu*
*Hp 90010068*
*3 days*
*4s*
*03/07/18 @ 1645*
*Resu after repair*