

15/5/2010

INS. CASE OWNER:

1CC

CC4 / AXA1801

1619, 6063⁵²

LKK:

IDAC:

Surveyor:

x6Q

DOI:

27/6/18

Date / Time:

17/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

FBL 8655X

Name of Insured:

GOLF TIAN SENG.

Insured Tel No.:

HP: 96533379

Excess Sec II :SS

D.O.A:

11/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8MOOKP21/53920

Policy No.:

P19 64082

Make / Model:

HONDA

Place of Accident:

RAPPLES BOULEVARD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SLR 8747K

INSRS:
WSP:
Tel:
Liability:
RMKS:

W-51

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SLR 8747K - 6

FBL 8655X - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 5.7.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice: RARE

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

17/18

Sent By:

Bee

FINALIZATION

Date/Time:

Confirm with:

Confirm by: x6Q

Repair Cost:

4%

SS 2,000

(5 days) Reduction:

50 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

31.12.18

Confirm with: SARINA

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NR

If NO or B 28, Ass. Lia:

Repair Cost:

0.651

SS 2,140.00

OI LOST CONTROL HIT TP.

Loss of Rental (LOR):

SS 434.75

(5 days) x 84.95

Loss of Use (LOU):

SS -

(S x days)

Loss of Income (LOI):

SS 250.00

(S 50 x 5 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

3350

Total:

SS 2,822.20

Global Sum S\$:

FINAL PAYMENT

Date/Time:

31.12.18

Confirm with: SARINA

Email ☒ Call ☐

Payee 1:

SS 2,822.20

Name 1:

N-51 AUTOMOTIVE PIR LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

CSS/ASM18011619/G246

Special Instruction:

Surveyor:

Smart claim

ASSIGNMENT (Office)

From (Person):

Chan Kian Chuan

of

ASM

Date/Time:

26062018 2:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 8347K

Insured:

FBL 8655X

at Workshop m/s

N-51 Automofix

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

Claim No:

S8M00 KP9

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

27062018 @ before 12pm

H.O.D. Endorsement:

Date/Time:

26062018 3:21pm

Person Contacted:

Elynn

Vehicle:

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLR 8347K - X

FBL 8655X - X

260618 1:43pm

Confirmed with repairer all grab car do 'DS'

(084 (713) wof

ASS. REC. BY:

REF: ASM(AXA)

ASSIGNMENT

From: Date: 27/6/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 8347K

at Workshop m/s N-51 Automotive

of 2 Kaki Bukit Ave 2 #01-17

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record) Before 12pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$91K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLR 8347K Yr Regn: 29 Aug 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 102969 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU31253161

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 25/60 R 16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SIHTT

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45: ± 2.00 (RED: 9 1.994.40 50/-)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011619/Geb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-06-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBL 8655X	Veh. Inspected	SLR 8347K
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00KP9	Excess (\$)	0.00
Assign From	SMART CLAIM (CHAN KIAN CHUAN)	Assign Date	26/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/06/2018	Inspection Date	27/06/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 92313188

ESTIMATE

Repair Code : CLM14598

Date in : 11/06/2018

Vehicle Num. : SLR8347K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253161/LEB5953180

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR / <i>Buc</i>	1	852.00	852.00
FRONT LH DOOR BLACK TAPE / <i>ABC</i>	1	35.00	35.00
FRONT LH DOOR GLASS OUTER MOULDING <i>X LANN</i>	1	58.00	58.00
FRONT LH DOOR SIDE MIRROR <i>X</i>	1	606.00	606.00
FRONT LH DOOR SIDE MIRROR COVER / <i>Cut</i>	1	78.00	78.00
FRONT LH FENDER ARCH GARNISH / <i>SCR</i>	1	201.00	201.00
REAR LH DOOR TRANSPARENT STICKER / <i>ABC</i>	1	35.00	35.00
REAR LH FENDER ARCH GARNISH / <i>Cut</i>	1	201.00	201.00
ROCKER GARNISH LH / <i>Cut</i>	1	377.00	377.00
Subtotal before discount			2,443.00
Percentage discount 20%			488.60
Sub-total 1			1,954.40
FRONT LH FENDER ARCH GARNISH CLIPS - SET / <i>ABC</i>	1	50.00	50.00
REAR LH FENDER ARCH GARNISH CLIPS - SET / <i>ABC</i>	1	50.00	50.00
ROCKER GARNISH LH CLIPS - SET / <i>ABC</i>	1	100.00	100.00
Subtotal before discount			200.00
Percentage discount 0%			0.00
Sub-total 2			200.00
Parts-total			2,154.40

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 92313188

ESTIMATE

Repair Code : CLM14598

Date in : 11/06/2018

Vehicle Num. : SLR8347K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253161/LEB5953180

LABOUR

To remove, reinstall window glass. (to FR)

40 100.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

60 120.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

500 750.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400 750.00

To apply anti-rust chemical on repaired and replaced panel.

40 120.00

Labour Total

1,840.00

Parts & Labour Total

3,994.40

*** This is a computer-generated document which requires no signature.***

page 2

SDays.

Lump Sum Repair

After repair photos.

Guo Qiang - 8288 0282

21/6/18



Service Request Details

Claim

S8M00KP9

Reference

None 

Loss Date

June 11, 2018

Request Date

June 26, 2018

Due Date

July 3, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLR8347K

Make

TPVD HONDA

Model

VEZEL HYBIRD

Service Address

...

Primary Contact/Insured

GOH TIAN SENG

BLK 40 BEO CRESCENT, #03-22, 160040, Singapore

JGTS3110@YAHOO.COM.SG

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



MANDATE REQUEST FOR S8M00KP9

K.C.

Type

🔔 Question

Message

Liability: Insured lost control and hit third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$2,140.00 (w/GST) Loss of Rental: \$424.75 (5days x \$84.95) Loss of Income: \$1,008.40 (5days x \$201.68) LTA : \$7.45 Total: \$3,580.60 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (21/11/2018)

[Reply](#)



Re:MANDATE REQUEST FOR S8M00KP9

Type

🔗 Question

Message

Repair Cost : \$2,140.00 (w/GST) Loss of Rental: \$424.75 (5days x \$84.95) Loss of Income: \$250(5days) LTA :
\$7.45 Total: \$2,822.20

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBL 8655X (Insd veh)	Model:	HONDA VEZEL HYBIRD 1.5X
	SLR 8347K (TP veh)		
Date of Accident:	11/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	4,274.01	
Final Repair Cost	:	\$	2,140.00	
Loss of Use	:	\$	250.00	5 days at \$50.00 per day
Rental (if any)	:	\$	424.75	5 days
LTA / GIA Search Fee	:	\$	7.45	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	2,822.20

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	N-51 AUTOMOTIVE PTE LTD	:	\$ 2,822.20

NUR SHAQILAH BTE ABDOL
WAHAB

28/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011619/Geb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-01-2019		
ATTN: KIAN CHUAN		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBL 8655X	Veh. Inspected	SLR 8347K	
Policy No.	P1963082	Coverage (\$)	0.00	
Claim No.	S8M00KP9	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	02/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBIRD 1.5X	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31253161	Colour	BLACK	
Odometer	102969	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	SJHTT	6 mm	
L/H Front Tyre	215/60R16	SJHTT	6 mm	
R/H Rear Tyre	215/60R16	SJHTT	6 mm	
L/H Rear Tyre	215/60R16	SJHTT	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/06/2018	Inspection Date	27/06/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8347K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH DOOR (CONSISTENT)	BUCKLED	852.00	852.00
1	FRONT LH DOOR BLACK TAPE (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT LH DOOR GLASS OUTER MOULDING (CONSISTENT)	NOT NECESSARY	58.00	-
1	FRONT LH DOOR SIDE MIRROR (CONSISTENT)	NOT NECESSARY	606.00	-
1	FRONT LH DOOR SIDE MIRROR COVER (CONSISTENT)	CUT	78.00	78.00
1	FRONT LH FENDER ARCH GARNISH (CONSISTENT)	SCRATCHED	201.00	201.00
1	REAR LH DOOR TRANSPARENT STICKER (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR LH FENDER ARCH GARNISH (CONSISTENT)	CUT	201.00	201.00
1	ROCKER GARNISH LH (CONSISTENT)	CUT	377.00	377.00
	LESS 20% DISCOUNT		-488.60	-355.80
			1,954.40	1,423.20
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT LH FENDER ARCH GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REAR LH FENDER ARCH GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET ROCKER GARNISH LH CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	100.00
			200.00	200.00
<u>LABOUR</u>				
	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)		100.00	40.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.		120.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		750.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		750.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			1,840.00	1,040.00
GRAND TOTAL			3,994.40	2,663.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC4/ASM18011619/Geb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.