



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 25.06.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLR7469Z TOYOTA AXIO HYBRID

To Supply

1)	1pc	rear bumper	\$	700.00 <i>de</i>
2)	1set	rear bumper clip	\$	30.00 <i>ne</i>
3)	1pc	rear bumper left side retainer	\$	60.00 <i>ne</i>
5)	1pc	rear bumper left reflector	\$	94.00 <i>x</i>
7)	1pc	rear bumper left inner ventilation duct	\$	20.00 <i>?</i>
9)	1pc	left tail lamp lower bracket	\$	70.00 <i>ne</i>
10)	1pc	left tail lamp	\$	450.00 <i>ne</i>
12)	1pc	left tail lamp housing	\$	285.60 <i>Ry</i>
14)	1pc	left tail lamp lower bracket	\$	70.00 <i>x repeat</i>
16)	1pc	rear boot lid	\$	680.00 <i>Ry</i>
21)	1pc	rear boot lid "corolla" emblem	\$	59.60 <i>ne</i>
22)	1pc	rear boot lid "Hybrid Synergy Drive" emblem	\$	61.70 <i>ne</i>
23)	1pc	rear boot lid "Axio" emblem	\$	48.60 <i>ne</i>
24)	1pc	rear boot lid weatherstrip	\$	120.00 <i>twi</i>
25)	2pcs	rear boot lid hinges	\$	315.20 <i>Ry</i>
28)	1pc	rear end panel	\$	380.00 <i>?</i>
29)	1pc	rear end panel top garnish	\$	180.00 <i>?</i>
30)	1set	rear end panel top garnish clip	\$	20.00 <i>?</i>
33)	1pc	left rear fender assy	\$	885.80 <i>Ry</i>
34)	1pc	left rear fender mudflap	\$	72.60 <i>?</i>
35)	1pc	left deck floor box 64997-13051	\$	518.10 <i>x</i>
36)	1pc	package tray trim. panel assy 64330-12A30	\$	614.00 <i>x</i>

@\$157.60

37)	lpc	package tray trim pad 64334-12380	\$	26.00	X
40)	lpc	left rear luggage compartment cover 64713-12011	\$	316.00	X

Sub total parts	\$	6,077.20
Less: 25% discount	\$	(1,519.30)
	\$	4,557.90

To supply S.Neti parts

1)	1set	reverse sensor	\$	180.00	Mu ✓
-----	------	----------------	----	--------	------

L/charges

1)	Towing charges (use king trolley)	\$	80.00	✓
2)	To transfer rear boot lid trim board, mechanism parts	\$	50.00	X
3)	To tuff kote rear portion	\$	150.00	60
4)	To remove fuel tank to facilitate the repair	\$	100.00	X
5)	To remove & replace reverse sensor	\$	40.00	30
6)	To remove rear bumper, cut / welding rear end panel, knock floor panel, left rear fender, replace rear boot lid, rear bumper, left . Align rear boot lid, rear bumper & etc.	\$	1,200.00	800
7)	To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel, floor panel & left rear fender. To polish	\$	1,400.00	800

Sub total L/charges	\$	3,020.00
Estimated total	\$	7,757.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanglin 97495744
26/6/18 @ 12pm
6 days 'WP'
Resurvey after repair
sur @ (Mkando.com)