

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3055G

DATE 25/6/2018 15:24

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Clips ✓			\$ 22.00
	Tail Lamp (RH) ✓			\$ 565.60
	Rear Fender (RH) ✓			\$ 2,020.10
	Rear Fender Inner Lining (RH) ✕			\$ 164.40
	Rear Windscreen Moulding ✓			\$ 60.00
	Rear Wheel Hub Cap, RH ✕			\$ 150.70
	SUB TOTAL			\$ 3,586.40
	LESS 20%			\$ 717.28
	DISCOUNTED TOTAL			\$ 2,869.12
	Rear Bumper Rubber Mat ✓			\$ 50.00
	Rear Windscreen Sealant ✓			\$ 46.00
				\$ 96.00
	Labour Charge			600
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,840.00
	ESTIMATE TOTAL			\$ 4,805.12

Kalvin LKK
 26/6/18 14:15h
 4872
 PIP
 Before PIP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.