

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE344HYr Regn: 2015, AugustType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dynac.c. 2982Colour: Blues

A/C: Insured / Std / NI / NA

Sp. Reading: 67612

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEAT3SY00K204532Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 195 R15C

Journey

R: 155 R12C Yokoo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 25/06/18Survey held at NHTDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orFront o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP (11)

L/S \$2800

R (\$3,471.10/55%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

b)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

c)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + RM \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.E. (\$



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

18/06/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111

Joy

Accident date: 18/06/2018

Estimated repair cost for vehicle no: GBE344H TOYOTA DYNA 150 3.0 M '15

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Best</i>		\$356.20 ✓
2	1	Front Grille <i>Net rec</i>		\$372.70 ✓
3	1	Front R/H Head Lamp <i>lit</i>		\$573.90 ✓
4	1	Front R/H Side Panel <i>deded</i>		\$192.25 ✓
5	1	Front R/H Side Panel Top Cover <i>cut</i>		\$181.45 ✓
6	1	Front R/H Door <i>deded</i>		\$1,712.10 ✓
7	1	Front R/H Door Side Mirror Assy <i>new</i>		\$398.40 ✓
8	1	Front R/H Door Sticker (Special <i>Nett</i>) <i>new</i>		\$30.00 ✓
9	1	Front R/H Step Panel <i>lit</i>		\$374.10 ✓

3420

2565

Subtotal :- \$4,191.10

Auto Consultants hence notify
Repairer of the following:

Labour charges

- To display damaged parts, during recovery.
- To remove & refit R/H door, gear motor, trim board, lock & glass
- To check wiring
- Tuff kote
- Panel beating
- Spray painting

knowledge by Repairer

date:

\$180.00 *80*

\$50.00 *30*

\$150.00 *+*

\$850.00 *70*

\$850.00 *450*

Subtotal :- \$2,080.00

Total:- \$6,271.10

total 3525

N/S 28K

28K

Adrian King

25/06/18

N/S 04 Days

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 70000

Vehicle Details

Vehicle No.: GBE344H
Vehicle to be Exported: Yes
Intended De-registration Date: 18 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA DYNA 150 MANUAL
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: 1KD2493550
Chassis No.: JTFAT35Y00K204532
Maximum Power Output: -
Open Market Value: \$27,856.00
Original Registration Date: 21 Aug 2015
First Registration Date: 21 Aug 2015
Transfer Count: 0
Actual ARF Paid: \$1,393.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Aug 2025
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$5,105.00
COE Rebate Amount: \$3,661.00
Total Rebate Amount: \$3,661.00

The information contained herein is correct as at 18 Jun 2018

OK

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1807-0145 / GBE344H
Yr Ref : SHA5334D
Date : 25th July 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

WITHOUT PREJUDICE

Dear Sirs,

**RE: ACCIDENT INVOLVING GBE344H & SHA5334D AT 36 CHAI CHEE AVE ON 17.06.2018,
13:00HR**

We are instructed by **TAN BOON SENG INTERIOR & DECORATION** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **GBE344H** was damaged by vehicle **SHA5334D** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 2,800.00
2) Loss of Use for 04 days	\$ 600.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 3,407.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$3,407.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,



NEW HOCK TECK MOTOR PTE LTD



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

India International Insurance Pte Ltd

64 Cecil Street #04/ #05

IOB Building

Singapore 049711

Invoice No : NPL1807-0145

Date : 25-Jul-18

Date of Accident : 17-Jun-18

Vehicle No. : GBE344H

Client: TAN BOON SENG INTERIOR & DECORATION

Model Type : Toyota Dyna

Descriptions		Amount
Lump Sum Repair Cost		2,800.00
Total		2,800.00

SIN DOLLARS: TWO THOUSAND AND EIGHT HUNDRED ONLY



> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 18 Jun 2018 / 09:38:03

Receipt Date/Time : 18 Jun 2018 / 09:38:03

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180618-000297

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHA5334D

As at 17 Jun 2018/13:00:00

Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SHA5334D

Enquiry Fee

20180618093731185353

7.00 0.49 7.49

Sub-Total

7.00 0.49 7.49

Total Before Rounding

7.00 0.49 7.49

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

xxxxxxxxxxx4469	Credit Card: Visa/MasterCard	7.45
-----------------	---------------------------------	------

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd

Kaki Bukit Avenue 6

Blk 1 #01-43

Singapore 417883

Dear Sir,

Accident on

Involving Vehicles

Along

17/06/18, 13:00

GBE344H, SHA5334D

36 Chai Chee Ave

I/We, the registered owner/driver of vehicle registration no: GBE344H
have involved in the above accident.

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, _____, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,


TAN BOON BENG INTERIOR & DECORATION

Owner's Signature

(Company's stamp if applicable)

Name: _____

NRIC No.: _____

Date: _____

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)


In consideration for your agreement to repair my motor vehicle registration no. GBE3441 and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).


I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 25 day of 06 2013.

Signature :  TAN BOON SENG INTERIOR & DECORATE
Name : Tan Boon Seng Interior & Decoration
ID No. : 3071700010
Address : _____

Witness Signature : 
Witness Name : Chew Yue Yin
Witness ID : 18266187
Witness Address : 1 Kaki Bukit Avenue 6 #01-43
Singapore 417883

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 24 August 2018 12:09 PM
To: 'Admin nht'
Cc: Chloe; Admin A
Subject: GBE344H CLAIMING SHA5334D DOA 17.06.18
Attachments: III VIDEO.mp4

WITHOUT PREJUDICE

Dear Sukyi,

Attached video evidence for your viewing.

Based on video, your swerved into our insured's vehicle which was travelling straight on his lane.

In view of this, we regret to inform you that we are unable to look into your claim.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

View Received Message

This mail is associated with :

*GBE344H (MCT18060510)
[SHA5334D]
TP
TAN BOON SENG INTERIOR DECORATION
Jun 17 2018 1:00PM

New Hock Teck Motor Pte Ltd

- Reply
- Reply All
- Mark as Unread
- Print Message
- Delete Message
- Forward

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 15/08/2018 15:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - GBE344H - Claim Handler: NATALIE LEE

Approved:0.00.

DOCUMENTS SUMMARY
There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2018 Edit Reg		25 Jun 2018 00:00 Edit Adj Rpt	\$2,800.00 Edit Estimates	\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	TAN BOON SENG INTERIOR DECORATION , Co. Reg. No.: 30717000D								
Vehicle Reg. No.:	GBE344H	Date of Loss:	17/06/2018 13:00 - :59 [33 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060510	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA5334D	Policy No. (Claimant):	MU009281						
		Excess:							
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (15/08/2018): Alert - Adj Mandate Approved (\$0.00) - GBE344H - Claim Handler: NATALIE LEE III_SG (03/07/2018): Alert - Adj Mandate Approved (\$0.00) - GBE344H - Claim Handler: NATALIE LEE 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE344H (MCT18060510)
[SHA5334D]
TP
TAN BOON SENG INTERIOR DECORATION
Jun 17 2018 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video										1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	India International Insurance Pte Ltd (HQ)								Thumbnail		Print		
1	03/07/18 10:32	Video - Accident								1 Load MP4				
Photos/Images										3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print		
1	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
2	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
3	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
4	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
5	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
6	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
7	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
8	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
9	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
10	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
11	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
12	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
13	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
14	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
15	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
16	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
17	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
18	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
19	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
20	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
21	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
22	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
23	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
24	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
25	15/08/18 14:21	General View								1 Load JPG		<input checked="" type="checkbox"/>		
Documentation										1 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print		
1	27/06/18 20:49	TP GIA REPORT								1 Load PDF				
2	29/08/18 14:42	REJECTION EMAIL								1 Load PDF				
No	Finalized On	India International Insurance Pte Ltd (HQ)								Thumbnail		Print		
1	28/06/18 09:10	Singapore Accident Statement								1 Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18011628/AJA3Q2

Date: 03/09/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : GBE344H **Insured Vehicle No :** SHA5334D
 Date of Loss: 17/06/2018 Nature of Claim: TP Claim No: MCT18060510

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE344H**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2493550
 Reg. Date: 21/08/2015 (Man. Year: 2015) Chassis No: JTFAT35Y00K204532
 Colour: Silver Odometer: 67612 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
 Front Left Side: Journey 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Journey 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,191.10	2,565.00	1,626.10	38.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	960.00	1,120.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,271.10	3,525.00	2,746.10	43.79
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	6,271.10	2,800.00	3,471.10	55.35
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/06/2018
 Date Inspected: 25/06/2018 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Sep 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE344H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	356.20 F	*356.20 FL
2	1		*FRONT GRILLE	Not Necessary	372.70 F	*- FL
3	1		*FRONT R/H HEAD LAMP	Cut	573.90 F	*573.90 FL
4	1		*FRONT R/H SIDE PANEL	Dented	192.25 F	*192.25 FL
5	1		*FRONT R/H SIDE PANEL TOP COVER	Cut	181.45 F	*181.45 FL
6	1		*FRONT R/H DOOR	Dented	1,712.10 F	*1,712.10 FL
7	1		*FRONT R/H DOOR SIDE MIRROR ASSY	Not Necessary	398.40 F	*- FL
8	1		*FRONT R/H DOOR STICKER	Necessary	30.00 F	*30.00 FL
9	1		*FRONT R/H STEP PANEL	Cut	374.10 F	*374.10 FL

F=Franchise part. L=List/ItemDisc.

Sub Total (S\$)	4,191.10	3,420.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	855.00

Total Parts (S\$)	4,191.10	2,565.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT R/H DOOR ,GEAT MOTOR ,TRIM BOARD ,LOCK & GLASS	New	180.00	80.00
2	TO CHECK WIRING	New	50.00	30.00
3	TUFF KOTE	New	150.00	0.00
4	PANEL BEATING	New	850.00	400.00
5	SPRAY PAINTING	New	850.00	450.00
Gross Labour Cost (S\$)			2,080.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >