

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 26.06.2018
VEH NO : SJR6577A
MODEL : Honda Civic
D O A : 24.06.2018
YR REF : SKB6741P

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJR6577A (Honda Civic)

| <u>Item</u> | <u>Description</u> | <u>Qty</u> | <u>Amt</u> |
|-------------|---|------------|------------|
| NO | LIST ITEMS | | |
| 1 | Rear Bumper <i>Distorted</i> | 1 | 638.00 ✓ |
| 2 | Rear Bumper Clips <i>m</i> | 1 set | 30.00 ✓ |
| 3 | Rear Bumper Side Holder - LH & RH <i>m</i> | 2 | 48.20 ✓ |
| 4 | Rear Bumper Exhaust Garnish <i>Distorted</i> | 1 | 25.30 ✓ |
| 5 | Rear End Panel <i>Distorted</i> | 1 | 300.50 ✓ |
| 6 | Rear End Panel Top Garnish <i>Distorted</i> | 1 | 78.60 ✓ |
| 7 | Taillamp - LH & RH <i>lt</i> | 2 | 452.40 ✓ |
| 8 | Taillamp Panel - LH & RH <i>Repair</i> | 2 | 131.40 ✗ |
| 9 | Bootlid <i>Distorted</i> | 1 | 693.80 ✓ |
| 10 | Bootlid Lock <i>Distorted</i> | 1 | 88.30 ✓ |
| 11 | Bootlid Weatherstripe <i>cut</i> | 1 | 100.30 ✓ |
| 12 | Bootlid Hinge - LH & RH <i>Best</i> | 2 | 120.80 ✓ |
| 13 | Bootlid Inner Trim Board <i>Not m</i> | 1 | 133.70 ✗ |
| 14 | Bootlid Inner Trim Board Clips <i>m</i> | 1 set | 30.00 ✓ |
| 15 | Bootlid Reflector - LH & RH <i>lt</i> | 2 | 404.40 ✓ |
| 16 | Honda Logo <i>2</i> | 1 | 36.90 ✓ |
| 17 | Civic Emblem <i>1 set</i> | 1 | 34.60 ✓ |
| 18 | 1.8 Emblem | 1 | 23.70 ✓ |
| 19 | i-Vtec Emblem | 1 | 40.50 ✓ |
| 20 | Rear Fender Inner Trim Board - LH & RH <i>Distorted</i> | 2 | 484.60 ✓ |
| 21 | Rear Fender Inner Trim Board Clips <i>new</i> | 2 sets | 60.00 ✓ |
| 22 | Spare Tyre Panel <i>Distorted</i> | 1 | 985.60 ✓ |
| 23 | Spare Tyre Panel Top Cover <i>Distorted</i> | 1 | 303.80 ✓ |
| 24 | Spare Tyre Lock Screw <i>Distorted</i> | 1 | 30.90 ✓ |
| 25 | Tools Tray <i>Distorted</i> | 1 | 162.50 ✓ |
| 26 | Rear Exhaust Pipe <i>Repair</i> | 1 | 514.20 ✗ |
| 27 | Rear Exhaust Chrome Pipe - LH & RH <i>new</i> | 2 | 194.40 ✗ |
| 28 | Rear Exhaust Mounting <i>new</i> | 1 | 36.00 ✗ |

RE : ESTIMATE FOR ACCIDENT REPAIR SKB6741P (Honda Civic)

| | | | | |
|----------|-------------------------------------|---------|---|-------------|
| 29 | Centre Exhaust Pipe <i>new</i> | 5173.70 | 1 | 637.50 x |
| 30 | Rear Fender - LH & RH <i>2y's</i> | 4138.96 | 2 | 1,487.60 x |
| 31 | Rear Windscreen Moulding <i>new</i> | | 1 | 89.30 x |
| | | | | <hr/> |
| | | | | 8,397.80 |
| Less 20% | | | | (1,679.56) |
| | | | | <hr/> |
| | | | | \$ 6,718.24 |

S/NETT ITEMS

| | | | | |
|-------------|--|--|-------|-------------------|
| 1 | Rear Number Plate <i>new</i> | | 1 | 30.00 x |
| 2 | Rear Number Plate Holder <i>new</i> | | 1 | 30.00 x |
| 3 | Reverse Sensor <i>Damaged</i> | | 1 set | 280.00 <i>220</i> |
| 4 | Rear End Panel Sealant <i>new</i> | | 1 | 60.00 ✓ |
| 5 | Taillamp Sponge Gasket - LH & RH <i>new</i> | | 2 | 40.00 ✓ |
| 6 | Bootlid Reflector Sponge Gasket - LH & RH <i>new</i> | | 2 | 40.00 ✓ |
| 7 | Spare Tyre Panel Insulation Pad <i>new</i> | | 1 | 280.00 <i>250</i> |
| 8 | Rear Windscreen Sealant <i>new</i> | | 1 | 60.00 x |
| | | | | <hr/> |
| Total Parts | | | | \$ 7,538.24 |

LABOUR CHARGE

| | | | |
|--------------|---|----|--------------------------|
| 1 | To knocking & pull out rear portion & renew above parts | \$ | 2,000.00 1400 |
| 2 | To putty & spray up paint works | \$ | 1,800.00 1200 |
| 3 | To check wiring | \$ | 50.00 30 |
| 4 | To remove reverse sensor | \$ | 100.00 60 |
| 5 | To remove upholstery and rear seat | \$ | 350.00 280 |
| 6 | To remove exhaust pipe | \$ | 250.00 100 |
| 7 | To underseal | \$ | 150.00 100 |
| 8 | To remove rear windscreen | \$ | 180.00 X |
| 9 | To transfer bootlid fittings | \$ | 150.00 80 |
| Total Labour | | \$ | 5,030.00 |

Grand Total

\$ 12,568.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

NOTE: Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 7998.96
A/S: 6.4K
09 Days

RE : ESTIMATE FOR ACCIDENT REPAIR SKB6741P (Honda Civic)

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|--------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 7608E |
| Vehicle Details | |
| Vehicle No.: | SJR6577A |
| Vehicle to be Exported: | Yes |
| Intended De-registration Date: | 26 Jun 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | CIVIC 1.6L 5AT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2008 |
| Engine No.: | R16A14001448 |
| Chassis No.: | JHMF046209S200405 |
| Maximum Power Output: | 92.0 kW (123 bhp) |
| Open Market Value: | \$22,244.00 |
| Original Registration Date: | 03 Jul 2009 |
| First Registration Date: | 03 Jul 2009 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$22,244.00 |
| Intended Date of Exportation & PARF | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 02 Jul 2019 |
| PARF Rebate Amount: | \$12,234.00 |
| Intended Date of Exportation & COE | |
| COE Expiry Date: | 02 Jul 2019 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$12,899.00 |
| COE Rebate Amount: | \$1,311.00 |
| Total Rebate Amount: | \$13,545.00 |

The information contained herein is correct as at 26 Jun 2018

OK

V/L

Hsiao Tong (LKKAUTO)

From: Chin <chin@modernautomotive.com.sg>
Sent: Wednesday, 23 January 2019 11:42 AM
To: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Asher Sng (LKKAUTO)
Subject: Re: SJR6577A (AIG)
Attachments: 20190123115131.pdf

Dear Hsiao Tong

Please let us have your offer of the above claims.

Thank you

Regards,
Grace Chin
Modern Automotive Pte Ltd
Blk 3023-A, Ubi Road 1 #01-61
Singapore 408717

Tel: 6748 4422
Fax: 6747 6720

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SKB6741P

Our Ref : SJR6577A

Date : 31.07.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-3000 Fax : 6-415-3727

Attn : The Motor Claim Dept

**RE : ACCIDENT INVOLVING SJR6577A & SKB6741P ON 24.06.2018
ALONG CTE TWDS TPE BEFORE AMK AVE 5 EXIT**

We refer to the above matter.

We have been authorized by our client Mr Teo Chu Laik to make claim against your insured vehicle No. SKB6741P in respect of the above accident for the following :

| | |
|----------------------------------|------------------------|
| Repair Cost | \$ 6,848.00 (Incl GST) |
| Loss of rental (\$120 x 10 days) | \$ 1,200.00 |
| Search fee | \$ 7.49 |
| Total : | \$ 8,055.49 |

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 APRIL 2019

CHEW KHEAN CHENG EIRENE
23 BALMORAL ROAD
#19-25
SINGAPORE 259806

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18011629/Ahb3

YOUR REF : SKB 6741P

ACCIDENT INVOLVING SKB 6741P AND SJR 6577A ALONG CTE TOWARDS SLE
ON 24.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SJR 6577A against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle SJR 6577A. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,


Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

edward@vinegroup.com.sg
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 3 April, 2019 4:09 PM
To: edward@vinegroup.com.sg
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SKB 6741P_ACCIDENT INVOLVING SKB 6741P AND SJR 6577A ALONG CTE TOWARDS SLE ON 24.06.2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 APRIL 2019

CHEW KHEAN CHENG EIRENE
23 BALMORAL ROAD
#19-25
SINGAPORE 259806

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18011629/Ahb3
YOUR REF : SKB 6741P
ACCIDENT INVOLVING SKB 6741P AND SJR 6577A ALONG CTE TOWARDS SLE ON 24.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SJR 6577A against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle SJR 6577A. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

LETTER OF AUTHORIZATION

Date: 25/6/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SJR 6577A & SKB 6741P

ON 24/6/18 ALONG CTE twds TPE before


AMK AVE 5 Exit

This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

Teo Chee Lark S1267608E

Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$7,800.00 (Global Sum – all in) for vehicle no. SJR 6577A that was damaged pursuant to the accident which occurred on 24/06/2018 (date) along CTE TOWARDS SLE (location) involving vehicle no/s SKB 6741P. This is pursuant to the inspection conducted on 26/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TEO CHU LAIK ("the third party claimant") of vehicle no. SJR 6577A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJR 6577A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 04 (day) of Apr (month) **2019** (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001233

Date : 31/07/2018
Vehicle Num. : SJR 6577A
Make/Model : HONDA CIVIC-2009
Chassis/Eng# :
Accident Date : 24/06/2018
Claim No. :
Reference :
Policy No. : S 28973160 SMF

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|---------------------------|------------|------------|
| | | LABOUR : | | |
| | | ACCIDENT REPAIR (LUMPSUM) | | 6,400.00 |
| | | Labour Total S\$: | | 6,400.00 |

Total S\$: 6,400.00
GST @ 7% S\$: 448.00
Amount Due S\$: 6,848.00
=====


MODERN AUTOMOTIVE PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TELI: 6383 2661 FAX: 6484 2836
REG. NO. 430058/00D

No. 19433

Date, 5/7/14

OFFICIAL RECEIPT

Received from

Teo Chu Lark

the sum of Dollars

One thousand two hundred only

being Payment Of

SXV 9A70X

(25/6/14 - 5/7/14)

DAWN ENTERPRISES

\$ 1200/-

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

TP
STR 6577A

Nº 35542

RENTAL AGREEMENT

DATE 25/6/18

HIRER'S PARTICULARS

Name TGO CHU LAIK
Address 24 Cactus Dr.
#03-12
S 809694
I/C or Passport No. 1267608E Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) 92288602 (Residence) _____

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

- No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
- This vehicle is licensed to carry 8 passengers only.
- Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
- For usage to Malaysia subject to higher excess all claims of S\$5,000.00 and different rental rate.
- Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
- No refund will be given for vehicle returns early.
- No refund will be given for petrol left in vehicle.
- Hirer is liable to pay all parking fee and traffic summonses.
- Vehicles to be return during office hour only.
- No Service on Public Holiday and Sunday.

SCHEDULE

MODEL

SKV9470X

T/1/1/1/1/1

| Date | Time | Mileage |
|----------------|------|---------|
| <u>25/6/18</u> | | |
| <u>5/7/18</u> | | |

CHARGES

| | |
|-------------------------------------|-------------------|
| 10 Day at \$ <u>120.00</u> per days | \$ <u>1200.00</u> |
| Day at \$ _____ per week | |
| Day at \$ _____ per month | |
| TOTAL AMOUNT | \$ <u>1200.00</u> |
| AMOUNT PAID | \$ <u>1200.00</u> |
| BALANCE DUE | |
| Days Extension From _____ To _____ | |
| Amount Deposit (refundable) \$ | |

FROM

25/6/18

TO

5/7/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES

Enquire Vehicle & Owner Information (Vehicle No. SKB6741P As At 24 Jun 2018 / 13:20:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MODERN AUTOMOTIVE

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1375826C

Owner Name: CHEW KHEAN CHENG EIRENE

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 23

Registered Street Name: BALMORAL ROAD

Registered Unit No.: # 19 - 25

Registered Building Name: -

Registered Postal Code: 259806

Current Vehicle Details

Vehicle No.: SKB6741P

Make Description/Model: MAZDA / MAZDA6 2.0L SDN V GRADE

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



Thank you

Minder Kaur has successfully logged out.

Your last login date and time was 25 Jun 2018, 16:48:11.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

| S/No. | Asset Type | Asset ID | Asset Owner ID | Transaction Type | Transaction Amount (\$) | Log Date/Time |
|-------|------------|----------|----------------|---|-------------------------|------------------------|
| 1 | Vehicle | SKB6741P | - | 18.19 Enquire Veh Owner Info (Others) by Law Firm | 7.49 | 25 Jun 2018 / 16:49:37 |

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING


















































| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|---|--|--|------------|---|
| Main | 27 Jun 2018 Edit Reg | | 26 Jun 2018 00:00 Edit Adj Rpt | \$56,400.00 Edit Estimates | \$56,400.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | CHEW KHEAN CHENG EIRENE , ID: S1375826C | | | | | | | | |
| Main Claimant: | TEO CHU LAIK , ID: S1267608E | | | | | | | | |
| Vehicle Reg. No.: | SJR6577A | Date of Loss: | 24/06/2018 13:00 - :59 [107 Months and 21 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 1568442059SG | Policy/Cover Note No.: | 2100339914 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SKB6741P | Policy No. (Claimant): | S289731605MF | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com | | | | | | | | |
| Claimant's Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/07/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SJR6577A (1568442059SG)
 [SKB6741P]
 TP
 TEO CHU LAIK
 Jun 24 2018 1:00PM
 [CHEW KHEAN CHENG EIRENE]
 Modern Automotive Pte Ltd

| | | | | | | | | | | | | | | | | | | | | |
|-------------------------|-----------------|--|--|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|-------------|----------|-------------|-----------------|--|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | | | View in Browser | | |
| Letters/Correspondences | | | | | | | | | | | | | | | 1 per page | | <div></div> | <div></div> | | |
| No | Finalized On | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | (Draft) | | Third Party Express Settlement – Payment Breakdown | | | | | | | | | | | | <div></div> | Edit | | | | |
| Photos/Images | | | | | | | | | | | | | | | 3 per page | | <div></div> | <div></div> | | |
| No | Relabel/Reorder | | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 2 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 3 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 4 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 5 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 6 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 7 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 8 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 9 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 10 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 11 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 12 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 13 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 14 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 15 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 16 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 17 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 18 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 19 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 20 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 21 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 22 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 23 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 24 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 25 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 26 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 27 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 28 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 29 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 30 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 31 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 32 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 33 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |
| 34 | 27/07/18 15:05 | | General View | | | | | | | | | | | | <div></div> | Load JPG | | <div></div> | | |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 35 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 27/07/18 15:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 27/07/18 15:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|---|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 84 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 85 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 86 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 87 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 88 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 89 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 90 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 91 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 92 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 93 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 94 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 95 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 96 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 97 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 98 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 99 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 100 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| 101 | 27/07/18 15:05 | Reinspection Photo | | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 26/06/18 16:53 | TP GIA REPORT | | |
| 2 | 03/04/19 15:39 | TP ESTIMATE - MARKED | | |
| 3 | 03/04/19 16:12 | EMAIL TO OI | | |
| 4 | 03/04/19 16:12 | LETTER TO OI | | |
| 5 | 12/04/19 09:39 | WORKSHOP INVOICE | | |
| 6 | 12/04/19 09:39 | AUTHORISATION TO ACT FORM | | |
| 7 | 12/04/19 09:39 | Release Voucher | | |
| 8 | 12/04/19 09:39 | LTA SEARCH | | |
| 9 | 12/04/19 09:39 | RENTAL RECEIPT | | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 27/06/18 13:17 | OI GIA REPORT | | |

Documents Checklist

| | | | |
|---|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer. <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|---------------------|--------|-------------------------|
| Vehicle No: | SKB6741P (Insd veh) | Model: | HONDA CIVIC 1.3 EC8 (M) |
| | SJR6577A (TP veh) | | |
| Date of Accident: | 24/06/2018 | | |

| | | |
|-----------------------------------|-------------|------------------------|
| Global Sum Settlement | : [X] Yes | : [] No |
| Repair Estimate | : \$ | 13,448.02 |
| Final Repair Cost | : \$ | 7,800.00 |
| Loss of Use | : \$ | days at \$0.00 per day |
| Rental (if any) | : \$ | 10 days |
| LTA / GIA Search Fee | : \$ | |
| Others: | : \$ | |
| | : \$ | |
| Final Settlement Sum (Global Sum) | : \$ | 7,800.00 |

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|---------------------------|------|----------|
| 1) | Modern Automotive Pte Ltd | : \$ | 7,800.00 |
| 2) | | : \$ | |
| 3) | | : \$ | |
| 4) | | : \$ | |

JOANNE LEE KHANG MIN

12 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18011629/AHB3Q2

Date: 12/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100339914

Claimant Vehicle No: SJR6577A

Insured Vehicle No: SKB6741P

Date of Loss: 24/06/2018

Nature of Claim: TP

Claim No: 1568442059SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR6577A**

Make & Model: HONDA CIVIC, 1.3 EC8 (M)

Engine No: R16A14001448

Reg. Date: 03/07/2009 (Man. Year: 2008)

Chassis No: JHMF46209S200405

Colour: Silver

Odometer: 245846 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|-----------------|--------------|
| Parts | 7,538.24 | 4,748.96 | 2,789.28 | 37.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,030.00 | 3,250.00 | 1,780.00 | 35.39 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,568.24 | 7,998.96 | 4,569.28 | 36.36 |
| Approved Total (Overridden) (S\$) | | 6,400.00 | | |
| (S\$) | 12,568.24 | 6,400.00 | 6,168.24 | 49.08 |
| + GST 7.00/7.00% (S\$) | 879.78 | 448.00 | 431.78 | 49.08 |
| Nett Amount (S\$) | 13,448.02 | 6,848.00 | 6,600.02 | 49.08 |
| + Car Rental (10.0 x S\$100.00/day) (S\$) | | 1,000.00 | | |
| + Doc/Search Fee (S\$) | | 7.49 | | |
| Nett Liability (S\$) | | 7,855.49 | | |
| Global Sum Settlement (S\$) | | 7,800.00 | | |

INSPECTION

Date of Assignment: 26/06/2018

Date Inspected: 26/06/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER | Distorted | 638.00 FL | *638.00 FL |
| 2 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 30.00 FL | *30.00 FL |
| 3 | 2 | | *REAR BUMPER SIDE HOLDER-LH & RH | Necessary | 48.20 FL | *48.20 FL |
| 4 | 1 | | *REAR BUMPER EXHAUST GARNISH | Deformed | 25.30 FL | *25.30 FL |
| 5 | 1 | | *REAR END PANEL | Dented | 300.50 FL | *300.50 FL |
| 6 | 1 | | *REAR END PANEL TOP GARNISH | Deformed | 78.60 FL | *78.60 FL |
| 7 | 2 | | *TAILLAMP -LH & RH | Cut | 452.40 FL | *452.40 FL |
| 8 | 2 | | *TAILLAMP PANEL -LH & RH | Repair | 131.40 FL | *- FL |
| 9 | 1 | | *BOOTLID | Buckled | 693.80 FL | *693.80 FL |
| 10 | 1 | | *BOOTLID LOCK | Damaged | 88.30 FL | *88.30 FL |
| 11 | 1 | | *BOOTLID WEATHERSTRIP | Cut | 100.30 FL | *100.30 FL |
| 12 | 2 | | *BOOTLID HINGE-LH & RH | Bent | 120.80 FL | *120.80 FL |
| 13 | 1 | | *BOOTLID INNER TRIM BOARD | Not Necessary | 133.70 FL | *- FL |
| 14 | 1 | | *SET BOOTLID INNER TRIM BOARD CLIPS | Necessary | 30.00 FL | *30.00 FL |
| 15 | 2 | | *BOOTLID REFLECTOR -LH & RH | Cut | 404.40 FL | *404.40 FL |
| 16 | 1 | | *HONDA LOGO | Necessary | 36.90 FL | *36.90 FL |
| 17 | 1 | | *CIVIC EMBLEM | Necessary | 34.60 FL | *34.60 FL |
| 18 | 1 | | *1.8 EMBLEM | Necessary | 23.70 FL | *23.70 FL |
| 19 | 1 | | *I-VTEC EMBLEM | Necessary | 40.50 FL | *40.50 FL |
| 20 | 2 | | *REAR FENDER INNER TRIM BOARD -LH & RH | Deformed | 484.60 FL | *484.60 FL |
| 21 | 2 | | *SET REAR FENDER INNER TRIM BOARD CLIPS | Necessary | 60.00 FL | *60.00 FL |
| 22 | 1 | | *SPARE TYRE PANEL | Distorted | 985.60 FL | *985.60 FL |
| 23 | 1 | | *SPARE TYRE PANEL TOP COVER | Deformed | 303.80 FL | *303.80 FL |
| 24 | 1 | | *SPARE TYRE LOCK SCREW | Damaged | 30.90 FL | *30.90 FL |
| 25 | 1 | | *TOOLS TRAY | Deformed | 162.50 FL | *162.50 FL |
| 26 | 1 | | *REAR EXHAUST PIPE | Repair | 514.20 FL | *- FL |
| 27 | 2 | | *REAR EXHAUST CHROME PIPE -LH & RH | Not Necessary | 194.40 FL | *- FL |
| 28 | 1 | | *REAR EXHAUST MOUNTING | Not Necessary | 36.00 FL | *- FL |
| 29 | 1 | | *CENTRE EXHAUST PIPE | Not Necessary | 637.50 FL | *- FL |
| 30 | 2 | | *REAR FENDER -LH & RH | Repair | 1,487.60 FL | *- FL |
| 31 | 1 | | *REAR WINDSCREEN MOULDING | Not Necessary | 89.30 FL | *- FL |
| 32 | 1 | | *REAR NUMBER PLATE | Not Necessary | 30.00 FS | *- FS |
| 33 | 1 | | *REAR NUMBER PLATE HOLDER | Not Necessary | 30.00 FS | *- FS |
| 34 | 1 | | *SET REVERSE SENSOR | Damaged | 280.00 FS | *220.00 FS |
| 35 | 1 | | *REAR END PANEL SEALANT | Necessary | 60.00 FS | *60.00 FS |
| 36 | 2 | | *TAILLAMP SPONGE GASKET-LH & RH | Necessary | 40.00 FS | *40.00 FS |
| 37 | 2 | | *BOOTLID REFLECTOR SPONGE GASKET -LH & RH | Necessary | 40.00 FS | *40.00 FS |
| 38 | 1 | | *SPARE TYRE PANEL INSULATION PAD | Necessary | 280.00 FS | *250.00 FS |
| 39 | 1 | | *REAR WINDSCREEN SEALANT | Not Necessary | 60.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) **9,217.80** **5,783.70**
 - List Item Discount on L Items 20.00/20.00% (S\$) **1,679.56** **1,034.74**

Total Parts (S\$) **7,538.24** **4,748.96**

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|----------|
| Labour Items | | | | |
| 1 | TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS | New | 2,000.00 | 1,400.00 |
| 2 | TO PUTTY & SPRAY UP PAINT WORKS | New | 1,800.00 | 1,200.00 |
| 3 | TO CHECK WIRING | New | 50.00 | 30.00 |
| 4 | TO REMOVE REVERSE SENSOR | New | 100.00 | 60.00 |
| 5 | TO REMOVE UPHOLSTERY AND REAR SEAT | New | 350.00 | 280.00 |
| 6 | TO REMOVE EXHAUST PIPE | New | 250.00 | 100.00 |
| 7 | TO UNDERSEAL | New | 150.00 | 100.00 |
| 8 | TO REMOVE REAR WINDSCREEN | New | 180.00 | 0.00 |
| 9 | TO TRANSFER BOOTLID FITTINGS | New | 150.00 | 80.00 |
| Gross Labour Cost (S\$) | | | 5,030.00 | 3,250.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >