

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Vivian

Quotation

DATE : 26.06.2018
 VEH NO : SJR6577A
 MODEL : Honda Civic
 D O A : 24.06.2018
 YR REF : SKB6741P

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJR6577A (Honda Civic)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	638.00 ✓
2	Rear Bumper Clips <i>m</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>m</i>	2	48.20 ✓
4	Rear Bumper Exhaust Garnish <i>Rehd</i>	1	25.30 ✓
5	Rear End Panel <i>Dented</i>	1	300.50 ✓
6	Rear End Panel Top Garnish <i>Rehd</i>	1	78.60 ✓
7	Taillamp - LH & RH <i>lt</i>	2	452.40 ✓
8	Taillamp Panel - LH & RH <i>Repair</i>	2	131.40 ✗
9	Bootlid <i>Buckled</i>	1	693.80 ✓
10	Bootlid Lock <i>Dented</i>	1	88.30 ✓
11	Bootlid Weatherstripe <i>cut</i>	1	100.30 ✓
12	Bootlid Hinge - LH & RH <i>Best</i>	2	120.80 ✓
13	Bootlid Inner Trim Board <i>nt m</i>	1	133.70 ✗
14	Bootlid Inner Trim Board Clips <i>m</i>	1 set	30.00 ✓
15	Bootlid Reflector - LH & RH <i>lt</i>	2	404.40 ✓
16	Honda Logo	1	36.90 ✓
17	Civic Emblem <i>for</i>	1	34.60 ✓
18	1.8 Emblem	1	23.70 ✓
19	i-Vtec Emblem	1	40.50 ✓
20	Rear Fender Inner Trim Board - LH & RH <i>Rehd</i>	2	484.60 ✓
21	Rear Fender Inner Trim Board Clips <i>nt m</i>	2 sets	60.00 ✓
22	Spare Tyre Panel <i>Distorted</i>	1	985.60 ✓
23	Spare Tyre Panel Top Cover <i>Rehd</i>	1	303.80 ✓
24	Spare Tyre Lock Screw <i>Dented</i>	1	30.90 ✓
25	Tools Tray <i>Rehd</i>	1	162.50 ✓
26	Rear Exhaust Pipe <i>Repair</i>	1	514.20 ✗
27	Rear Exhaust Chrome Pipe - LH & RH <i>nt m</i>	2	194.40 ✗
28	Rear Exhaust Mounting <i>nt m</i>	1	36.00 ✗

RE : ESTIMATE FOR ACCIDENT REPAIR SKB6741P (Honda Civic)

29	Centre Exhaust Pipe <i>MM</i>	5173.70	1	637.50 X
30	Rear Fender - LH & RH <i>Rys</i>	4138.86	2	1,487.60 X
31	Rear Windscreen Moulding <i>MM</i>		1	89.30 X
				8,397.80
Less 20%				(1,679.56)
				\$ 6,718.24

S/NETT ITEMS

1	Rear Number Plate	1	30.00	X
2	Rear Number Plate Holder	1	30.00	X
3	Reverse Sensor	1 set	280.00	220
4	Rear End Panel Sealant	1	60.00	✓
5	Taillamp Sponge Gasket - LH & RH	2	40.00	✓
6	Bootlid Reflector Sponge Gasket - LH & RH	2	40.00	✓
7	Spare Tyre Panel Insulation Pad	1	280.00	250
8	Rear Windscreen Sealant	1	60.00	X
Total Parts			\$	7,538.24

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 2,000.00 1400
2	To putty & spray up paint works	\$ 1,800.00 1200
3	To check wiring	\$ 50.00 30
4	To remove reverse sensor	\$ 100.00 60
5	To remove upholstery and rear seat	\$ 350.00 280
6	To remove exhaust pipe <i>3230.</i>	\$ 250.00 100
7	To underseal	\$ 150.00 100
8	To remove rear windscreen	\$ 180.00 X
9	To transfer bootlid fittings	\$ 150.00 80
Total Labour		\$ 5,030.00

Grand Total

\$ 12,568.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

NOTE: Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7998.96

L/S: 6.4K

09 Days

RE : ESTIMATE FOR ACCIDENT REPAIR SKB6741P (Honda Civic)

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.