

ASS. REC. BY:

REF: FC18011631 / THd3n2

Special Instruction

Surveyor:
CWS

Taufik
Sithara

ASSIGNMENT (Office)

From (Person)

of

FCI

Date/Time: 26/6/18 @ 2.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP FES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 4370J

Insured:

SHA 0213C

at Workshop m/s

Cycle & Carriage Industries
188 puhden loop

Tel:

9187717 / 66714336

of

Policy No:

Claim No:

D18004974MFSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

4.11pm 26/6/18

Person Contacted:

Eric

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 4370J-X
	SHA 213C-CC3 / AIG13016497 / Y9293Y DOA: 16/09/2013
	Part by Part \$4998.15 CRD: 1511.27 : 23%

(08/13/13) wef

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: Date: 18/07/2018

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKV 4370J
at Workshop m/s Cycle & Camiagc Industries
of 188 Pandan Loop

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Moring Eric

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 977K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKV 4370J Yr Regn: 2009, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz S350 c.c. 3498

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 107921 T/Radio: Insured / Std / NI / NA

Eng/No: WDD 22115624303218

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255 / 45 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 18/7/18

Survey held at G C Pandan Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt w/s

The U/C / Chassis frame / Body Structure affected due to collision.

Ref: 57251

Date / Time Action / Instruction

RECEIVED 31 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 31/8 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format : TP

Lump Sum / I.B.I.: (\$ 4998.15)

145

50

23

218



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011631/T1d3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 213C	Veh. Inspected	SKV 4370J
Policy No.		Coverage (\$)	0.00
Claim No.	D18004974MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	26/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/06/2018	Inspection Date	18/07/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	25-06-2018	Our Ref No. D18004974MFSH
Accident Date	23-06-2018	Claim Type. Third Party
Insured Vehicle	SHA0213C	Third Party Vehicle. SKV4370J
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ERIC LEE MING HUI	
Contact No.	66714336/ 91817717	Fax No. 68721272
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV4370J*RA

Wang Renqiang
Hillview Avenue
#06-22
Singapore 669630

Vehicle & Document Information
WIP No **24621**
Reg No/Reg Date **SKV4370J*RA / 28/12/2009**
Date In/Mileage **/ 0**
Chassis No **WDD2211562A303218**
Engine No **27296531359949**
Make/Model **MB/S 350 LONG SEDAN (V221)**
Colour/Trim **021 197 Obsidian Bl/ 042 211 Leather Ant**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	25/06/2018/ 11:49	EL	350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : GA3105032X // 23-6-18 TP VEH NO : SHA213C - FIRST CAP DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				✓ 480.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				1200 1680.00
A BPIRES RESPRAY FRONT BUMPER, LH/ FRONT FENDER.				960 1920.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
M LEFT CHROME TRIM	1.00	108.14	00.00	cut 108.14
M RIGHT CHROME TRIM	1.00	108.14	00.00	cut 108.14
M CENTRE CHROME TRIM	1.00	128.39	00.00	cut 128.39
M FRONT BUMPER	1.00	1739.69	00.00	cut 1739.69
M PARKING SENDER UNIT	1.00	345.06	00.00	cut 345.06

ESTIMATE

Tanfer 97495749

wp
18/7/18 e 3pm 4 days.
su@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

Nett 6,509.42
7% GST on 6509.42 455.66

Total Payable 6,965.08

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 195400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV4370J*RA

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 24621
Reg No/Reg Date SKV4370J*RA / 28/12/2009
Date In/Mileage 18/07/2018/ 107921
Chassis No WDD2211562A303248
Engine No 27296531359949
Make/Model MB/S 350 LONG SEDAN (V221)
Colour/Trim 021 197 Obsidian B1/ 042 211 Leather Ant

SKV4370J*RA

Account No	Terms	Date/Time Printed	CSE	Operator	
WF001862	Credit	31/08/2018/ 08:57	EL	350 / Eric Lee Ming Hui	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : GA3105032X // 23-6-18
TP VEN NO : SHA213C - FIRST CAP
DATE IN/DATE SURVEY: 18-7-18 // TAUFIKH - LKK
DIRECT SETTLEMENT : FIRST CAP // 10-7-18

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPIRES

RESpray FRONT BUMPER, LH/ FRONT FENDER.

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

X LEFT CHROME TRIM

1.00 108.14 00.00 108.14

X RIGHT CHROME TRIM

1.00 108.14 00.00 108.14

X CENTRE CHROME TRIM

1.00 128.39 00.00 128.39

X FRONT BUMPER

1.00 1739.69 00.00 1739.69

X PARKING SENDER UNIT

1.00 273.79 00.00 273.79

ESTIMATE

Finalization

Confirmed & accepted by

7% GST on **Nett 4,998.15**
4998.15 349.87

Authorized signatory and company stamp

Total Payable 5,348.02

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011631/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 213C	Veh. Inspected	SKV 4370J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004974MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ S350	c.c	3498	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WDD2211562A303218	Colour	BLACK	
Odometer	107921	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R18	GOODYEAR	6 mm	
L/H Front Tyre	255/45 R18	GOODYEAR	6 mm	
R/H Rear Tyre	255/45 R18	GOODYEAR	6 mm	
L/H Rear Tyre	255/45 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2018	Inspection Date	18/07/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 4370J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LEFT CHROME TRIM (SN)	CUT	108.14	108.14
1	RIGHT CHROME TRIM (SN)	NECESSARY	108.14	108.14
1	CENTRE CHROME TRIM (SN)	NECESSARY	128.39	128.39
1	FRONT BUMPER (SN)	DEFORMED	1,739.69	1,739.69
1	PARKING SENDER UNIT (SN)	CUT	345.06	273.79
			2,429.42	2,358.15
LABOUR				
	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		480.00	480.00
	RESPRAY FRONT BUMPER,LH/FRONT FENDER.		1,680.00	1,200.00
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	960.00
			4,080.00	2,640.00
GRAND TOTAL			6,509.42	4,998.15
RECOMMENDED COST OF REPAIRS				4,998.15

Report Ref No. CS/FCI18011631/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.