

Survivor

CWS

ASSIGNMENT (Office)

From (Person): Serene Ler

of FCI

Date/Time: 26/6/18 @ 3:08pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 4217C

Insured: SHD 6669R

at Workshop in/ of: Cycle & Carriage Industries

Tel: 91865112 / 67714377

188 punden loop

Policy No:

Claim No: D18004986MPSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 23/06/2018

CA / REV / REP. / REV 24 HRS (DS?)

H.O.D. Endorsement:

Date/Time: 4:14pm @ 26/6/18

Person Contacted: Alan

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 4217C -x
	SHD 6669R -x

108/11/13
ASS. REC. BY:

Ref: FCI

2778I

ASSIGNMENT

From: Date: 03/07/2018

Estimated Cost:

ON ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SLW 4217C
at Workshop m/s: cycle & Carriage Industries
of: 188 pandan loop

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Alan

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW 4217C Yr Regn: 2018 / PGB

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: MERCEDES ~~7602~~ WLC200 c.c. 1991

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 7505 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDC 2539422 F383229

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/06/18 D.O.I. 03/07/18

Survey held at CEC (PL)

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Final Sig 83,672.09 (Red 2128.02, 36%)

RECEIVED 05 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B. (\$ 3,672.09)

140

50

23

213

MOTOR SURVEY ASSIGNMENT

Date	25-06-2018	Our Ref No. D18004986MFSH
Accident Date	23-06-2018	Claim Type. Third Party
Insured Vehicle	SHD6669R	Third Party Vehicle. SLW4217C
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	DIRECT SETTLEMENT: EST. COR - \$6,206.12	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



COVER NOTE

MERCEDES-BENZ MOTOR INSURANCE PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder

Name of Policyholder : GOH MONG HOCK ✓
 Period of Insurance : 02 Feb 2018 to 03 Feb 2019
 Engine No. : 27492031326520 ✓
 Chassis No. : WDC2539422F383229 ✓



Vehicle No. : SLW 4276
 Cover Note No. : 1800010157
 Endorsement No. :
 Issued Date : 06 Feb 2018



ABOUT THE COVER

Make/Model : MERCEDES Benz GLC200 ✓
 Engine Capacity/Tonnage : 1,991.00 CC ✓
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDP") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
 GOH MONG HOCK - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS FOR CLAIMS RELATED REPAIRS

1 Eunus Service Center (For accident reporting only) Add: 330 Ubi Road 3 Singapore 408850 67412338
 2 Pandan Loop Service Center - Body Care & Repair (For accident repair & accident reporting) Add: 188 Pandan Loop Singapore 126378 67776388
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Daimler Financial Services Africa & Asia Pacific Ltd ✓

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately. We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504612236
 CYCLE & CARRIAGE - LEEHAN
 239 ALEXANDRA ROAD
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Signature

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S 13627781**
Name:

GOH MONG HOCK

Birth Date: **25 Mar 1959**
Issue Date: **21 May 2003**



FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)


Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

PASS DATE

13 Mar 1978

FOR C&C USE ONLY

NP 428A



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	27781
Vehicle Details	
Vehicle No.:	SLW4217C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC200 (R18 LED)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	27492031326520
Chassis No.:	WDC2539422F383229
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,404.00
Original Registration Date:	12 Feb 2018
First Registration Date:	12 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$51,366.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2028
PARF Rebate Amount:	\$38,524.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,002.00
COE Rebate Amount:	\$43,166.00
Total Rebate Amount:	\$81,690.00

The information contained herein is correct as at 05 Dec 2018

OK



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW4217C

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information
WIP No **24629**
Reg No/Reg Date **SLW4217C / 12/02/2018**
Date In/Mileage **/ 0**
Chassis No **WDC2539422F383229**
Engine No **27492031326520**
Make/Model **MB/MB GLC 200 SUV (X253)**
Colour/Trim **028 896 Brilliant B/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	25/06/2018/ 16:48	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M. BPNUN POLICY NO/ACC DATE :1800010157 // 23-06-2018 DRIVE IN:25-06-2018 // TP CAR NO:SHD6669R (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960 1440.00
A BPIRES RESPRAY REAR BUMPER				600 720.00
M REAR BUMPER	1.00	830.87	00.00	DE 830.87
M REAR BOTTOM PANEL	1.00	429.87	00.00	DE 429.87
M REAR BOTTOM CHROME	1.00	471.35	00.00	CPM 471.35
M CT/R BASIC MOUNTING FOR BUMPER	1.00	126.42	00.00	126.42
M CT/R PARKING SENSOR	4.00	172.07	00.00	688.28
M CT/R PARKING SENSOR SEAL	4.00	6.42	00.00	25.68
M REAR CROSS MEMBER	1.00	687.64	00.00	687.64

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirmed & accepted by

Date:

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 671 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Repair
By 9001018
3 days
03/07/18 @ 1515

Nett 5,800.11
7% GST on 5800.11 406.01
Total Payable 6,206.12

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400357W
GST Reg No. MR-0500111-X

ESTIMATE FOR SLW4217C

Finalization

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Rasul

Vehicle & Document Information

WIP No 24629
Reg No/Reg Date SLW4217C / 12/02/2018
Date In/Mileage 03/07/2018 / 7505
Chassis No S WDC2539422F383229
Engine No 27492031326520
Make/Model MB/MB GLC 200 SUV (X253)
Colour/Trim 028 896 Brilliant B / 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	30/10/2018 / 21:57	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M. BPNSUN
POLICY NO/ACC DATE : 1800010157 // 23-06-2018
DRIVE IN: 25-06-2018 // TP CAR NO: SHD6669R (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY: 03-07-2018 // LKK RASUL
BY/AUTHORIZED ON : SERENE // 26-06-2018

- A BPILAB
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT
- A BPILAB
REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT
ASSY COMPONENTS & REFINISH.
- A BPIRES
RESPRAY REAR BUMPER
- X REAR BUMPER
- X REAR BOTTOM PANEL
- X REAR BOTTOM CHROME

3 Days

ESTIMATE

0.10	380.00
	960.00
	600.00
1.00	830.87 00.00
1.00	429.87 00.00
1.00	471.35 00.00
	471.35

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

Nett	3,672.09
7% GST on	3672.09
	257.05
Total Payable	3,929.14

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011632/R1cd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6669R	Veh. Inspected	SLW 4217C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004986MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDC2539422F383229	Colour	BLUE	
Odometer	7505	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	6 mm	
L/H Front Tyre	235/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2018	Inspection Date	03/07/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 4217C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	DEFORMED	830.87	830.87
1	REAR BOTTOM PANEL (SN)	DEFORMED	429.87	429.87
1	REAR BOTTOM CHROME (SN)	CRACKED	471.35	471.35
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	126.42	-
4	CT/R PARKING SENSOR (SN)	NOT NECESSARY	688.28	-
4	CT/R PARKING SENSOR SEAL (SN)	NOT NECESSARY	25.68	-
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	687.64	-
			3,260.11	1,732.09
	<u>LABOUR</u>			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.		1,440.00	960.00
	RESPRAY REAR BUMPER.		720.00	600.00
			2,540.00	1,940.00
	GRAND TOTAL		5,800.11	3,672.09
	RECOMMENDED COST OF REPAIRS			3,672.09

Report Ref No. CS/FCI18011632/R1cd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.