



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

44c

NTUC/ ALG SGP8199R)

DOA: 21/06/2018@0750

ALG Asia Pacific Insurance Pte Ltd

25/06/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJB 6639 P - MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T

CHASSIS NO: JMYSRCY2A8U005583 (01/2008)

1 pc	Rear emblem 'LANCER'	\$ 52.00	(NETT) Net ✓
1 pc	Rear emblem 'EX'	\$ 45.00	(NETT) Net ✓
1 pc	Rear boot 'C&C' emblem	\$ 45.00	(NETT) Net ✓
1 pc	Rear boot	\$ 693.00	(NETT) Repair ✓
1 pc	Rear boot logo	\$ 49.00	(NETT) Net ✓
1 pc	Rear boot lock	\$ 77.00	(NETT) Net ✓
1 pc	Rear boot rubber	\$ 176.00	(NETT) X ✓
1 pc	Rear bumper	\$ 815.00	(NETT) DE ✓
1 pc	Rear bumper reflector RH	\$ 27.00	(NETT) X ✓
1 pc	Rear bumper reflector LH	\$ 27.00	(NETT) ? ✓
1 pc	Rear bumper reinforcement	\$ 210.00	(NETT) Net ✓
4 pcs	Rear bumper clips @ \$5	\$ 20.00	(NETT) Net ✓
1 pc	Rear bumper retainer LH	\$ 19.00	(NETT) Net ✓
1 pc	Rear end panel	\$ 506.00	(NETT) Repair ✓
1 pc	Front bumper	\$ 858.00	(NETT) DE ✓
1 pc	Front grille	\$ 367.00	(NETT) Net ✓
1 pc	Front grille logo	\$ 55.00	(NETT) Net ✓
1 pc	Front bumper lower ctr grille	\$ 87.00	(NETT) ? ✓
1 pc	Front bumper reinforcement	\$ 390.00	(NETT) ? ✓
1 pc	Front bumper top beam	\$ 84.00	(NETT) ? ✓
8 pcs	Front bumper top beam rivets @ \$5	\$ 40.00	(NETT) ? ✓
1 pc	Front bumper retainer LH	\$ 16.00	(NETT) X ✓
1 pc	Front bumper retainer RH	\$ 16.00	(NETT) X ✓
1 pc	Front headlamp lower bracket LH	\$ 16.00	(NETT) ? ✓
1 pc	Front headlamp lower bracket RH	\$ 16.00	(NETT) ? ✓
8 pcs	Front headlamp lower bracket rivets @ \$5	\$ 40.00	(NETT) ? ✓
1 pc	Front headlamp LH	\$ 792.00	(NETT) Net ✓
1 pc	Front headlamp RH	\$ 792.00	(NETT) ? ✓
1 pc	Front support panel top garnish	\$ 65.00	(NETT) X ✓



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJB 6639 P - MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T

6 pcs	Front support panel top garnish clips @ \$5	\$ 30.00	(NETT) ?
		\$ 6,425.00	
	LESS 10%	\$ 642.50	
		\$ 5,782.50	
	Front no.plate (S/NETT)	\$ 35.00	74 ✓
	Rear no.plate (S/NETT)	\$ 35.00	154 ✓
	Reverse sensor (S/NETT)	\$ 200.00	cut ✓
	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front bonnet, front fender LH, front bumper and affected areas.	\$ 500.00	300
	Putty and respray front inner panel, front bonnet, front fender LH and front bumper.	\$ 600.00	400
	Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear fender LH, rear bumper, tyre compartment and affected areas.	\$ 600.00	400 550
	Putty and respray rear inner panel, rear end panel, rear boot, rear fender LH, rear bumper and affected areas.	\$ 800.00	600
	ADD 7% GST	\$ 8,552.50	
		\$ 598.68	
		\$ 9,151.18	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

Page 2 of 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8 days
L/s
27/06/18 @ 1430
Repair after repair