



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

LKF

AXA/AIG(SDS7677D)
DOA: 17/05/2018@1140

AIG ASIA PACIFIC INSURANCE PTE LTD

26/06/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM - SKL3125K
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR
CHASSIS NO: WAUZZZ8R49A023015 (2009)

1 pc Front fender RH
1 pc Front door RH
1 pc Front door rubber (stick to door)

\$ 752.85
\$ 1,877.35
\$ 145.85
\$ 2,776.05
\$ 277.61
\$ 2,498.44

LESS 10%

Repair, putty and respray front rim RH

\$ 100.00

Remove and reinstall front door glass & fitting

\$ 60.00

Remove/reinstall/replace necessary parts: jacking, panel beating
repair and straighten front fender RH, front door RH and
RH 'A' pillar.

\$ 450.00

Putty and respray front fender RH, front door RH & RH 'A'
pillar

\$ 600.00
\$ 3,708.44
\$ 259.59
\$ 3,968.03

ADD 7% GST

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.
CHARN'S CUSTOMCRAFT

Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey
Hp 90010068
3 days
P/P
27/06/18 @ 1415
Resurvey after repair