



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

AXA/AIG(SDS7677D)

DOA: 17/05/2018@1140

AIG ASIA PACIFIC INSURANCE PTE LTD

26/06/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

CHASSIS NO: WAUZZZ8R49A023015 (2009)

1 pc	Front fender RH	\$ 752.85
1 pc	Front door RH	\$ 1,877.35
1 pc	Front door rubber (stick to door)	\$ 145.85
		\$ 2,776.05
	LESS 10%	\$ 277.61
		\$ 2,498.44
	Repair, putty and respray front rim RH	\$ 100.00
	Remove and reinstall front door glass & fitting	\$ 60.00
	Remove/reinstall/replace necessary parts: jacking, panel beating repair and straighten front fender RH, front door RH and RH 'A' pillar.	\$ 450.00
	Putty and respray front fender RH, front door RH & RH 'A' pilllar	\$ 600.00
		\$ 3,708.44
	ADD 7% GST	\$ 259.59
		\$ 3,968.03

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....