ASS REC. EY:	REP ES FO	118011639/KJ	d3 special features	un:
CWS From (Person) &		FCI FCI		26/6/18@ 2.57pm
Estimated Cost: OD TP WS / TP R	ES/OD RES/EVA/INV		Cup	orant.
To Inspect Vehicle No at Workshop m/s of	SLF & Autowor 176 Sin Ming Di	261G × House	Insured: SHB Tel. 646	
Policy No:	140 311 1110 01	Claim No:	D1800498	8 MFSH
Sum Insured		Excess:		
Make of Veh: (Client's Record)			D.O.A.	24 06 2018
	1 REV 24 HRS lup 0 26/6/18 Person Co	intacted: Yew Ke		ndorsement:
	Vinstruction (JE F5261 G-CSINC		h3n) N	10A: 11/10/2016
311	B3502T-NAIAI	G17008930/k	4 DOA	: 64 04 2017
18ho 11	Lay 8245d	enail & Con	, frme	

REF: 1-02/



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004988MFSH

Date: 27/7/2018

Our Ref: CS/FCI18011639/Ktd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLF 5261G

Please be informed that we had conducted the inspection of the abovementioned vehicle $\underline{24/7/2018}$ at the premises of M/s Autoworx House and have the following to report: -

Workshop Estimate Amount	: S\$	5,066.50
Revised Estimate Amount	: S\$	3,211.63
"Check" Items Amount	: S\$	235.65
LTA Reimbursement Value	: <u>S\$</u>	
Nett Value	: <u>S</u> \$	

Description of Damage:
The vehicle sustained damages at the

Front portion.

nearside front

Comments/ Present Status:

Damages Consistent.

Yours faithfully Kenneth Automotive Assessor



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwitting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

26-06-2018

Our Ref No. D18004988MFSH

Accident Date

24-06-2018

Claim Type. Third Party

Insured Vehicle

SHB3502T

Third Party Vehicle. SLF5261G

Survey Location

C/O 176 SIN MING DRIVE #02-01

Contact Person.

NA

Contact No.

64528211/0

Fax No. 64517420

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

AUTOWORX HOUSE

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From:

Sithara <Sithara@msfirstcapital.com.sg>

Sent:

Tuesday, 26 June 2018 3:03 PM

To:

'assignments@lkkauto.com'; SUR; Admin-D (LKKAuto)

Subject:

FW: SURVEY ASSESSMENT - D18004988MFSH/1

Attachments:

Jobsheet_D18004988MFSH_TPD1.pdf

Dear Sirs,

Please note our insured reported as below - he mentioned there was no fresh damage to third party's vehicle.

As such, kindly verify on our driver's allegations as well as the consistency of damages to accident.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Taxi SHB35025 bumper.

Thanks and regards.

Sithara G S Motor Claims



Change of email address Sithara@msfirstcapital.com.sq

MS First Capital Insurance Ltd | 36 Robinson Rd #16-01 City House Singapore 068877 | TEL: 6507 3848 | Fax No.: 6507 3849 | Company Regn. No. 195000106C

A Member of MS&AD INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender

From: CWS Motor Claims

Sent: Tuesday, June 26, 2018 2:57 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Sithara < Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18004988MFSH/1

Dear Sir/Mdm.

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Friday, 27 July 2018 10:00 AM

To:

Admin-D (LKKAuto); 'Claim Workflow System'; assignments

Cc:

SITHARA@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18004988MFSH/1

Attachments:

PRELI ADVISED SLF 5261G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLF 5261G

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 26 June 2018 4:24 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18004988MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 26 June 2018 2:57 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18004988MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721 TEL: 64520715 FAX: 64529250

ESTIMATE

Thames Limousine Services LLP c/o 46 Lentor Plain Singapore 786548

Not Notharks

11 Ly 82850h

Rewny Afre Paint

Gelay,

Date: 10/7/2016

QUANTITY	PARTICULARS		AMOUNT (\$)	
	RE: TOYOTA WISH / SLF 5261 (3		
	A	2		
1 pc	front bonnet 7 P3-13			B 867.90
1 pc	front bonnet emblem			1 67 10
1 pc	front bumper			Del Bre 675.40
1 pc	front bumper reinforcement			n 577.00
1 pc	front bumper top grille 361.89			577.00 467.30
1 pc	front bumper sponge			Ju 314.20
6 pc	front bumper grille clip		@ 3.70	ne 22.20
2 pc	front head lamp	ols Ga	@ 975.30	1,950.60
			sub total	4,942.00
			less 25%	1,235.50
			sub total	3,706.50
1 pc	front number plate		.nett	25.00
1 pc	front number plate casing	100	nett	35.00 35.00
	To remove and replace the parts and realign the necessary affected		e, panel beat	600.00
	and rounger the necessary amount	a al oao.		000.00
	To check wiring system.			40.00
	To apply putty & spray painting or	affected areas		650.00
	To apply party & spray painting of	anected areas.		030.00
		LKK Auto Consultan the Repairer of the f	ts hence notify	1
		» To resurvey before/afte	spray painting	5,066.50
		 To display damaged pa 	rt(s) during resurvey	11
		 Parts prices are subject Third party survey is on 	to confirmation a "Without Prejudice" basis	
		 No illegal modification(s) is allowed	
		 Supplementary item(s) is subject to final approx 	must be resurveyed and al from Insurance Company	
		Acknowledged by Repaire	r	
0	Pg 1 o	Signature:		

Pg 1 of 1^{Date}



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	I OMITIME INCOM	RANCE LTD	Ref : CS/FCI1801163	39/Ktd3n2
A. (A. (1) C. (1)	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 24-10-2018 Code: FCI2	
1.		Policy Particula	ars :- THIRD PARTY CLAI	M
	Insured Veh.	SHB 3502T	Veh. Inspected	SLF 5261G
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18004988MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	26/06/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	TOYOTA WISH (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDGG20W40J005030	Colour	METALLIC SILVER
	Odometer	164318	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
١.		Descr	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	24/06/2018	Inspection Date	24/07/2018
	Survey held at	AUTOWORX HOUSE		
		176 SIN MING DRIVE #02-01 SINGAPORE 575721		
5a.			Remarks	
	B)THE INSPECTION	ISISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BAS	
5b.	New York Control of the Control of t		ate Days of Repair	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5261G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BENT	867.90	793.13
1	FRONT BONNET EMBLEM	NECESSARY	67.40	67.40
1	FRONT BUMPER	DENTED / BUCKLED	675.40	675.40
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	577.00	
1	FRONT BUMPER TOP GRILLE	CUT	467.30	361.84
1	FRONT BUMPER SPONGE	SERVICEABLE	314.20	1.54
6	FRONT BUMPER GRILLE CLIP @\$3.70	NECESSARY	22.20	22.20
2	FRONT HEAD LAMP @\$975.30	O/S CUT	1,950.60	975.30
	LESS 25% DISCOUNT		-1,235.50	-723.82
	125000000		3,706.50	2,171.45
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) }	BENT	35.00	45.00
1	FRONT NUMBER PLATE CASING (SN) }	BENT	35.00	-
			70.00	45.00
	LABOUR			
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT		600.00	400.00
	TO CHECK WIRING SYSTEM.		40.00	20.00
	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		650.00	440.00
			1,290.00	860.00
	GRAND TOTAL		5,066.50	3,076.45

RECOMMENDED COST OF LUMP SUM REPAIRS	2,450.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18011639/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.