

ASS. REC. BY:

REF: CS/FCI18011646/Urds¹² Special Instruction:

Surveyor: CWS ASSIGNMENT (Office)

From (Person): Eurene jaw of PEI Date/Time: 26/6/18 @ 2.21pm

Estimated Cos: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GV 2144G Insured: SHB 2959R

at Workshop m/s Kai Liang Motor Tel: 6747 4189

of Blk 1 Kaki Bukit Ave 6 # 01-101

Policy No: _____ Claim No: D18004948MP8H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/06/2018

(Client's Record) up? 27/6/2018 @ 11am

CA / REV / REP. / REV 24 HRS _____ H.O.D. Endorsement: _____

Date/Time: 3.37pm @ 26/6/18 Person Contacted: Mr. Tan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GV 2144G - CCG / AIG / 3016118 / Ahb3w2 DOA: 22/8/2013
	SHB 2959R - NS / INCL / 700820 / H / vb2 DOA: 22/09/2017

ASSIGNMENT

From: Date: 27/6/2018

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GV 2144G

at Workshop m/s Kai Liang Motor service

of Blk 1, Kaki Bukit Ave 6 #01-101

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 11 am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 20k.

IDAC Accident Rpt: Consistent? : Yes or No

CA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up \$3355

Date: Person Contacted: Vehicle: IN / OUT

Veh No: GV2144G Yr Regn: 1 1 02

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or M/

Make: Toyota D/ue C.C 2986

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 465827 T/Radio: Insured / Std / NI / NA

Eng/No: LY2120006577

C/No: 2

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185-1214

R: 155-1212

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Steel radial

Front R/Bal. 6 mm

Rear R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 6/6 mm

D.O.A. 20/6/18 D.O.I. 27/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27/6/18 12:45 3.15 barli.

anely estimate

20/7/18 confirmed L/S \$1650 with Kai Liang

Red: \$308632, 70%.

RECEIVED 20 JUL 2018

MV: \$20k, LTA: \$12,451.00, NV: 7549.00

Date/Time, File Pass to? : Preli. Report

1) fypat : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

S + RS, SI

Photos

Others

Report Format: TP
Lump Sum / LBI: (\$ 1650.00)

Survey Fee:	140
Transportation:	50
	50
	45
TOTAL	285



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004948MFSH

Our Ref: CS/FCI18011646/Urd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GV 2144G .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.06.2018 at the premises of M/s KAI LIANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,536.32</u> .
Revised Estimate Amount	: S\$ <u>2,066.09</u> .
“Check” Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u> </u> .
LTA Reimbursement Value	: S\$ <u> </u> .
Nett Value	: S\$ <u> </u> .

Description of Damage:

The vehicle sustained damages
at n/s front portion.



Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-06-2018	Our Ref No. D18004948MFSH
Accident Date	20-06-2018	Claim Type. Third Party
Insured Vehicle	SHB2959R	Third Party Vehicle. GV2144G
Survey Location	AUTOBAY@KAKI BUKIT BLK 1 KAKI BUKIT AVE 6 #01-101	
Contact Person.	ANNIE/MR TAN	
Contact No.	67474189/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAI LIANG MOTOR SERVICE	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8335G
Vehicle Details	
Vehicle No.:	GV2144G
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Blue
Manufacturing Year:	2001
Engine No.:	5L5107669
Chassis No.:	LY2120006577
Maximum Power Output:	-
Open Market Value:	\$25,582.00
Original Registration Date:	26 Jan 2002
First Registration Date:	26 Jan 2002
Transfer Count:	1
Actual ARF Paid:	\$1,280.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,466.00
COE Rebate Amount:	\$12,451.00
Total Rebate Amount:	\$12,451.00

The information contained herein is correct as at 27 Jun 2018

OK

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

SGCARMART CONNECT
BRIDGING BUYERS & SELLERS

Toyota Dyna Price Range Depreciation > 10 year(s) Vehicle Type Submit Advanced Search

Home » Used Cars » Direct Owners » Toyota Dyna 150 (COE till 01/2021)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle

PAN PACIFIC
SERVICE YOU DESERVE.
PEOPLE YOU TRUST.

MORE THAN 1,000 FLEET UNIT
Daily, Weekly, Monthly & Yearly Fleet Available.

Trim your debts and enjoy
interest rate
from as low
as 4.70% p.a.
(EIR: 8.48% p.a.)
Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply.

Maybank
Compare

Toyota Dyna 150 (COE till 01/2021)

Overview Financial Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist Add to Compare Add a Note Report Error

Car Details

Price	\$19,800
Depreciation	\$7,620 /yr
Reg Date	17-Feb-2006 (2yrs 7mths 4days COE left)
Lifespan	16-Feb-2026
Manufactured	2005
Mileage	146,368 km (11.8k /yr)
Transmission	Manual
Engine Cap	2,986 cc
Curb Weight	1,740 kg
Fuel type	Diesel
Features	Very Spacious Interior, And Very Smooth And Responsive Engine.
Accessories	CD Changer.
Description	Well Maintained! Very Low Mileage! 4 New Tyres, CD Changer, Half Canopy, Passed Inspection, New Road Tax. Call Now!
COE	\$22,583
OMV	\$23,681
ARF	\$1,185
Dereg Value	\$11,743 as of today (change)
No. of Owners	1
Type of Veh	Truck
Category	COE Car, Direct Owner Sale
Availability	Available


Add to Shortlist Add to Compare Add a Note

Posted on: 24-Jun-2018 | Last Updated on: 24-Jun-2018
Tags: Toyota Dyna, 2006 Toyota Dyna, Toyota, Dyna, Used Toyota

Upfront Payment » more Financial info

Transfer Fee	\$25
Down Payment	\$1,980 (change) Maximum 90% Loan
1st Instalment	\$642
Total Upfront Payment	\$2,647 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

Seller Information

Contact Person(s) Kim
Contact No. 97878795
Enquiry Contact Seller

USEFUL FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » M01

Instructions on how to complete a seller to end-consumer deal
Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services

STA VEHICLE INSPECTION
Afraid of lemons? Request to have this car evaluated professionally.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

KAI LIANG MOTOR SERVICE

1 Kaki Bukit Ave 6
 #01-101 Autobay
 SINGAPORE 417883
 TEL:67474189

no of Allocated
 2/ku
 tel:62563561
 27/6/18
 1/5 #1650/2
 Hdy.

VEHICLE NO:GV 2144G

QTY	PARTICULAR	AMOUNT
1 PCS	FRONT DOOR N/S	R \$1,248.10 X
2 PCS	FRONT DOOR HINGES @\$85.50	rn \$171.00 X
1 PCS	CORNER PANEL N/S	20/2el \$376.50 —
1 PCS	FRONT SIGNAL LAMP N/S	cm \$166.20 —
1 PCS	FRONT SIDE LAMP N/S	320 \$189.62 —
1 PCS	FRONT STEP GARNISH N/S	cm \$266.20 —
1 PCS	FRONT BUMPER	3rd \$481.60 —
1 PCS	FRONT DOOR 'ROC' STICKER N/S	rn \$48.00 —
1 PCS	FRONT DOOR PILLAR OUTER N/S	R \$699.10 X
		\$3,646.32

25%

LABOUR CHARGES:

- TO CHECK WIRING
- TO TRANSFER FRONT DOOR COMPONENTS
- TO SPRAY RUST PROOFING
- LABOUR FOR PANEL BEATING & REPLACING PARTS
- TO PUTTY & SPRAY PAINTING

\$50.00 20
 rn \$80.00 X
 \$80.00 30
 \$680.00 420
 \$1,000.00 450

TOTAL \$5,536.32

2066.09

...sultants hence notify

If Repairer of the following:

- 1. resurvey before anti-rust spray painting
- 1. display damaged part(s) during resurvey
- Prices prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011646/Urd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2959R	Veh. Inspected	GV 2144G
Policy No.		Coverage (\$)	0.00
Claim No.	D18004948MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	26/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	LY2120006577	Colour	BLUE
Odometer	465827	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14	STEEL RADIAL	6 mm
L/H Front Tyre	185 R14	STEEL RADIAL	6 mm
R/H Rear Tyre	155 R12 (D)	STEEL RADIAL	6/6 mm
L/H Rear Tyre	155 R12 (D)	STEEL RADIAL	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/06/2018	Inspection Date	27/06/2018
Survey held at	KAI LIANG MOTOR SERVICE BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 2144G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	1,248.10	-
2	FRONT DOOR HINGES @\$85.50	NOT NECESSARY	171.00	-
1	CORNER PANEL N/S	DENTED / BENT	376.50	376.50
1	FRONT SIGNAL LAMP N/S	CRACKED	166.20	166.20
1	FRONT SIDE LAMP N/S	BROKEN	189.62	189.62
1	FRONT STEO GARNISH N/S	CRACKED	266.20	266.20
1	FRONT BUMPER	BENT	481.60	481.60
1	FRONT DOOR "ROC" STICKER N/S	NECESSARY	48.00	48.00
1	FRONT DOOR PILLAR OUTER N/S	TO REPAIR SEE LABOUR	699.10	-
	LESS 25% DISCOUNT		-	-382.03
			3,646.32	1,146.09
LABOUR				
	TO CHECK WIRING.		50.00	20.00
	TO TRANSFER FRONT DOOR COMPONENTS.	NOT NECESSARY	80.00	-
	TO SPRAY RUST PROOFING.		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS INCLUSIVE OF THE REPAIR OF FRONT DOOR N/S AND FRONT DOOR PILLAR OUTER N/S.		680.00	420.00
	TO PUTTY & SPRAY PAINTING.		1,000.00	450.00
			1,890.00	920.00
GRAND TOTAL			5,536.32	2,066.09
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/FC118011646/Urd3n2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,451.00=NETT VALUE: \$7,549.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.