

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BUKIT
Singapore 415875

TP QBE
Ashes.

26th JUNE 2018

Accident date: 23rd JUNE 2018

Estimated repair cost for vehicle no: SJQ4899P HONDA CIVIC 1.8L A '09

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -RH <i>Smashed</i>		\$921.40 ✓
2	1	Front head lamp lower bracket <i>Best</i>		\$60.50 ✓
3	1	Front bumper <i>Delco</i>		\$638.00 ✓
4	1	front number plate <i>new</i>		\$50.00 ✗
5	2	Front bumper side bracket <i>RH new</i>	\$22.80	\$45.60 <i>22.80</i>
6	1	Front bumper clips <i>new</i>		\$30.00 ✓
7	1	Front bumper fog lamp -RH <i>2 new</i>		\$250.40 ✗
8	1	Front bumper fog lamp cover <i>new</i>		\$88.20 ✗
9	1	Front bumper lower rubber <i>new</i>		\$115.40 ✗
10	1	Front bumper reinforcement <i>new</i>		\$258.20 ✗
11	1	Front grille <i>new</i>		\$205.20 ✗
12	1	Front grille chome <i>new</i>		\$180.30 ✗
13	1	Front grille emble logo <i>new</i>		\$45.10 ✗
14	1	Front support panel <i>Repis</i>		\$485.30 ✗
15	1	Front support panel side bracket <i>new</i>		\$164.50 ✗
16	1	Front fender-RH <i>Distorted</i>		\$535.00 ✓
17	1	Front fender cowling <i>torn</i>		\$105.00 ✓
18	10	Front fender cowling clips <i>new</i>	\$5.00	\$50.00 <i>30</i>
19	1	Front fender inner panel-RH <i>Repis</i>		\$292.70 ✗
20	1	Front R/H fender side glass <i>new</i>		\$256.00 ✗
21	1	Front R/H fender side glass moulding <i>new</i>		\$79.00 ✓
22	1	front R/H Tyre <i>Abel New</i>		\$350.00 ✗
23	1	Front R/H Rim <i>at</i>		\$500.00 ✓
24	1	Front R/H Shock Absorber <i>Best</i>		\$196.50 ✓

25	1	Front R/H lower arm <i>Best</i>	\$354.70 ✓
26	1	Front R/H knuckle arm <i>Best</i>	\$314.30 ✓
27	1	Front R/H knuckle arm bearing <i>new</i>	\$235.80 ✓

4022

Subtotal :- \$6,807.10

3217.60

Labour charges

To Remove & refix cushion	\$120.00 X
To Remove & refix front RH undercarriage	\$280.00 220
To Remove & refix R/h fender side glass	\$120.00 40
Gum	\$50.00 20
To check wheel alignment computer	\$120.00 80 1250
Tuff kote	\$120.00 X
To Check Wiring System	\$60.00 30
Towing charges	\$100.00 60
Panel beating	\$800.00 400
Spray painting	\$800.00 400

Subtotal :- \$2,570.00

Total:- \$9,377.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4467.60
h/sr 3350
05 Days.