

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 02 Jul 2018

Preliminary Advice

Insured Vehicle No	: SJT1047K		
TP Vehicle No	: SLM2738G	Accident Date	: 23/06/2018
Make	: LEXUS ES250	Assignment Date	: 26/06/2018
Date of Inspection	: 28/06/2018	Est. Duration of Repair	: 6 or 8 days
Inspection At	: Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,422.40
Revised Amount	:S\$	7,060.20-10,092.20
Check Items (Estimated)	:S\$	4,764.20
Total	:S\$	11,824.40-14,856.40

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.