

INS. CASE OWNER:

KIAN HONG

CC 3, 16 180 11663, A 21/3/18

LKK:

IDAC:

Surveyor:

APRUAN

DOI:

ASSIGNMENT

20/6/18

Date / Time:

26/6/18

Registered in Merimen:

26/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

0JA 9933A

Name of Insured:

Goh Nguey Chan

Insured Tel No.:

HP: 81002233

Excess Sec II : \$5

D.O.A: 26/6/18

Is driver the owner?

(YES) NO

Nature of Accident:

Claim No.:

930079275G

Policy No.:

77000 649X1

Make / Model:

M-Benz C43

Place of Accident:

Alexandria Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLS 4422Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

28/6
11/18

SLS 4422Y - X

0JA 9933A - 0A/10/180079275G/18 : 0A 26/6/18

OI coming out from slip read.

13-12-18

TRANSFER: THIN2 TO JOY
PENDING FINALISATION

FOR MANDATE.

- MANDATE APPROVED

17/07/19

- COMPLETED AMOUNT PAID TO LOD.
- AW 100% IN ORDER.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

77114
18/2

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 14,500.00 (12 days) Reduction: 25 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

S\$ 15,301.00 (100 (Assessed) BOLA S/N No.: 11 (C))

If NO or B 28, Ass. Lia:

Repair Cost:

GST S\$ 15,301.00

Loss of Rental (LOR):

S\$ - (days)

Loss of Use (LOU):

S\$ 900 (360 x 15 days)

Loss of Income (LOI):

S\$ - (S x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/JTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

Legal Cost

S\$ -

Total:

S\$ 16,203

Global Sum S\$: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 15,303.00

Name 1:

PREMIUM AUTOMOBILES PTE LTD

Payee 2: (Strike if N.A.)

S\$ 900.00

Name 2:

CHAN YUEN HUN

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 320.00

REF: ALH

1663 (Anas) - (V)

ASSIGNMENT

From: Date 28062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SLS 4422Y

at Workshop mile

of Premium 59 ubi Rd 1

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

105K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 8/8

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Van No SLS4422Y Yr Regn 2017 Sept

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan CC 999.

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading:

25587

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228V751013081

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A

D.O.I

28/06/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP ALH.

\$14,300 - ✓✓

CRAB: \$7,746.44 (35%)

Date/Time: File Pass to:

☐

Preli. Report

Date/Time: File Return to:

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. S + RS

1. Photos

1. Other

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0730/2018/PH
Date	:	26-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SJA 9933 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr.Chan Yuen Mun
Address	:	Blk 23 Yishun St 51 #04-07 Singapore 768086
Telephone	:	HP +6581271358
Type of Claim	:	Third Party Claim
Policy No.	:	170005522
Vehicle No	:	SLS 4422 Y
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Sep-17
Engine No	:	CHZ 528845
Chassis No	:	WAUZZZ8V9J1013081
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Jun-18
Place of Accident	:	Intersection between commonwealth ave & Alexandra road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 4422 Y .

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00 ✓
2	To renew lhs 1/4 glss and rear windscreen to facillitate fender renewal.	S/N \$ 600.00 ✓
3	To dislodge and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.	S/N \$ 1,400.00 ✓
4	To removeand reinstall rear seat,back rest,hat tray,ABC pillar trims,luggage compartmenttrims,seat belts.Dislodge roof liner and disengagecurtain airbag etc.	S/N \$ 1,400.00 ✓
5	To dismantle rear bumper and rear lid.Cut out and weld lhs rear fender,and connecting plates.Renew rear bumper.Re-organise rear crash management components.Reinstall all parts removed.	S/N \$ 5,400.00 3000

✓ ✓
6 To respray rear bumper, lhs rear fender, connecting plates, lhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works. S ~~4,300.00~~ 2200.

7 To carry out diagnostic check. S/N S 192.00 ✓

TOTAL LABOUR CHARGES

S 13,572.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLS 4422 Y

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	BUMPER COVER <i>Deln d</i>	\$ 1,697.00	✓ 1,357.60
2	FIXING PARTS FOR BUMPER <i>new</i>	\$ 166.00	+
3	SPOILER <i>Not nec</i>	\$ 206.00	+
4	GUIDE SECTION <i>Not nec</i>	2 \$ 28.00	✗
5	LOCKING MECHANISM <i>Not Nec</i>	2 \$ 50.00	✗
6	WHEEL HOUSING LINER - LH <i>Not nec</i>	\$ 32.00	✗
7	GUIDE SECTION - LH <i>Engd.</i>	\$ 57.00	✓ 45.04
8	REAR LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$ 70.00	✗
9	SENSOR -INNER/OUTER <i>Not nec</i>	\$ 211.00	✗
10	SECTIONAL PART - SIDE PANEL - LH <i>Buckleed</i>	\$ 2,006.00	✓ 1,604.80
11	CONNECTING PLATE - LH REAR <i>Repair</i>	\$ 85.00	✗
12	BOTTOM PLATE - LH <i>Repair</i>	\$ 174.00	✗
14	SIDE WINDOW - LH <i>Free</i>	\$ 502.00	✓ 401.20
15	REAR WINDOW	\$ 704.00	✓ 563.20
16	PRIMER <i>xx</i>	2 \$ 37.00	✓ 29.12
17	LED TAIL LIGHT - LH <i>Not Nec</i>	\$ 730.00	✗
18	WHEEL HOUSING LINER - LH <i>Not nec</i>	\$ 215.00	✗
19	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not nec</i>	\$ 77.00	✗
20	1/4 GLASS SEALANT <i>Nec</i>	\$ 100.00	✓
SUB-TOTAL SPARE PARTS		\$ 7,147.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

10pp

*Please take
photo
after
removal
of bumper.*

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0730/2018/PH
Date : 26-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SJA 9933 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

12 days - exclude 1 PH & 2 Sundays

JD - 24 Sep 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Chan Yuen Mun
Address : Blk 23 Yishun St 51
#04-07
Singapore 768086
Telephone : HP +6581271358
Type of Claim : Third Party Claim
Policy No. : 170005522
Vehicle No : **SLS 4422 Y**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ 528845
Chassis No : WAUZZZ8V9J1013081
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jun-18
Place of Accident : Intersection between commonwealth ave & Alexandra road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 4422 Y.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid.Check function.	S/N	\$	280.00	\$ 280.00 ✓
2	To renew lhs 1/4 glss and rear windscreen to facillitate fender renewal.	S/N	\$	600.00	\$ 600.00 ✓
3	To dislodge and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.	S/N	\$	1,400.00	\$ 1,400.00 ✓
4	To removeand reinstall rear seat,back rest,hat tray,ABC pillar trims,luggage compartmenttrims,seat belts.Dislodge roof liner and disengagecurtain airbag etc.	S/N	\$	1,400.00	\$ 1,400.00 ✓
5	To dismantle rear bumper and rear lid.Cut out and weld lhs rear fender,and connecting plates.Renew rear bumper.Re-organise rear crash management components.Reinstall all parts removed.	S/N	\$	5,400.00	\$ 3,000.00 ✓

6	To respray rear bumper,lhs rear fender,connecting plates,lhs sill panel,door entrance,drain panel,roof channel and end panelling.To carry out stone chip treatment and joint sealer works.	\$	4,300.00	\$	2,200.00
---	--	----	----------	----	----------

7	To carry out diagnostic check.	S/N	\$	192.00	\$	192.00
---	--------------------------------	-----	----	--------	----	--------

TOTAL LABOUR CHARGES

\$	13,572.00	\$	9,072.00
----	-----------	----	----------

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLS 4422 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER	\$ 1,697.00	\$ 1,357.60 ✓
2	FIXING PARTS FOR BUMPER	\$ 166.00	
3	SPOILER	\$ 206.00	
4	GUIDE SECTION	2 \$ 28.00	
5	LOCKING MECHANISM	2 \$ 50.00	
6	WHEEL HOUSING LINER - LH	\$ 32.00	
7	GUIDE SECTION - LH	\$ 57.00	\$ 45.04 ✓
8	REAR LIGHT REFLECTOR - LH/RH	2 \$ 70.00	
9	SENSOR -INNER/OUTER	\$ 211.00	
10	SECTIONAL PART - SIDE PANEL - LH	\$ 2,006.00	\$ 1,604.80 ✓
11	CONNECTING PLATE - LH REAR	\$ 85.00	
12	BOTTOM PLATE - LH	\$ 174.00	
14	SIDE WINDOW - LH	\$ 502.00	\$ 401.20 ✓
15	REAR WINDOW	\$ 704.00	\$ 563.20 ✓
16	PRIMER	2 \$ 37.00	\$ 29.12 ✓
17	LED TAIL LIGHT - LH	\$ 730.00	
18	WHEEL HOUSING LINER - LH	\$ 215.00	
19	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 77.00	
20	1/4 GLASS SEALANT	\$ 100.00	\$ 100.00 ✓
SUB-TOTAL SPARE PARTS		\$ 7,147.00	\$ 4,100.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0730/2018/PH 6-Aug-18 Jeffery Tan 1 SLS 4422 Y Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Vent trim <i>2xhd</i>	\$ 60.00	\$ 47.44
2	Metal filler <i>new</i>	\$ 280.00	\$ 280.00
	S/N		
	TOTAL	\$ 340.00	\$ 327.44

For Premium Automobiles Pte Ltd

Adrian Ling
S.L.S.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

515 44227

Material List for Accident Vehicle Regn No. SDA 8002 P

S/N	Parts Description	Damage Pa	
		S/NETT	
21	RR WINDSCREEN SEALANT	\$	200.00 ✓
22	ARCYLIC SEALANT	\$	180.00 ✓
23	CAVITY WAX	\$	140.00 ✓
24	STONE CHIP TREATMENT	\$	180.00 ✓
25	SUNDRIES	\$	300.00 ✓ 99.50
TOTAL SPARE PARTS		:	\$ 8,147.00
TOTAL LABOUR CHARGES		:	\$ 13,572.00
GRAND TOTAL		:	\$ 21,719.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 28/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 12 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

(A)

Joy Irene (LKKAUTO)

From: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Sent: Thursday, 13 June 2019 3:42 PM
To: Joy Irene (LKKAUTO)
Cc: Admin A
Subject: RE: 9326679227SG / PREMIUM AUTOMOBILES / SJA 9933A AND SLS 4422Y ON 22.06.2018

LKK ref: CC3/AIG18011663/AJA3Q2

Dear Joy,

Appreciate if you are able enlighten / show us the damages that warrant a replacement for items below:

No.	Parts
10	Sectional Part -Side Panel-LH
13	Side Window LH
14	Rear Window-LH
21	Metal Filler
22	RR Windscreen Sealant
23	Acrylic Sealant
24	Cavity Wax
25	Stone chip treatment

Photo 11-20.

Please see photo 11-20 which illustrate the buckled Sectional Part (Rear Fender). Also photo 21-24 depict the actual sectioning of the rear fender.

As a consequence of cutting the fender, the rear and side window glasses has to be removed and ~~one~~ ~~the~~ cannot be reused.

Metal filler, acrylic sealant, cavity wax and stone chip treatment are necessary items or treatment required when the rear fender is being replaced.

Best regards,
Chan Kian Meng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1678
KianMeng.Chan1@aig.com | www.aig.sg

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Saturday, June 01, 2019 3:06 PM
To: Chan, Kian-Meng
Cc: Admin A
Subject: [EXTERNAL] RE: 9326679227SG / PREMIUM AUTOMOBILES / SJA 9933A AND SLS 4422Y ON 22.06.2018

Hope that the above clarifies matters.

This message is from an external sender; be cautious with links and attachments.

Hi Kian Meng,

We would like to follow-up on your approval in Merimen.

Thank you.

Best Regards,
Joy Irene | Case Handler

Print Received Message

This mail is associated with :

***SLS4422Y (9326679227SG)**
[SJA9933A]
TP
CHAN YUEN MUN
Jun 22 2018 6:00PM
[GOH NGUANG CHIAN]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 10/07/2019 08:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16203.00) - SLS4422Y - Claim Handler: Chan, Kian-Meng

Approved:16203.00:Kindly settle at best.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S85811781



Name

CHAN YUEN MUN



Race

CHINESE

Date of birth

17-12-1985

Country/Place of birth

MALAYSIA

Sex

M

S85811781

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S85811781

NAME

CHAN YUEN MUN

Birth Date: 17 Dec 1985

Issue Date: 06 May 2013



S85811781



NRIC No: S85811781



Date of issue

23-11-2017

BLK 23 YISHUN STREET 51 #04-07
SINGAPORE 788086

NRIC No: S85811781

Date: 05/06/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of the driver; and other motor vehicles $\leq 2500\text{kg}$ 06 May 2013



NP 425A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1700055222

Period of Insurance : 22 Sep 2017 to 21 Sep 2018

Issued Date : 25 Sep 2017

ABOUT THE POLICYHOLDER

Name of Policyholder : CHAN YUEN MUN
 Address : 52 STRATHMORE AVENUE
 13-237
 SINGAPORE 141052
 Occupation/Nature of Business : Manager/Director/Management

ABOUT THE VEHICLE

Registration No. : SLS4422Y Engine Capacity/Tonnage : 999.00 CC
 Chassis No. : WAUZZZ8V9J1013081 Engine No. : CHZ528845
 Seating Capacity : 5 First Year of Registration : 2017 Body Type : Sedan
 Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Hire Purchase Company/Employer's Loan : United Overseas Bank Limited

ABOUT THE COVER

Sum Insured : Market Value Off Peak Car : No
 Driver Restriction : NA Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIGRE") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God: Strike, Riots and Civil Commotions: PA to Authorized Driver / Unnamed Passengers: \$10000, Dealer + AIG Authorized Workshops: PA Insured: \$100000, Future and Accessories (Cosmetics): \$5000, Solar Film: \$1150, New For Old (36 months), Loss of Use: In-Car Camera Excess Waiver, Glass Roof/Moon Roof/Sun Roof/ Panoramic Glass Roof

EXCESS

Section 1
 Fire - \$0, Own Damage - \$600, Theft - \$0, Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver
 CHAN YUEN MUN - \$600 (Own Damage)

PREMIUM

Premium : \$ 2,730.71
 GST (7%) : \$ 191.15

Total : \$ 2,921.86

Your Premium includes the following discount(s)

No Claim Discount - 0%

BREAKDOWN OF PAYMENT

Vehicle No: SLS4422Y

Accident on 22/6/2018 at Junction Commonwealth Ave & Alexandra road

Involving vehicle/s SJA9933A

1) Repair cost \$ 15,301.00

Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00

Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or
Rental Car \$ 900.00

Payable to: Chan Yuen Mun

4) Medical fees \$ _____

Payable to: _____

5) Others \$ _____

Payable to: _____

Premium Automobiles

Joy

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18011663/ua3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/0730/2018/MAS

30 Apr 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLS 4422 Y, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLS 4422 Y**, claimant, **Mr. Chan Yuen Mun**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013706 – S\$15,301.00
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$900.00 (S\$60.00 x 12 working days + 2 Sunday + 1 PH)
6. GIA Search Fee – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 4422 Y

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

total pages



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18011663/ub3

18 JULY 2018

GOH M GUANG CHIAN
116 KIM SENG ROAD
#09-05
SINGAPORE 239434

Dear Sir/Madam,

ACCIDENT INVOLVING SJA 9933A & SLS 4422Y ON 22/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

As spoken, based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 5 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Chan Yuen Mun (the third party claimant) of Blk 23 Yishun St 51
#04-07, Singapore 768086 (address), owner of SLS4422Y (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLS4422Y that was damaged pursuant to the accident which occurred on 22/6/2018
(date) along Junction Commonwealth Ave & Alexandra road (location) involving vehicle no/s
SJA9933A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 18 (day) of AUG (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$15,301.00 (Repair Cost), S\$900.00 (Loss of ~~rental~~/use), S\$2.00 (Disbursement), for vehicle no. SLS4422Y that was damaged pursuant to the accident which occurred on 22/6/2018 (date) along Junction Commonwealth Ave & Alexandra road (location) involving vehicle no/s SJA9933A. This is pursuant to the inspection conducted on 28/6/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chan Yuen Mun ("the third party claimant") of vehicle no. SLS4422Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLS4422Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17 (day) of July (month) 2019 (year)


LKK
LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2223
Main Telefax: 6471 2723

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2223
Telefax: 6475 1021

Ubi Service Centre
35 Ubi Road 1
Singapore 408722
Telephone: 6188 7221

Customer Service
Service Appointment
Your Breakdown Service
27501
customer.care@premiumauto.com.sg

6346 2223
6426 1235

Page: 1 11:18

INS TAX INVOICE

Company Reg. No.: 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013706 Date: 24/04/2019 Order: SLS4422Y Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS4422Y (V 35185)	Regn Date: 22/09/2017	Mileage: 45968	WIP No.: 15032
Model: A3 SEDAN 1.0 TFSI 8V/MANG	Chassis: WAUZZZ8V9J1013081	Engine: CHZ 528845	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO RENEW 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABC PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS AND SEAT BELT. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID, CUT OUT AND WELD LHS REAR FENDER AND CONNECTING	3000.00	1.00	3,000.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6838 2223
Fax: 6475 1118

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2221
Fax: 6475 1021

Ubi Service Centre
350 Ubi Avenue 1
Singapore 408599
Telephone: 6886 2122
Fax: 6886 2122

Customer Service
24-hour Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 3323
6828 1238

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013706 Date : 24/04/2019 Order : SLS4422Y Term : 30	Account: 80006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS4422Y (V 35185) Regn Date: 22/09/2017 Mileage: 45968 WIP No.: 15032
Model: A3 SEDAN 1.0 TFSI 8VWANG Chassis: WAUZZZ8V9J1013001 Engine: CHZ 528845 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	PLATES, RENEW REAR BUMPER, REORGANISE REAR CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED M:	2200.00	1.00	2,200.00
S	BODYWORK	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS SILL PANEL AND END PANNELLING, TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	800.00	1.00	800.00
S	BODYWORK	TO SUPPLY 1/4 GLASS SEALANT, REAR WINDSCREEN SEALANT, CAVITY WAX, ACRYLIC SEALANT AND STONE CHIP TREATMENT M:	280.00	1.00	280.00
X	ABV5809837	TO SUPPLY METAL FILLER SUBPART	1.00	2006.00	1,604.00
X	ABV5845297K NVB	Less 020%	1.00	501.50	401.20
X	ABV5845501E NVB	SIDE WINDOW Less 020%	1.00	704.00	563.20
		REAR WINDOW Less 020%			
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119998
Main Telephone: 6366 2223
Main Telefax: 6471 5135

Alexandra Service Centre
281 Alexandra Road
Singapore 119998
Telephone: 6366 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408719
Telephone: 6386 2223
Telefax: 6471 1023

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2223
9626 1233

INSURANCE INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 11:18

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013706
Date : 24/04/2019
Order : SLS4422Y
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLS4422Y (V 35185)

Regn Date: 22/09/2017

Mileage: 45968

WIP No.: 15032

Model: A3 SEDAN 1.0 TFSI 8VMANG

Chassis: WAUZZZ8V9J1013081

Engine: CHZ 528845

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details		Qty	Unit Price	Amount
X	ABV5807067G GRU	COVER	Less 020%	1.00	1697.00	1,357.60
X	ABV5807377A	GUIDE	Less 020%	1.00	56.30	45.04
X	ABV5807063B	ADAPTER	Less 020%	1.00	31.70	25.36
X	A6R0819465B	TRIM (SK) (A)	Less 020%	1.00	59.30	47.44
X	ABV5867767 4PK	(AIR) (GER) TRIM (13/08	Less 020%	1.00	92.80	74.24
X	AD 00920002	PRIMER (DG)	Less 020%	2.00	18.20	29.12

Parts 4,148.00
Labour 0.00
Sublet 10,152.00
Menus 0.00
Lubricant 0.00

Sub-Total 14,300.00

7% GST 1,001.00

Grand Total 15,301.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-095607

Date of Request: 23/06/2018

Your Ref No:

Online Purchase

Premium Autocare Centre
24 Benoi Sector
Singapore 629857

Dear Sir/Madam,

Enquiry Date 23/06/2018
Enquiry By Wong Khong Seng, George
TP Vehicle No. SJA9933A
Accident Date 22/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJA9933A	AIG Asia Pacific Insurance Pte. Ltd.	17/10/2017-16/10/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2018 Edit Reg		28 Jun 2018 00:00 Edit Adj Rpt	S\$14,300.00 Edit Estimates	S\$14,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: GOH NGUANG CHIAN , ID: S2702440H									
Main Claimant: CHAN YUEN MUN , ID: S85811781									
Vehicle Reg. No.: SLS4422Y		Date of Loss: 22/06/2018 18:00 - :59 [9 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9326679227SG		Policy/Cover Note No.: 1700064971 (Comprehensive) Coverage: 17/10/2017 - 16/10/2018							
Vehicle Reg. No. (Insured): SJA9933A		Policy No. (Claimant): 1700055222							
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (10/07/2019): Alert - Adj Mandate Approved (S\$16203.00) - SLS4422Y - Claim Handler: Chan, Kian...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS4422Y (9326679227SG)
[SJA9933A]
TP
CHAN YUEN MUN
Jun 22 2018 6:00PM
[GOH NGUANG CHIAN]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼	
Letters/Correspondences						1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit	
Photos/Images						3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	12/04/19 09:01	General View				Load JPG ☒	
2	12/04/19 09:01	General View				Load JPG ☒	
3	12/04/19 09:01	General View				Load JPG ☒	
4	12/04/19 09:01	General View				Load JPG ☒	
5	12/04/19 09:01	General View				Load JPG ☒	
6	12/04/19 09:01	General View				Load JPG ☒	
7	12/04/19 09:01	General View				Load JPG ☒	
8	12/04/19 09:01	General View				Load JPG ☒	
9	12/04/19 09:01	General View				Load JPG ☒	
10	12/04/19 09:01	General View				Load JPG ☒	
11	12/04/19 09:01	General View				Load JPG ☒	
12	12/04/19 09:01	General View				Load JPG ☒	
13	12/04/19 09:01	General View				Load JPG ☒	
14	12/04/19 09:01	General View				Load JPG ☒	
15	12/04/19 09:01	General View				Load JPG ☒	
16	12/04/19 09:01	General View				Load JPG ☒	
17	12/04/19 09:01	General View				Load JPG ☒	
18	12/04/19 09:01	General View				Load JPG ☒	
19	12/04/19 09:01	General View				Load JPG ☒	
20	12/04/19 09:01	General View				Load JPG ☒	
21	12/04/19 09:01	Reinspection Photo				Load JPG ☒	
22	12/04/19 09:01	Reinspection Photo				Load JPG ☒	
23	12/04/19 09:01	Reinspection Photo				Load JPG ☒	
24	12/04/19 09:01	Reinspection Photo				Load JPG ☒	
25	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
26	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
27	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
28	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
29	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
30	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
31	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
32	12/04/19 09:02	Reinspection Photo				Load JPG ☒	
33	12/04/19 09:02	Reinspection Photo				Load JPG ☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 19:12	TP ESTIMATE	Load PDF	
2	26/06/18 19:12	TP GIA REPORT	Load PDF	
3	03/07/18 13:31	TP ESTIMATE - MARKED	Load PDF	
4	03/05/19 15:17	LETTER TO OI	Load PDF	
5	29/07/19 09:25	WORKSHOP INVOICE	Load PDF	
6	29/07/19 09:25	AUTHORISATION TO ACT FORM	Load PDF	
7	29/07/19 09:25	Release Voucher	Load PDF	
8	29/07/19 09:25	GIA SEARCH	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/06/18 12:40	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJA9933A (Insd veh)	Model:	AUDI A3 999CC TFSI S
	SLS4422Y (TP veh)		TRONIC (LED) (A)
Date of Accident:	22/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	23,589.69
Final Repair Cost	:	\$	15,301.00
Loss of Use	:	\$	900.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	16,203.00

15.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 11(c) _____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 15,303.00
2)	Chan Yuen Mun	:	\$ 900.00
3)		:	\$

JOANNE LEE KHANG MIN

29 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18011663/AHA3Q2

Date: 29/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700064971

Claimant Vehicle
No : SLS4422Y

Insured Vehicle No : SJA9933A

Date of Loss: 22/06/2018

Nature of Claim:

TP

Claim No: 9326679227SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS4422Y

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A)

Engine No: CHZ528845

Reg. Date: 22/09/2017 (Man. Year: 2017)

Chassis No: WAUZZZ8V9J1013081

Colour: Blue

Odometer: 25587 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,474.44	5,228.00	3,246.44	38.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,572.00	9,072.00	4,500.00	33.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,046.44	14,300.00	7,746.44	35.14
+ GST 7.00/7.00% (S\$)	1,543.25	1,001.00	542.25	35.14
Nett Amount (S\$)	23,589.69	15,301.00	8,288.69	35.14
+ Loss of Use (15.0 x S\$60.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,203.00		

INSPECTION

Date of Assignment: 28/06/2018

Date Inspected:

28/06/2018

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

12.0 days

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Deformed	1,697.00 FS	*1,357.60 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	166.00 FS	*- FS
3	1		*SPOILER	Not Necessary	206.00 FS	*- FS
4	2		*GUIDE SECTION	Not Necessary	28.00 FS	*- FS
5	2		*LOCKING MECHANISM	Not Necessary	50.00 FS	*- FS
6	1		*WHEEL HOUSING LINER-LH	Not Necessary	32.00 FS	*- FS
7	1		*GUIDE SECTION -LH	Damaged	57.00 FS	*45.04 FS
8	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	70.00 FS	*- FS
9	1		*SENSOR- INNER/OUTER	Not Necessary	211.00 FS	*- FS
10	1		*SECTIONAL PART -SIDE PANEL-LH	Buckled	2,006.00 FS	*1,604.80 FS
11	1		*CONNECTING PLATE -LH REAR	Repair	85.00 FS	*- FS
12	1		*BOTTOM PLATE-LH	Repair	174.00 FS	*- FS
13	1		*SIDE WINDOW-LH	Necessary	502.00 FS	*401.20 FS
14	1		*REAR WINDOW	Necessary	704.00 FS	*563.20 FS
15	2		*PRIMER	Necessary	37.00 FS	*29.12 FS
16	1		*LD TAIL LIGHT-LH	Not Necessary	730.00 FS	*- FS
17	1		*WHEEL HOUSING LINER-LH	Not Necessary	215.00 FS	*- FS
18	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	77.00 FS	*- FS
19	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
20	1		*VENT TRIM	Deformed	47.44 FS	*47.44 FS
21	1		*METAL FILLER	Necessary	280.00 FS	*280.00 FS
22	1		*RR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
23	1		*ARCYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
26	1		*SUNDRIES	Necessary	300.00 FS	*99.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,474.44	5,228.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION	New	280.00	280.00
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST ,HAT TRAY ,ABC PILLAR TRIMS ,LUGGAGE COMPARTMENTTRIMS ,SEAT BELTS .DISLodge ROOF LINER AND DISENGAGECURTION AIRBAG ETC	New	1,400.00	1,400.00
5	TO DISMANTLE REAR BUMPER AND REAR LID ,CUT OUT AND WELD LHS REAR FENDER ,AND CONNECTING PLATES .RENEW REAR BUMPER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	5,400.00	3,000.00
6	TO RESPRAY REAR BUMPER ,LHS REAR FENDER ,CONNECTING PLATES ,LHS SILL PANEL ,DOOR ENTRANCE ,DRAIN PANEL,ROOF CHANNEL AND END PANELLING .TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,300.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,572.00	9,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >