

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0730/2018/PH
Date : 26-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SJA 9933 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Chan Yuen Mun
Address : Blk 23 Yishun St 51
#04-07
Singapore 768086
Telephone : HP +6581271358
Type of Claim : Third Party Claim
Policy No. : 170005522
Vehicle No : **SLS 4422 Y**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ 528845
Chassis No : WAUZZZ8V9J1013081
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jun-18
Place of Accident : Intersection between commonwealth ave & Alexandra road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 4422 Y .

| S/N | Nature of Jobs | Estimated Charges |
|-----|--|-------------------|
| 1 | To remove and transfer rear parking aid.Check function. | S/N \$ 280.00 |
| 2 | To renew lhs 1/4 glss and rear windscreen to facillitate fender renewal. | S/N \$ 600.00 |
| 3 | To dislodge and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment. | S/N \$ 1,400.00 |
| 4 | To removeand reinstall rear seat,back rest,hat tray,ABC pillar trims,luggage compartmenttrims,seat belts.Dislodge roof liner and disengagecurtain airbag etc. | S/N \$ 1,400.00 |
| 5 | To dismantle rear bumper and rear lid.Cut out and weld lhs rear fender,and connecting plates.Renew rear bumper.Re-organise rear crash management components.Reinstall all parts removed. | S/N \$ 5,400.00 |

| | | | |
|---|--|----|----------|
| 6 | To respray rear bumper,lhs rear fender,connecting plates,lhs sill panel,door entrance,drain panel,roof channel and end panelling.To carry out stone chip treatment and joint sealer works. | \$ | 4,300.00 |
|---|--|----|----------|

| | | | | |
|---|--------------------------------|-----|----|--------|
| 7 | To carry out diagnostic check. | S/N | \$ | 192.00 |
|---|--------------------------------|-----|----|--------|

TOTAL LABOUR CHARGES

| | |
|----|-----------|
| \$ | 13,572.00 |
|----|-----------|

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLS 4422 Y

| S/N | Parts Description | Damage Parts & Prices | |
|------------------------------|--|-----------------------|---------|
| | | S/NETT | REMARKS |
| 1 | BUMPER COVER | \$ 1,697.00 | |
| 2 | FIXING PARTS FOR BUMPER | \$ 166.00 | |
| 3 | SPOILER | \$ 206.00 | |
| 4 | GUIDE SECTION | 2 \$ 28.00 | |
| 5 | LOCKING MECHANISM | 2 \$ 50.00 | |
| 6 | WHEEL HOUSING LINER - LH | \$ 32.00 | |
| 7 | GUIDE SECTION - LH | \$ 57.00 | |
| 8 | REAR LIGHT REFLECTOR - LH/RH | 2 \$ 70.00 | |
| 9 | SENSOR -INNER/OUTER | \$ 211.00 | |
| 10 | SECTIONAL PART - SIDE PANEL - LH | \$ 2,006.00 | |
| 11 | CONNECTING PLATE - LH REAR | \$ 85.00 | |
| 12 | BOTTOM PLATE - LH | \$ 174.00 | |
| 14 | SIDE WINDOW - LH | \$ 502.00 | |
| 15 | REAR WINDOW | \$ 704.00 | |
| 16 | PRIMER | 2 \$ 37.00 | |
| 17 | LED TAIL LIGHT - LH | \$ 730.00 | |
| 18 | WHEEL HOUSING LINER - LH | \$ 215.00 | |
| 19 | ATTACHMENT PARTS FOR WHEEL HOUSING LINER | \$ 77.00 | |
| 20 | 1/4 GLASS SEALANT | \$ 100.00 | |
| SUB-TOTAL SPARE PARTS | | \$ 7,147.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8002 P

| <u>S/N</u> | <u>Parts Description</u> | <u>Damage Pa</u> <u>S/NETT</u> |
|-----------------------------|--------------------------|-----------------------------------|
| 21 | RR WINDSCREEN SEALANT | \$ 200.00 |
| 22 | ARCYLIC SEALANT | \$ 180.00 |
| 23 | CAVITY WAX | \$ 140.00 |
| 24 | STONE CHIP TREATMENT | \$ 180.00 |
| 25 | SUNDRIES | \$ 300.00 |
| TOTAL SPARE PARTS | | : \$ 8,147.00 |
| TOTAL LABOUR CHARGES | | : \$ 13,572.00 |
| GRAND TOTAL | | : \$ 21,719.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant