
BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D



墨 6744 2377

Date: 26th Jun 2018, Tuesday

M/s AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 Singapore 079120 Tel: 6419 3000 By EMAIL: admin-a@lkkauto.com.sg

Dear Sir / Madam,

REF: Your Insured Vehicle SLR4222M

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA) ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SFW 5844G & SLR 4222M ON 23/06/2018 WITHIN AIRPORT TERMINAL 2 @ 0630 HRS.

Our client's vehicle - SFW 5844G was damaged in the above accident.

A copy of the Singapore Accident Statement report filed is enclosed.

As a result of the accident, the vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us have the list of surveyors to conduct a pre-repair survey of the vehicle within 2 working days.

Please be informed that the said vehicle can be inspected at:

Name of Workshop: Best Solution Autocare Pte Ltd

Address: 53 Ubi Avenue 1 #03-01 Paya Ubi Industrial Park S(408934)

Contact Person: Ms LEE
Telephone No: 6744 0777

Fax No: 6744 2377

Please note that if we do not receive any reply from you within the stipulated timeline, you will be deemed to have waived your rights to a pre-repair inspection. In view of that, we shall proceed to repair the vehicle without further reference to you.

Thank You

BEST SOLUTION AUTOCARE PTE-LTD

Authorized Signatory