

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adam King
Surveyed Date : 26/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : the authorised, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0417/2017/JN 14-Nov-18 Jeffery Tan 1 SLA 8282 C Audi A1 1.0 SB TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Audi Emblem	\$ 108.00	✓ 8.6
2	"A1" emblem	\$ 83.00	✓ 66.16
3	"TFS" emblem	\$ 83.00	✓ 66.16
		\$ 274.00	
TOTAL		\$ 274.00	

For Premium Automobiles Pte Ltd

Adrian Ling
Slip 14/11/18.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0716/2018/JT
Date : 22-Jun-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 23 Nov 18

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms. Teng Yi Wen June
Address : 381 Tanglin Road
#11-03
Singapore 247965
Telephone : (HP) +65 9430099 (Mr. Teng)
Type of Claim : Own Damage Claims
Policy No. : 2100450428-01000
Vehicle No : **SLA 8282 C**
Model Code : Audi A1 1.0 SB TFSI
Model / Year : Jan-16
Engine No : CHZ 057775
Chassis No : WAUZZZ8X5GB058751
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Allan Wu / Johnny Boo
Accident Date : 30-Apr-17
Place of Accident : Commonwealth Ave West

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLA 8282 C.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	\$ 280.00
2	To remove and transfer rear lid convenience lock system and wire harness for tail lights.	S/N	\$ 280.00	\$ 280.00
3	To remove rear fitting, dismantle and renew rear bumper and rear lid. Transfer old fitting and align to position. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,500.00	\$ 1,000.00
4	To respray rear bumper and rear lid.		\$ 1,700.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 3,952.00</u>	<u>\$ 2,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLA 8282 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,238.00	
2	REAR BUMPER FIXING PARTS	\$ 62.00	
3	REAR LID	\$ 2,194.00	\$ 1,755.20
4	REAR LID ATTACHEMENT PARTS	\$ 240.00	
5	PARKING ADHESIVE	\$ 14.00	\$ 11.12
6	REAR LID LOCK	\$ 152.00	
7	REAR WINDSCREEN	\$ 608.00	\$ 486.40
8	GLASS PRIMER	\$ 18.00	\$ 14.40
9	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
10	Added parts - see attached	\$ 274.00	\$ 218.32
11	SUNDRIES	\$ 200.00	\$ 2.08
TOTAL SPARE PARTS		\$ 5,200.00	\$ 2,687.52
TOTAL LABOUR CHARGES		\$ 3,952.00	\$ 2,852.00
GRAND TOTAL		\$ 9,152.00	\$ 5,539.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0417/2017/JN
14-Nov-18
Jeffery Tan
1
SLA 8282 C
Audi A1 1.0 SB TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Audi Emblem	\$ 108.00	✓ 86.00
2	"A1" emblem	\$ 83.00	✓ 66.16
3	"TFS" emblem	\$ 83.00	✓ 66.16
		\$ 274.00	218.32
TOTAL		\$ 274.00	

For Premium Automobiles Pte Ltd

Adrian Ling
Slip. 14/11/18.

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLA 8282 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0716/2018/MAS

2 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLA 8282 C, Audi A1 SB 1.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLA 8282 C**, claimant, **Ms. Teng Yiwen, June**, please find the related document per attached.

1. A copy of the Original invoice no. 85013303 – S\$5,285.29
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLA 8282 C

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road

Singapore 159938

Main Telephone: 6836 2223

Main Telefax: 6471 3733

Page 1 16:36

Alexandra Service Centre

281 Alexandra Road

Singapore 159938

Telephone: 6388 2223

Telefax: 6475 1023

Ubi Service Centre

55 Ubi Road 1

Singapore 408871

Telephone: 6388 2223

Telefax: 6475 1023

Customer Service

Service Appointment

24 Hour Breakdown Service

Email

customer.care@premiumauto.com.sg

6366 2323

9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

BST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013303

Date: 20/12/2018

Order: SLA8282C

Term: 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLA8282C (V 28816)

Regn Date: 29/01/2016

Mileage: 17441

WIP No.: 22381

Model: AI SB 1.0 TFSI S tronic 8XFC56

Chassis: WAUZZZ8X56B058751

Engine: CHZ 057775

Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE REAR FITTING, DISMANTLE AND RENEW REAR LID, REPAIR REAR BUMPER, TRANSFER OLD FITTING AND ALIGN TO POSITION, REORGANISE REAR CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND REAR LID	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M:	200.00	1.00	200.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road

Singapore 159938

Main Telephone: 6836 2223

Main Telefax: 6471 3733

Page 2 16:36

Alexandra Service Centre

281 Alexandra Road

Singapore 159938

Telephone: 6388 2223

Telefax: 6475 1023

Ubi Service Centre

55 Ubi Road 1

Singapore 408634

Telephone: 6388 3338

Telefax: 6841 1183

Customer Service

Service Appointment

24-hour Breakdown Service

Email

customer.care@premiumauto.com.sg

6366 2323

9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013303
Date: 20/12/2018
Order: SLA8282C
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLA8282C (V 28816)

Regn Date: 29/01/2016

Mileage: 17441

WIP No.: 22381

Model: A1 SB 1.0 TFSI S tronic 8XFCSE

Chassis: WAUZZZ8X56B058751

Engine: CHZ 057775

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
		TO SUPPLY REAR WINDSCREEN SEALANT			
X	ABX4827023B	(A) (SK) LID	1.00	2194.00	1,755.20
X	ABX4845501A NVB	REAR WINDOW	1.00	608.00	486.40
X	ABX0853742A 2ZZ	AUDI SIGN	1.00	107.50	86.00
X	ABX0853741 2ZZ	INSCRIPTION 'A1'	1.00	82.70	66.16
X	ABX0853737A 2ZZ	INSCRIPTION 'TFSI'	1.00	82.70	66.16
X	ABD0853419F	PACKING	1.00	13.90	11.12
X	ABT0827310	NUT	2.00	1.30	2.08
X	AD 00920002	PRIMER (DG)	1.00	18.00	14.40

Parts 2,487.52
Labour 0.00
Sublet 3,052.00
Menus 0.00
Lubricant 0.00

Sub-Total 4,939.52

7% GST 345.77

Grand Total 5,285.29

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SLA 8282 C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0716/2017/JT
Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A1 SB 1.0 TFSI S-tronic
Vehicle Chassis No. : WAUZZZ8X5GB058751
Vehicle Regn No. : SLA 8282 C
Vehicle Mileage : 17441 km
Vehicle Owner : Ms. Teng Yiwen, June
Certificate No : 2100450428-01000
Policy Excess : \$642.00 (Inclusive GST)
Accident Date : 30th April 2017
Place : Commonwealth Ave West
Repair Cost : \$ 5,285.29
WIP No. : 22381
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 17/11/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2017		27 Jun 2018 09:38 Edit Adj Rpt	S\$5,539.52 Edit Estimates	S\$5,539.52 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TENG YI WEN JUNE, ID: S8617685H, Tel: +6582880578		
Vehicle Reg. No.:	SLA8282C	Date of Loss:	30/04/2017 14:00 - :59 [15 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 3320373846SG	Policy/Cover Note No.:	2100450428-01000 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/07/2018]		
Driver/Custodian:	TENG KEE NAM (66 / Male), NRIC: S8617685H, Tel: +6594310099		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (05/07/2018): Alert - Adj Mandate Approved (S\$5886.00) - SLA8282C - Claim Handler: Loo, Tong S...
- AIG_SG (28/06/2018): SLA8282C / OD / 30/04/2017 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLA8282C (3320373846SG)**
OD
Apr 30 2017 2:00PM
[TENG YI WEN JUNE]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

1 per page
☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 15:13	Adjuster Immediate Advice	Load HTM	

3 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 14:55	General View	Load JPG	☒
2	27/06/18 14:55	Chassis Number	Load JPG	☒
3	27/06/18 14:55	General View	Load JPG	☒
4	27/06/18 14:55	General View	Load JPG	☒
5	27/06/18 14:55	General View	Load JPG	☒
6	27/06/18 14:55	General View	Load JPG	☒
7	27/06/18 14:55	General View	Load JPG	☒
8	27/06/18 14:55	General View	Load JPG	☒
9	27/06/18 14:55	General View	Load JPG	☒
10	27/06/18 14:55	General View	Load JPG	☒
11	27/06/18 14:55	General View	Load JPG	☒
12	27/06/18 14:55	General View	Load JPG	☒
13	27/06/18 14:55	General View	Load JPG	☒

1 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 14:54	Singapore Accident Statement	Load PDF	
2	27/06/18 14:54	Police Report	Load PDF	
3	27/06/18 14:54	ESTIMATE	Load PDF	
4	27/06/18 16:36	Certificate of Insurance	Load PDF	
5	27/06/18 16:36	Driver's Driving License	Load PDF	
6	10/01/19 13:45	SUPPLEMENTARY	Load PDF	
7	10/01/19 13:45	DISCHARGE VOUCHER	Load PDF	
8	10/01/19 13:45	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

View [View in Browser](#)

1 per page
☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/05/17 11:20	Accident Statement	Load HTM	
2	19/06/18 14:36	Addendum Sheet	Load JPG	☒
3	19/06/18 14:39	Accident Statement Addm. #1	Load HTM	

3 per page
☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
----	--------------	-----------------------------------	-----------	-------

Documents Checklist

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18011674/AQBS2

Date: 10/01/2019

REFERENCE

Insured/Claimant: TENG YI WEN JUNE
Date of Loss: 30/04/2017

Policy No: 2100450428-01000
Nature of Claim: OD

Claim No: 3320373846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA8282C**
Make & Model: AUDI A1, 999cc SB 1.0 TFSI (PI) (A)
Reg. Date: 29/01/2016 (Man. Year: 2015)
Colour: Red
Engine Capacity: 999 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CHZ057775
Chassis No: WAUZZZ8X5GB058751
Odometer: 14845 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):
Handbrake (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Yes
No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R16
Front Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm

Rear Tyre Size: 215/45 R16
Rear Left Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,144.32	2,687.52	2,456.80	47.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,852.00	1,100.00	27.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,096.32	5,539.52	3,556.80	39.10
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,496.32	4,939.52	3,556.80	41.86
+ GST 7.00/7.00% (S\$)	594.74	345.77	248.97	41.86
Nett Amount (S\$)	9,091.06	5,285.29	3,805.77	41.86

INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 26/06/2018

Estimated Period of Repair: 4.0 days

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Inspected At:
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,238.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	62.00 FS	*- FS
3	1		*REAR LID	Dented	2,194.00 FS	*1,755.20 FS
4	1		*REAR LID ATTACHMENT PARTS	Not Necessary	240.00 FS	*- FS
5	1		*PARKING ADHESIVE	Necessary	14.00 FS	*11.12 FS
6	1		*REAR LID LOCK	Not Necessary	152.00 FS	*- FS
7	1		*REAR WINDSCREEN	Necessary	608.00 FS	*486.40 FS
8	1		*GLASS PIRMER	Necessary	18.00 FS	*14.40 FS
9	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
10	1		*SUNDRIES	Necessary	200.00 FS	*2.08 FS
11	1		*AUDI EMBLEM	Necessary	86.00 FS	*86.00 FS
12	1		*A1 EMBLEM	Necessary	66.16 FS	*66.16 FS
13	1		*TFS EMBLEM	Necessary	66.16 FS	*66.16 FS
Total Parts (S\$)					5,144.32	2,687.52

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LID CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	New	280.00	280.00
3	TO REMOVE REAR FITTINGS, DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TRANSFER OLD FITTING AND ALIGN TO POSITION. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,500.00	1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID.	New	1,700.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			3,952.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >