

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5329J****AAD1806-229***Not Notarized  
61 Sep 8 1250h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5329J**

VF1ABL15AUC279360

RENAULT

LATITUDE

23.6.2018

**TOKIO MARINE****PART****LIST**

|    |                                    |    |                         |     |
|----|------------------------------------|----|-------------------------|-----|
| 1  | 1 BUMPER COVER REAR                | \$ | <i>But 1nd</i> 1,108.46 | ✓   |
| 2  | 1 BUMPER LOWER REAR                | \$ | <i>SH</i> 768.84        | } X |
| 3  | 1 BUMPER BRACKET CTR REAR          | \$ | <i>SH</i> 113.47        |     |
| 4  | 1 BUMPER BRACKET SIDE RH REAR      | \$ | <i>SH</i> 135.97        |     |
| 5  | 1 BUMPER RETAINER RH REAR          | \$ | <i>SH</i> 44.99         |     |
| 6  | 1 BUMPER REFLECTOR RH              | \$ | <i>SH</i> 43.61         |     |
| 7  | 1 BUMPER BRACKET SIDE LH REAR      | \$ | <i>SH</i> 135.97        | } X |
| 8  | 1 BUMPER RETAINER LH REAR          | \$ | <i>SH</i> 44.99         |     |
| 9  | 1 BUMPER REFLECTOR LH              | \$ | <i>SH</i> 43.61         |     |
| 10 | 1 BUMPER BEAM REAR                 | \$ | <i>N</i> 777.52         | X   |
| 11 | 1 BUMPER BEAM BRACKET LH REAR      | \$ | <i>N</i> 225.95         | X   |
| 12 | 1 BUMPER BEAM BRACKET RH REAR      | \$ | <i>N</i> 225.95         | X   |
| 13 | 1 OUTER PANEL REAR (End Panel)     | \$ | <i>N</i> 1,471.77       | } X |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM | \$ | <i>SH</i> 404.56        |     |
| 15 | 1 TAILLAMP RH                      | \$ | <i>SH</i> 552.55        |     |
| 16 | 1 TAILLAMP PANEL RH                | \$ | <i>N</i> 986.70         |     |
| 17 | 1 BOOT REAR                        | \$ | <i>N</i> 2,872.68       |     |
| 18 | 1 BOOT FINISHER                    | \$ | <i>SH</i> 470.06        |     |
| 19 | 1 BOOT WHEATERSTRIP                | \$ | <i>SH</i> 323.05        |     |
| 20 | 1 BOOT REFLECTOR LAMP LH           | \$ | <i>SH</i> 493.35        |     |
| 21 | 1 BOOT REFLECTOR LAMP RH           | \$ | <i>SH</i> 493.35        |     |
| 22 | 1 BOOT BADGE 'RENAULT'             | \$ | <i>UN</i> 225.36        |     |
| 23 | 1 BOOT BADGE                       | \$ | <i>UN</i> 225.36        |     |
| 24 | 1 BOOT STRUT LH                    | \$ | <i>SH</i> 276.08        | } X |
| 25 | 1 BOOT STRUT RH                    | \$ | <i>SH</i> 276.08        |     |
| 26 | 1 BOOT HINGE LH                    | \$ | <i>N</i> 367.84         |     |
| 27 | 1 BOOT HINGE RH                    | \$ | <i>N</i> 367.84         |     |
| 28 | 1 BOOT INNER TRIM                  | \$ | <i>SH</i> 586.45        |     |
| 29 | 1 BOOT SWITCH                      | \$ | <i>SH</i> 168.13        |     |

**Trans-cab Auto Services Pte Ltd****AAD1806-229**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5329J**

|    |                   |        |                   |
|----|-------------------|--------|-------------------|
| 30 | 1 BOOT LOCK       | \$     | <i>n</i> 202.67 X |
| 31 | 1 BOOT LOCK CATCH | \$     | <i>n</i> 74.40 X  |
|    |                   | \$     | <b>14,507.62</b>  |
|    |                   | 10% \$ | <b>7.44</b>       |
|    |                   | \$     | <b>14,500.18</b>  |

**Special Nett**

|    |                                      |    |                    |
|----|--------------------------------------|----|--------------------|
| 1  | 1SET PARKING AID                     | \$ | <i>sn</i> 700.00 X |
| 2  | 1SET REAR BUMPER CLIP                | \$ | <i>nn</i> 66.00 —  |
| 3  | 1SET BUMPER BRACKET CTR CLIP         | \$ | <i>nn</i> 33.00 —  |
| 4  | 1SET BUMPER BRACKET SIDE CLIP RH RR  | \$ | <i>nn</i> 10.00 X  |
| 5  | 1SET BUMEP R RETAINER RH CLIP RR     | \$ | <i>nn</i> 20.00 X  |
| 6  | 1SET BUMEP R BRACKET SIDE CLIP LH RR | \$ | <i>nn</i> 10.00 X  |
| 7  | 1SET BUMEP R RETAINER CLIP LH RR     | \$ | <i>nn</i> 20.00 X  |
| 8  | 1SET BUMPER LOWER REAR RIVET         | \$ | <i>nn</i> 22.00 X  |
| 9  | 1SET BUMPER LOWER REAR CLIP          | \$ | <i>nn</i> 66.00 X  |
| 10 | 1 EXHAUST MOUNTING REAR              | \$ | <i>nn</i> 17.82 X  |
| 11 | 2 REAR WINDSCREEN SELANT             | \$ | <i>nn</i> 80.00 X  |
|    | 1 WINDSCREEN MOULDING                | \$ | <i>nn</i> 100.00 X |
|    | 1 REAR WINDSCREEN INNER SPONGE SEAL  | \$ | <i>nn</i> 100.00 X |

**TOTAL \$ 1,244.82****TOTAL PARTS \$ 15,745.00****LABOUR**

|                                                                                                                                 |    |                      |
|---------------------------------------------------------------------------------------------------------------------------------|----|----------------------|
| Putty And Spray Painting Of The Affected Portion.                                                                               | \$ | 3,000.00 <i>2201</i> |
| Panel Beating, Knocking And Straightening The<br>Necessary Portion, Remove And Renewal Of Parts,<br>Adjust And Realign The Same | \$ | 2,200.00 <i>2001</i> |
| To Rust-Proofing Of The Affected Areas.                                                                                         | \$ | <i>nn</i> 170.00 X   |
| To reinstall rear bumper parking sensor.                                                                                        | \$ | 170.00 <i>601</i>    |

**Trans-cab Auto Services Pte Ltd**

AAD1806-229

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5329J

|                                                                                      |    |          |
|--------------------------------------------------------------------------------------|----|----------|
| To transfer of bootlid fittings, attachments and perform water seepage test.         | \$ | 170.00 X |
| To repair and realign rear exhaust pipe.                                             | \$ | 170.00 X |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | 170.00 X |
| To transfer of rear end panel fittings, attachment and perform water seepage test.   | \$ | 170.00 X |
| To transfer of rear end panel fittings, attachment and perform water seepage test.   | \$ | 170.00 X |
| To transfer of rear windscreen fittings and conduct water seepage test.              | \$ | 170.00 X |
| To check steering geometry and computer wheel alignment                              | \$ | 220.00 X |

**TOTAL \$ 6,780.00****Over All Total \$ 22,525.00****(LUMP SUM)****Repair Days****10 DAYS***2 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: