

ASS. REC. BY:

REF:

TMI / CC3 / TML8011684 / Kvb n2

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_


Insured: SL 3352HPolicy No. MH000848Claims No. M1803207

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S11C 5329J Yr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or AMake: Renault Latitude c.c. 1995Colour: M. White / Red A/C: Insured / Std / NI / NASp. Reading 468212 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: V11A BL15AUC 279360Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: GrTi 215/60R16Ling R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 23/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/6 File pass to Carhenge

27/6/16 11pm 812506 (Real 21, 275, 94N)

28/6/18 Email GIA to TMI

S11C 5329J - CC3 / TML16018958 / Kvb n2

SL 3352H - X

DPA: 03-10-16

RECEIVED 29 JUN 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2) 28/6 - typist

Days Of Repair: 2Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ - RS. \$

Fixtures

Others

TOTAL

250

10

260

Report Format:

meimen

Lump Sum / I.B.I. (\$)

1250/-

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2018		28 Jun 2018 15:04				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	FUSION CAR RENTALS PTE LTD, Co. Reg. No.: 201620140G		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5329J	Date of Loss:	23/06/2018 00:00 - :59
Claim Type:	TP / M1803207	Policy/Cover Note No.:	MH000848 (Third Party Only) Coverage: 26/07/2017 - 25/07/2018
Vehicle Reg. No. (Insured):	SJL3352H	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/07/2018]		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

6/25/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHC5329J
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001912
Chassis No.:	VF1ABL15AUC279360
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Sep 2014
First Registration Date:	15 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2022
PARF Rebate Amount:	\$9,373.00

**Intended COE Rebate Details**

COE Expiry Date:	14 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$26,757.00
<b>Total Rebate Amount:</b>	<b>\$36,130.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Jun 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/06/2018 12:26
Date Of Accident	23/06/2018 12:05
Exact Location Of Accident	HENDERSON ROAD TOWARDS TELOK BLANGAH HEIGHTS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5329J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN THONG SOON
NRIC No	S0440771G
Date Of Birth	30/12/1954
Occupation	OUTDOOR
Date Of Driving Pass	23/04/1980
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84821711
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 152 ANG MO KIO AVENUE 5 #11-3016
Postcode	560152
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	POTONG PASIR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 142 POTONG PASIR AVENUE 3 , POSTCODE: 350142 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2829999 - FAX NO: 62815964
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please refer to police report

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL3352H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KWAN SHAN WEN EUGENE
NRIC/Passport Number	S8928340Z
Contact Number	84482030
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name TAN THONG SOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5329J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



A = SHC 5329J  
B = SJL 3352H  
Henderson Road  
towards Telok Blangah Heights

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

GIA/MS SketchPlanForm\_V3

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180624/2055

1 of 3

Report No. T/20180624/2055

Police Station Of Origin:  
Potong Pasir NPP  
142 Potong Pasir Avenue 3 #01-240  
SINGAPORE 350142  
Tel No: 1800-2829999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/06/2018 15:30		Vide Report No.:		Station Diary No.: 18	
<b>Informant's Particulars</b>					
Name of Informant: TAN THONG SOON			Address: APT BLK 152 ANG MO KIO AVENUE 5 #11-3016 SINGAPORE 560152		
ID Type / ID No.: NRIC NO / S0440771G			Contact No.: Home/Office: Mobile: 84821711		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 30/12/1954	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class:		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/06/2018 12:05	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 HENDERSON ROAD TELOK BLANGAH HEIGHTS T-JUNCTION BETWEEN HENDERSON ROAD AND TELOK BLANGAH HEIGHTS				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

<b>Details of Vehicles Involved</b>						
Vehicle No.	Vehicle Type	Plate No.	Model	Color	Condition	No. of Passengers
SHC5329J	Taxi				Slightly Damaged	0
SJL3352H	Car				Slightly Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180624/2055

2 of 3

Report No. T/20180624/2055

Police Station Of Origin:  
Potong Pasir NPP  
142 Potong Pasir Avenue 3 #01-240  
SINGAPORE 350142  
Tel No: 1800-2829999

## CONTINUATION OF REPORT

Name	TAN THONG SOON	ID No.	S0440771G
Related Vehicle	SHC5329J (Taxi)	Contact No.	84821711
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	24/06/2018	Date Discharge	24/06/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Name	KWAN SHAN WEN EUGENE	ID No.	S8928340Z
Related Vehicle	SJL3352H (Car)	Contact No.	84482030
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 23/06/2018 at about 1205hrs, the Taxi(SHC5329J) that I had drove met with an accident at the T-junction between Henderson Road and turning right to Telok Blangah Heights. Prior to that, I was waiting at that said traffic light and there was another car in front of me. All of the sudden, another car (SJL3352H) hit the back of my Taxi. I managed to stop my taxi from hitting the car in front. Once stopped, both drivers wanted to exit out however as the traffic light had turned green, we did not want to hog the traffic. We drove to a nearby carpark and exchanged particulars.

My Taxi sustained scratches and dents at the rear bumper, causing some misalignment on the bumper and I am unsure of the damages to the other car. My Taxi does not have any in-car camera installed. Due to the impact, I felt a slight pain however I went home and got some rest. When I woke up, the pain worsen as such I went to Mount Alvernia Hospital for a medical check-up and received 7 days of MC. I am lodging this report to assist in any investigation necessary as well as to inform my Taxi Company of such matters.



**SINGAPORE  
POLICE FORCE**



T/20180624/2055

3 of 3

Report No. T/20180624/2055

Police Station Of Origin:  
Potong Pasir NPP  
142 Potong Pasir Avenue 3 #01-240  
SINGAPORE 350142  
Tel No: 1800-2829999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 MUHAMMAD FAKHRUDDIN BIN SHAHRI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

24/06/2018 15:30

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Classification Of Case:

SN 057

Authentication Stamp

NP168



SINGAPORE  
POLICE FORCE

SIGNATURE

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5329J****AAD1806-229***Not Notified  
61 Sep @ 1250h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5329J**

VF1ABL15AUC279360

RENAULT

LATITUDE

23.6.2018

**TOKIO MARINE****PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 TAILLAMP RH
- 16 1 TAILLAMP PANEL RH
- 17 1 BOOT REAR
- 18 1 BOOT FINISHER
- 19 1 BOOT WHEATERSTRIP
- 20 1 BOOT REFLECTOR LAMP LH
- 21 1 BOOT REFLECTOR LAMP RH
- 22 1 BOOT BADGE 'RENAULT'
- 23 1 BOOT BADGE
- 24 1 BOOT STRUT LH
- 25 1 BOOT STRUT RH
- 26 1 BOOT HINGE LH
- 27 1 BOOT HINGE RH
- 28 1 BOOT INNER TRIM
- 29 1 BOOT SWITCH

\$	<i>But 1/2nd</i>	1,108.46	✓
\$	<i>Sn</i>	768.84	} X
\$	<i>Sn</i>	113.47	
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>Sn</i>	135.97	} X
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>Sn</i>	777.52	X
\$	<i>Sn</i>	225.95	X
\$	<i>Sn</i>	225.95	X
\$	<i>Sn</i>	1,471.77	} X
\$	<i>Sn</i>	404.56	
\$	<i>Sn</i>	552.55	
\$	<i>Sn</i>	986.70	
\$	<i>Sn</i>	2,872.68	
\$	<i>Sn</i>	470.06	} X
\$	<i>Sn</i>	323.05	
\$	<i>Sn</i>	493.35	
\$	<i>Sn</i>	493.35	
\$	<i>Sn</i>	225.36	
\$	<i>Sn</i>	225.36	
\$	<i>Sn</i>	276.08	} X
\$	<i>Sn</i>	276.08	
\$	<i>Sn</i>	367.84	
\$	<i>Sn</i>	367.84	
\$	<i>Sn</i>	586.45	
\$	<i>Sn</i>	168.13	

**Trans-cab Auto Services Pte Ltd**

AAD1806-229

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5329J

30	1 BOOT LOCK	\$	<i>n</i> 202.67 X
31	1 BOOT LOCK CATCH	\$	<i>n</i> 74.40 X

	\$	14,507.62
10%	\$	7.44
	\$	<u>14,500.18</u>

13,056.85

**Special Nett**

1	1SET PARKING AID	\$	<i>in</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>nn</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00 X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00 X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00 X
10	1 EXHAUST MOUNTING REAR	\$	<i>nn</i> 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 X
	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 X
	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 X

TOTAL \$ 1,244.82

TOTAL PARTS \$ 15,745.00**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>

## Trans-cab Auto Services Pte Ltd

AAD1806-229

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5329J

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To repair and realign rear exhaust pipe.	\$	↷ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↷ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↷ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↷ 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↷ 170.00 X
To check steering geometry and computer wheel alignment	\$	↷ 220.00 X

**TOTAL \$ 6,780.00**

**Over All Total \$ 22,525.00**

21081.67

**(LUMP SUM)**

**Repair Days**

**10 DAYS**

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18011684/KVBN2

Date: 03/07/2018

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH000848
Claimant Vehicle No :	SHC5329J	Insured Vehicle No :	SJL3352H
Date of Loss:	23/06/2018	Nature of Claim:	TP
		Claim No:	M1803207

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC5329J	Engine No:	M9R8839C001912
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC279360
Reg. Date:	15/09/2014 (Man. Year: 2014)	Odometer:	468212 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,301.67	1,096.61	13,205.06	92.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,780.00	480.00	6,300.00	92.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,081.67</b>	<b>1,576.61</b>	<b>19,505.06</b>	<b>92.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		
(S\$)	21,081.67	1,250.00	19,831.67	94.07
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,475.72</b>	<b>87.50</b>	<b>1,388.22</b>	<b>94.07</b>
<b>Nett Amount (S\$)</b>	<b>22,557.39</b>	<b>1,337.50</b>	<b>21,219.89</b>	<b>94.07</b>

## INSPECTION

Date of Assignment:	28/06/2018	
Date Inspected:	26/06/2018 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2018)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5329J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled/Dented	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
18	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
19	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
20	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
21	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
22	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
23	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
24	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
25	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
26	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
27	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
28	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
29	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
30	1		*BOOT LOCK	Repair	202.67 FL	*- FL
31	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
32	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
33	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
34	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
35	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
36	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
37	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
40	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
41	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
42	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
44	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,752.43	1,207.46
- List Item Discount on L Items 10.00/10.00% (S\$)					1,450.76	110.85
Total Parts (S\$)					14,301.67	1,096.61

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (\$\$)			6,780.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >