

Date/Time	STAGE	DATE / PIC
2/2/18 VIC	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
02/02/18	Call OI	
	After call Itr to OI	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	☐ ☐
	After call Itr to OI	☐ ☐
	Authorisation To Act	☒ ☐
	Release Voucher	☒ ☐
	Final Repair Bill	☒ ☐
	Car Rental Invoice	☐ ☐
	Towing Invoice	☐ ☐
	LTA / GIA	☒ ☐
	Medical Bill	☐ ☐
	PIR - Against OIO	☒ ☐
	Mandate/Reject Instruction	☐ ☐
	LOD	☒ ☐
	Payment Breakdown Form	☐ ☐
	Post-Repair Photos	☐ ☐
	Others	☐ ☐
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: L16	\$5 15,500.00	18 days/Reduction: 62 %
		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	\$ 100	(Assessed / Assessed) BOLA S/N No.:
Repair Cost (w/acc)	\$5 16,500.00	
Loss of Rental (LOR):	\$5 -	(days)
Loss of Use (LOU):	\$5 12000.00	100 x 12 days
Loss of Income (LOI):	\$5 -	(5 x days)
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search	\$5 10.00	
Medical:	\$5 -	
Disbursement:	\$5 -	(e.g. Tow/Independent)
Legal Cost	\$5 -	
Total:	\$5 18,795.00	Global Sum \$5:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$5 18,795.00	Name 1: KANG CAT REPAIRERS PTE LTD
Payee 2: (Strike if N.A.)	\$5 -	Name 2: -
Payee 3: (Strike if N.A.)	\$5 -	Name 3: -

ACC. REC BY: Adrian Lim

REF:

ASSIGNMENT

27/04/06

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 18 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKJ8943T Yr Regn: 2006 AprilType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier cc 2362Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 130114 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACU300045458Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/65R17R: 225/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 26/06/18Survey held at KanyDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP111

COE Exp. - 26/06/21

L/S \$15,800.00
CRAB: \$25,642.81 (62%)

MV: 29K

PV: 13.4K

Nett: 15.6K

Date/Time: File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

2)

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Survey Fee:

Transportation:

5 - 10% 24

Phone

Others

TOTAL

Report Format

Lump Sum / L.B.J. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18011686/Ahb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-06-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2635U	Veh. Inspected	SKJ 8943T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/06/2018	Inspection Date	26/06/2018	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Aushby@K, Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@angnet.com.sg
GST: 201306201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04/#05 JOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62244174

ATTN: Motor Claim Department

Estimate No: EST1800193

Date: 26 Jun 2018

Veh Reg No: SKJ8943T

Make/Model: TOYOTA HARRIER 2.4A

Chasis No: ACUJ300045458

Reg. Date: 27/04/2006

Your Ref No: SHC2635U

Claim Type: Third Party

Accident Date: 23/06/2018

TP Veh Reg No: SHC2635U

Estimate Repair Cost to Vehicle No :SKJ8943T

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT BUMPER Distorted.	801.70 ✓	
2	1 PC FRT BUMPER REINFORCEMENT Bent	908.60 ✓	549.10
3	1 PC FRT BUMPER SPONGE crushed.	145.60 ✓	
4	1 PC FRT FOG LAMP LH at	370.80 ✓	
5	1 PC FRT FOG LAMP RH crushed.	370.80 ✓	
6	2 PCS FRT TOWING COVER Dented.	42.40 ✓	
7	2 PCS FRT BUMPER SIDE RETAINER New	137.40 ✓	
8	1 PC FRT NUMBER PLATE BASE crushed.	117.10 ✓	
9	1 PC FRT SUPPORT PANEL Distorted.	1,072.70 ✓	867.90
10	1 PC FRT GRILLE crushed	551.40 ✓	
11	1 PC FRT GRILLE EMBLEM New	72.10 ✓	
12	1 PC FRT SUPPORT TOP GARNISH New	107.60 X	
13	1 PC BONNET Dented	1,508.70 ✓	1366.10
14	2 PCS BONNET HINGE New	135.40 X	
15	1 PC FRT FENDER RH Distorted	922.10 ✓	
16	1 PC FRT FENDER COWLING RH torn	362.70 ✓	
17	1 PC FRT FENDER SIGNAL LAMP RH New	66.10 X	
18	1 PC FRT FENDER COWLING LH missing	362.70 ✓	
19	1 PC FRT DOOR LH RH Dented	1,043.70 ✓	
20	1 PC FRT DOOR TOP HINGE LH RH } Not	75.10 X	
21	1 PC FRT DOOR BOTTOM HINGE LH RH } New	85.60 X	
22	1 PC FRT DOOR PROTECTOR LH RH Deformed	251.70 ✓	
23	1 PC FRT DOOR RUBBER LH RH Not New	251.70 X	
24	1 PC FRT ROCKER PANEL GARNISH RH Deformed	664.70 ✓	
25	1 PC FRT WIPER WATER TANK Deformed	176.70 ✓	
26	1 PC FRONT WIPER WATER TANK MOTOR Damaged	199.70 ✓	
27	1 PC HEADLAMP RH smashed.	1,921.80 ✓	
28	1 PC HEAD LAMP BALAST RH missing.	534.70 ✓	
29	1 PC HEAD LAMP BULB (HID) smashed.	363.10 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@Kaki Bukit, Singapore 417853
TEL: 6747 7636 FAX: 6748 3071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 JOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Estimate No: EST1800193
Date: 26 Jun 2018

Veh Reg No: SKJ8943T
Make/Model: TOYOTA HARRIER 2.4A
Chassis No: ACU300045458
Reg. Date: 27/04/2006
Your Ref No: SHC2635U

Estimate Repair Cost to Vehicle No :SKJ8943T

Quantity	Description	List Price	Amount
		S\$	S\$
30	1 PC HEAD LAMP BULB (HIGH BEAM) <i>smashed</i>	70.60 ✓	
31	1 PC HEADLAMP LH <i>ut</i>	1,921.80 ✓	
32	1 PC RADIATOR <i>Not New</i>	1,173.50 ✗	
33	1 PC AIRCON CONDENSER <i>Bent</i>	1,702.90 ✓	1196.40
34	2 PCS AIRCON CONDENSER SIDE GARNISH <i>Defend</i>	155.20 ✓	
35	1 PC AIRCON CONDENSER ALUMINIUM PIPE <i>Not New</i>	332.10 ✗	
36	1 PC AIRCON DISCHARGE PIPE <i>Not New</i>	561.70 ✗	
37	1 PC FRT ABS PUMP <i>Cracked</i>	6,312.70 ✓	3978.10
38	1 PC FRT ABS PUMP WIRE HARNESS <i>Not New</i>	446.90 ✗	
39	1 PC FRT SHOCK ABSORBER RH	384.90 ✗	
40	1 PC FRT KNUCKLE ARM RH	453.30 ✗	
41	1 PC FRT LOWER ARM RH	422.90 ✗	
42	1 PC FRT WHEEL HUB RH	222.50 ✗	
43	1 PC FRT WHEEL HUB BEARING RH	162.90 ✗	
44	1 PC FRT DRIVE SHAFT RH	1,536.90 ✗	
45	1 PC FRT LINKAGE RH	122.60 ✗	
46	1 PC FRT LOWER ARM BALL JOINT RH	224.10 ✗	
47	1 PC FRT SPORTS RIM RH <i>ut</i>	2,835.60 ✓	800(SA)
48	1 PC FRT CROSSMEMBER <i>Bent</i>	2,315.50 ✓	
49	1 PC ENGINE MOUNTING FRT	173.30 ✗	
50	1 PC ENGINE MOUNTING REAR	145.40 ✗	
51	1 PC ENGINE MOUNTING LH	314.40 ✗	
52	1 PC ENGINE MOUNTING RH	296.20 ✗	
53	1 PC ENGINE UNDER COVER	130.70 ✗	
54	1 PC FRT SHOCK ABSORBER LH	384.90 ✗	
55	1 PC FRT KNUCKLE ARM LH	453.30 ✗	
56	1 PC FRT LOWER ARM LH	422.90 ✗	
57	1 PC FRT WHEEL HUB LH	222.50 ✗	
58	1 PC FRT WHEEL HUB BEARING LH	162.90 ✗	
59	1 PC FRT DRIVE SHAFT LH	1,536.90 ✗	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Aumity@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
(GST:201300201N)

M/S: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63475100

FAX: 62244174

ATTN: Motor Claim Department

Estimate No: EST1800193

Date: 26 Jun 2018

Veh Reg No: SKJ8943T

Make/Model: TOYOTA HARRIER 2.4A

Chassis No: ACU300045458

Reg. Date: 27/04/2006

Your Ref No: SHC2635U

Claim Type: Third Party

Accident Date: 23/06/2018

TP Veh Reg No: SHC2635U

Estimate Repair Cost to Vehicle No:SKJ8943T

Quantity	Description	List Price	Amount
60	1 PC FRT SPORTS RIM LH <i>Not new</i>	2,835.60 X	SS
61	1 PC FRT SPORTS RIM COVER LH <i>Not new</i>	- 130.70 X	
62	1 PC FRT LOWER ARM BALL JOINT LH <i>Not new</i>	- 224.10 X	
		42,416.80	
		Less 25%	10,604.20 31,812.81
Special Net			
63	1 SET FRT BUMPER CLIPS <i>new</i>	40.00 ✓	
64	1 SET FRT BUMPER SENSOR <i>Damaged</i>	250.00 200	
65	1 PC FRT NUMBER PLATE <i>new</i>	50.00 ✓	
66	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00 ✓	
67	1 SET FRT FENDER COWLING CLIPS LH <i>new</i>	40.00 ✓	
68	1 SET FRT ROCKER PANEL GARNISH RH CLIPS <i>new</i>	40.00 ✓	
69	1 PC FRT TYRE RH <i>Not new</i>	380.00 X	
70	1 SET ENGINE UNDER COVER CLIP <i>new</i>	40.00 ✓	
71	1 PC FRT TYRE LH <i>Not new</i>	380.00 X	
72	1 PC RADIATOR COOLANT <i>new</i>	100.00 40	
		1,360.00	1,360.00
Labour			
73	1 TOWING	100.00 60	
74	1 TO SPRAY UNDERSEAL	150.00 X	
75	1 TO REMOVE AND REFIT ABS PUMP	300.00 80	
76	1 TO REMOVE AND REFIT UNDERCARRIAGE	700.00 600	
77	1 TO REMOVE AND REFIT ENGINE <i>Not new</i>	800.00 X	
78	1 TO REMOVE AND REFIT ENGINE MOUNTING <i>Not new</i>	300.00 X	
79	1 TO CHECK WHEEL ALIGNMENT	120.00 80	
80	1 TO REFILL AIRCON GAS	120.00 100	
81	1 TO PERFORM DIAGNOSTIC TESTS & PROGRAMME ABS FAULT LIGHT	280.00 100	
82	1 (FRONT) TO SPRAY PAINTING	2,200.00 1400	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobuy@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 10B BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Estimate No: EST1800193
Date: 26 Jun 2018

Veh Reg No: SKJ8943T
Make/Model: TOYOTA HARRIER 2.4A
Chasis No: ACU300045458
Reg. Date: 27/04/2006
Your Ref No: SHC2635U


Estimate Repair Cost to Vehicle No :SKJ8943T

Quantity	Description	List Price S\$	Amount S\$
83	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,600.00	1400
84	1 TO CHECK WIRING	300.00	3820
		7,970.00	7,970.00
	Total		S\$ 41,142.81
	Add GST @ 7%		2,880.00
	Total Amount Payable		S\$ 44,022.81

TOTAL: SINGAPORE DOLLAR FORTY FOUR THOUSAND TWENTY TWO AND CENTS EIGHTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Adrian King. total: 20735.80
L/S 26/06/18. H/S 15.5K
18 Days. (Nett Value)

15.5K

18 Days

Print Received Message

This mail is associated with :

***SKJ8943T (MCT18060771)**

[SHC2635U]

TP

HU WEI

Jun 23 2018 3:00PM

[COMFORT TRANSPORTATION PTE LTD]

Kang Car Repairers Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 14/12/2018 14:05 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SKJ8943T - Claim Handler: Priya

Maintained: Please try to negotiate LOU to 22 days.



江氏修理汽車私人有限公司

KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0620188943III
Your Ref : SHC2635U

Date : 26 OCT 2018

WITHOUT PREJUDICE

India International Insurance Pte Ltd

C/O LKK Auto Consultants Pte Ltd

51 Ubi Ave 1

#01-25 Paya Ubi Industrial Pk

Singapore 408933

Attention: Motor Claim Department

Dear Sirs,

Accident involving SKJ8943T and SHC2635U on 23.06.2018 along Stadium Walk/ Stadium Boulevard.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SHC2635U.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Mr Hu Wei, the owner of motor-vehicle no: SKJ8943T, we submit his claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 16,585.00
Loss of use (25 days x \$150.00)	\$ 3,750.00
LTA search by law firm	\$ 10.00
	<u>\$ 20,345.00</u>
	=====

Our claim for loss of rental is as follows :-

No of days	Date	Remarks
	23.06.18	Date of Accident /vehicle tow in workshop
1	24.06.18	} Sunday
2	25.06.18	} Reporting
3	26.06.18	} email to III/ Surveyed by LKK Auto
4	27.06.18	} Repair Day 1
5	28.06.18	} Day 1
6	29.06.18	} Day 2
7	30.06.18	} Day 3
8	01.07.18	} Sunday
9	02.07.18	} Day 4

<u>No of days</u>	<u>Date</u>	<u>Remarks</u>
10	03.07.18	} Day 5
11	04.07.18	} Day 6
12	05.07.18	} Day 7
13	06.07.18	} Day 8
14	07.07.18	} Day 9
15	08.07.18	} Sunday
16	09.07.18	} Day 10
17	10.07.18	} Day 11
18	11.07.18	} Day 12
19	12.07.18	} Day 13
20	13.07.18	} Day 14
21	14.07.18	} Day 15
22	15.07.18	} Sunday
23	16.07.18	} Day 16
24	17.07.18	} Day 17
<u>25</u>	<u>18.07.18</u>	<u>} Day 18</u>
25 days		18 days recommended

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1800643
- 2) GIA report of SKJ8943T
- 3) Police Report No : T/20180623/2149
- 4) Police Investigation Result
- 5) LTA search fee and invoice from A C Syed & Partners

We hope to receive your early reply soon.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD



LETTER OF AUTHORITY

Your Ref: MCT18060771

India International Insurance Pte Ltd
64 Cecil St
#4/#05 IOB Building
Singapore 049711

Dear Sirs,

Accident involving SKJ8943T and SHC2635U
on 23.06.18 at Stadium Walk.

I/We am/are the owner/s of vehicle number SKJ8943T.

I/We had instructed KANG CAR REPAIRERS PTE LTD to make a claim on my/our behalf against your company in respect of the abovementioned matter.

I/We hereby authorize you to issue the settlement cheque in favour of my/our workshop, KANG CAR REPAIRERS PTE LTD in full and final settlement of my/our claim for my/our repair cost and loss of use/rental charges, in respect of the above accident.

Yours faithfully,

.....
Hu Wei

KANG CAR REPAIRERS PTE. LTD.

.....
Witnessed by: Long Chin Watt

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

This Discharge Voucher applies strictly for Claimant's claim for personal-injury / property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

India Ref: MCT18060771
Claimant Ref: SKJ8943T

We/I, KANG CAR REPAIRERS PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 16,585.00 (repair cost), S\$ 2,200.00 (loss of use/rental), S\$ 10.00 (search fee), vehicle no. SKJ8943T that was damaged pursuant to the accident which occurred on 23/06/2018 (date) at STADIUM WALK (location) involving vehicle no. SHC2635U (insured vehicle). This is pursuant to the inspection conducted on 26/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HU WEI ("the third party claimant") of vehicle no. SKJ8943T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKJ8943T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 18,795.00 to KANG CAR REPAIRERS PTE LTD

Dated this 19 DEC 2018 day of 20

KANG CAR REPAIRERS PTE. LTD.

CLAIMANT:

Signature: [Signature]

..... Signed by the workshop (with chop)

Name: Kong Chin Watt

NRIC: S0224616C

Address: 1 Kaki Bukit Ave 6
#02-06 S417883

Nationality: _____

Occupation: _____

WITNESS:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933



江氏修理汽車私人有限公司

KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Final No: KCR-INV1800643
Claim No: EST1800193
Date: 16 Oct 2018
Policy No: 5075157797-02
Veh Reg No: SKJ8943T
Make/Model: TOYOTA HARRIER
2.4A
Chassis No: ACU300045458
Engine No: 2AZB181112
Reg. Date: 27/04/2006

Your Ref No: SHC2635U
Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Tax Invoice to Vehicle No :SKJ8943T

PAGE:1

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>

As recommended by surveyor to proceed repair at total cost/lumpsum cost	S\$ 15,500.00
Add GST @ 7%	1,085.00
Total Amount payable	S\$ 16,585.00

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND FIVE HUNDRED EIGHTY FIVE ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : KANG CAR REPAIRERS PTE LTD	BILL NO: B051 /2018
YOUR REF:	
OUR REF : ACS.KC.LTA.JUNE.2018	DATE : 6/7/18

TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.

LTA SEARCHES FOR THE MONTH JUNE 2018

1. SLC 5921B as at 12.6.18	\$ 10.00
2. YM 9273E as at 13.6.18	\$ 10.00
3. SKH 5148C as at 16.6.18	\$ 10.00
4. PA 5212C as at 20.6.18	\$ 10.00
5. SLR 9676D as at 21.6.18	\$ 10.00
6. GBD 6523Z as at 21.6.18	\$ 10.00
7. SHC 2635U as at 23.6.18	\$ 10.00

Total:

\$ 70.00

[SINGAPORE DOLLARS: SEVENTY ONLY.]



M/s A C SYED & PARTNERS
ADVOCATES & SOLICITORS
SINGAPORE

We reserved the right to forward a subsequent bill for any disbursements omitted herein.

E. & O.E.

Enquire Vehicle & Owner Information (Vehicle No. SHC2635U As At 23 Jun 2018 / 03:40:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: ACS.LTA.KC.06.18

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC2635U

Make Description/Model: HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Insurance Company Name: INDIA INT'L INS PTE LTD



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408665
Tel +65 6547 0000
Fax +65 6547 8259
www.police.gov.sg

Our Ref : TP/IP/37191/2018
Date : 2 August, 2018

HU YIDI
APT BLK 9 BOON KENG ROAD
#37-158
SINGAPORE 330009

Dear Sir/Madam

**ACCIDENT INVOLVING SHC2635U AND SKJ8943T ON 23/06/2018 AT 1540 HRS, ALONG
STADIUM WALK**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SHC2635U had committed an offence of Inconsiderate Driving Under Section 65(b) RTA Cap 276. Action has been initiated against the said driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, Muhd Noor at telephone 65476201 via email at Muhammad_Noor_Rahman@spf.gov.sg

Yours faithfully


Juremah Ahmad SSI(2)
For Head, Traffic Investigation
Traffic Police
Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2018 Edit Reg		26 Jun 2018 00:00 Edit Adj Rpt	\$15,500.00 Edit Estimates	\$15,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	HU WEI, ID: S2711339G		
Vehicle Reg. No.:	SKJ8943T	Date of Loss:	23/06/2018 15:00 - :59 [145 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18060771	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC2635U	Policy No. (Claimant):	5075157797-02
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (14/12/2018): Alert - Adj Mandate Maintained - SKJ8943T - Claim Handler: Priya
- III_SG (04/09/2018): Alert - Adj Mandate Approved (\$0.00) - SKJ8943T - Claim Handler: Priya
- III_SG (03/07/2018): Alert - Adj Mandate Maintained - SKJ8943T - Claim Handler: Priya

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKJ8943T (MCT18060771)
 [SHC2635U]
 TP
 HU WEI
 Jun 23 2018 3:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Kang Car Repairers Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Video							1 per page		☒		
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail		Print		
1	04/09/18 17:54	Video - Accident					1 Load MP4				
Photos/Images							3 per page		☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	24/09/18 19:08	General View					1 Load JPG		☒		
2	24/09/18 19:08	General View					1 Load JPG		☒		
3	24/09/18 19:08	General View					1 Load JPG		☒		
4	24/09/18 19:08	General View					1 Load JPG		☒		
5	24/09/18 19:08	General View					1 Load JPG		☒		
6	24/09/18 19:08	General View					1 Load JPG		☒		
7	24/09/18 19:08	General View					1 Load JPG		☒		
8	24/09/18 19:08	General View					1 Load JPG		☒		
9	24/09/18 19:08	General View					1 Load JPG		☒		
10	24/09/18 19:08	General View					1 Load JPG		☒		
11	24/09/18 19:08	General View					1 Load JPG		☒		
12	24/09/18 19:08	General View					1 Load JPG		☒		
13	24/09/18 19:08	General View					1 Load JPG		☒		
14	24/09/18 19:08	General View					1 Load JPG		☒		
15	24/09/18 19:08	General View					1 Load JPG		☒		
16	24/09/18 19:08	General View					1 Load JPG		☒		
17	24/09/18 19:08	General View					1 Load JPG		☒		
18	24/09/18 19:08	General View					1 Load JPG		☒		
19	24/09/18 19:08	General View					1 Load JPG		☒		
20	24/09/18 19:08	General View					1 Load JPG		☒		
21	24/09/18 19:08	General View					1 Load JPG		☒		
22	24/09/18 19:08	General View					1 Load JPG		☒		
23	24/09/18 19:08	General View					1 Load JPG		☒		
24	24/09/18 19:08	General View					1 Load JPG		☒		
25	24/09/18 19:08	General View					1 Load JPG		☒		
26	24/09/18 19:08	General View					1 Load JPG		☒		
27	24/09/18 19:08	General View					1 Load JPG		☒		
28	24/09/18 19:08	General View					1 Load JPG		☒		
29	24/09/18 19:08	General View					1 Load JPG		☒		
30	24/09/18 19:08	General View					1 Load JPG		☒		
31	24/09/18 19:08	General View					1 Load JPG		☒		
32	24/09/18 19:08	General View					1 Load JPG		☒		
33	24/09/18 19:08	General View					1 Load JPG		☒		
34	24/09/18 19:08	General View					1 Load JPG		☒		

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
35	24/09/18 19:08	General View		☒
36	24/09/18 19:08	General View		☒
37	24/09/18 19:08	General View		☒
38	24/09/18 19:08	General View		☒
39	24/09/18 19:08	General View		☒
40	24/09/18 19:08	General View		☒
41	24/09/18 19:08	General View		☒
42	24/09/18 19:08	General View		☒
43	24/09/18 19:08	General View		☒
44	24/09/18 19:08	General View		☒
45	24/09/18 19:08	General View		☒
46	24/09/18 19:08	General View		☒
47	24/09/18 19:08	General View		☒
48	24/09/18 19:08	General View		☒
49	24/09/18 19:08	General View		☒
50	24/09/18 19:08	General View		☒
51	24/09/18 19:08	General View		☒
52	24/09/18 19:08	General View		☒
53	24/09/18 19:08	General View		☒
54	24/09/18 19:08	General View		☒
55	24/09/18 19:08	General View		☒
56	24/09/18 19:08	General View		☒
57	24/09/18 19:08	General View		☒
58	24/09/18 19:08	General View		☒
59	24/09/18 19:08	General View		☒
60	24/09/18 19:08	General View		☒
61	24/09/18 19:08	General View		☒
62	24/09/18 19:08	General View		☒
63	24/09/18 19:08	General View		☒
64	24/09/18 19:08	General View		☒
65	24/09/18 19:08	General View		☒
66	24/09/18 19:08	General View		☒
67	24/09/18 19:08	General View		☒
68	24/09/18 19:08	General View		☒
69	24/09/18 19:08	General View		☒
70	24/09/18 19:08	General View		☒
71	24/09/18 19:08	General View		☒
72	24/09/18 19:08	General View		☒
73	24/09/18 19:08	General View		☒
74	24/09/18 19:08	General View		☒
75	24/09/18 19:08	General View		☒
76	24/09/18 19:08	General View		☒
77	24/09/18 19:08	General View		☒
78	24/09/18 19:08	General View		☒
79	24/09/18 19:08	General View		☒
80	24/09/18 19:08	General View		☒
81	24/09/18 19:08	General View		☒
82	24/09/18 19:08	General View		☒
83	24/09/18 19:08	General View		☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
84	24/09/18 19:08	General View	 Load JPG	☒
85	24/09/18 19:08	General View	 Load JPG	☒
86	24/09/18 19:08	General View	 Load JPG	☒
87	24/09/18 19:08	General View	 Load JPG	☒
88	24/09/18 19:08	General View	 Load JPG	☒
89	24/09/18 19:08	General View	 Load JPG	☒
90	24/09/18 19:08	General View	 Load JPG	☒
91	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
92	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
93	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
94	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
95	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
96	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
97	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
98	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
99	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
100	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
101	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
102	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
103	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
104	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
105	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
106	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
107	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
108	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
109	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
110	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
111	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
112	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
113	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
114	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
115	24/09/18 19:08	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 14:31	EMAIL FROM III DD 26062018	 Load PDF	
2	27/06/18 14:31	TP EST & GIA REPORT	 Load PDF	
3	25/09/18 10:04	TP ESTIMATE - MARKED	 Load PDF	
4	10/12/18 17:06	WORKSHOP INVOICE	 Load PDF	
5	10/12/18 17:06	LTA SEARCH	 Load PDF	
6	10/12/18 17:06	LOD	 Load PDF	
7	26/12/18 14:26	AUTHORISATION TO ACT FORM	 Load PDF	
8	26/12/18 14:26	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/06/18 09:06	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

--

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18011686/AHB3Q2

Date: 26/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SKJ8943T

Insured Vehicle No: SHC2635U

Date of Loss: 23/06/2018

Nature of Claim: TP

Claim No: MCT18060771

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKJ8943T

Make & Model: TOYOTA HARRIER, 2.4 (A)

Reg. Date: 27/04/2006 (Man. Year: 2006)

Colour: Blue

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2AZB181112

Chassis No: ACU300045458

Odometer: 130114 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size: 225/65 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,172.60	17,665.80	15,506.80	46.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,970.00	3,820.00	4,150.00	52.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,142.60	21,485.80	19,656.80	47.78
Approved Total (Overridden) (S\$)		15,500.00		
(S\$)	41,142.60	15,500.00	25,642.60	62.33
+ GST 7.00/7.00% (S\$)	2,879.98	1,085.00	1,794.98	62.33
Nett Amount (S\$)	44,022.58	16,585.00	27,437.58	62.33
+ Loss of Use (22.0 x S\$100.00/day) (S\$)		2,200.00		
+ Doc/Search Fee (S\$)		10.00		
Nett Liability (S\$)		18,795.00		

INSPECTION

Date of Assignment: 26/06/2018

Date Inspected: 26/06/2018 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2018)	
Parts: M1-SUV	TOYOTA HARRIER 2.4 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKJ8943T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP BULB (HIGH BEAM)	Smashed	70.60 FL	*70.60 FL
2	1		*HEADLAMP LH	Cut	1,921.80 FL	*1,921.80 FL
3	1		*RADIATOR	Not Necessary	1,173.50 FL	*- FL
4	1		*AIRCON CONDENSER	Bent	1,702.90 FL	*1,196.40 FL
5	2		*AIRCON CONDENSER SIDE GARNISH	Deformed	155.20 FL	*155.20 FL
6	1		*AIRCON CONDENSER ALUMINIUM PIPE	Not Necessary	332.10 FL	*- FL
7	1		*AIRCON DISCHARGE PIPE	Not Necessary	561.70 FL	*- FL
8	1		*FRT ABS PUMP	Cracked	6,312.70 FL	*3,978.90 FL
9	1		*FRT ABS PUMP WIRE HARNESS	Not Necessary	446.90 FL	*- FL
10	1		*FRT SHOCK ABSORBER RH	Not Necessary	384.90 FL	*- FL
11	1		*FRT KNUCKLE ARM RH	Not Necessary	453.30 FL	*- FL
12	1		*FRT LOWER ARM RH	Not Necessary	422.90 FL	*- FL
13	1		*FRT WHEEL HUB RH	Not Necessary	222.50 FL	*- FL
14	1		*FRT WHEEL HUB BEARING RH	Not Necessary	162.90 FL	*- FL
15	1		*FRT DRIVE SHAFT RH	Not Necessary	1,536.90 FL	*- FL
16	1		*FRT LINKAGE RH	Not Necessary	122.60 FL	*- FL
17	1		*FRT LOWER ARM BALL JOINT RH	Not Necessary	224.10 FL	*- FL
18	1		*FRT SPORTS RIM RH	Cut	2,126.70 FS	*800.00 FS
19	1		*FRT CROSSMEMBER	Bent	2,315.50 FL	*2,315.50 FL
20	1		*ENGINE MOUNTING FRT	Not Necessary	173.30 FL	*- FL
21	1		*ENGINE MOUNTING REAR	Not Necessary	145.40 FL	*- FL
22	1		*ENGINE MOUNTING LH	Not Necessary	314.40 FL	*- FL
23	1		*ENGINE MOUNTING RH	Not Necessary	296.20 FL	*- FL
24	1		*ENGINE UNDER COVER	Not Necessary	130.70 FL	*- FL
25	1		*FRT SHOCK ABSORBER LH	Not Necessary	384.90 FL	*- FL
26	1		*FRT KNUCKLE ARM LH	Not Necessary	453.30 FL	*- FL
27	1		*FRT LOWER ARM LH	Not Necessary	422.90 FL	*- FL
28	1		*FRT WHEEL HUB LH	Not Necessary	222.50 FL	*- FL
29	1		*FRT WHEEL HUB BEARING LH	Not Necessary	162.90 FL	*- FL
30	1		*FRT DRIVE SHAFT LH	Not Necessary	1,536.90 FL	*- FL
31	1		*FRT SPORTS RIM LH	Not Necessary	2,835.60 FL	*- FL
32	1		*FRT SPORTS RIM COVER LH	Not Necessary	130.70 FL	*- FL
33	1		*FRT LOWER ARM BALL JOINT LH	Not Necessary	224.10 FL	*- FL
34	1		*SET FRT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
35	1		*SET FRT BUMPER SENSOR	Damaged	250.00 FS	*200.00 FS
36	1		*FRT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
37	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	40.00 FS	*40.00 FS
38	1		*SET FRT FENDER COWLING CLIPS LH	Necessary	40.00 FS	*40.00 FS
39	1		*SET FRT ROCKER PANEL GARNISH RH CLIPS	Necessary	40.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRT TYRE RH	Not Necessary	380.00 FS	*- FS
41	1		*SET ENGINE UNDER COVER CLIP	Necessary	40.00 FS	*40.00 FS
42	1		*FRT TYRE LH	Not Necessary	380.00 FS	*- FS
43	1		*RADIATOR COOLANT	Necessary	100.00 FS	*40.00 FS
44	1		*FRT BUMPER	Distorted	801.70 FL	*801.70 FL
45	1		*FRT BUMPER REINFORCEMENT	Bent	908.60 FL	*549.10 FL
46	1		*FRT BUMPER SPONGE	Cracked	145.60 FL	*145.60 FL
47	1		*FRT FOG LAMP LH	Cut	370.80 FL	*370.80 FL
48	1		*FRT FOG LAMP RH	Cracked	370.80 FL	*370.80 FL
49	2		*FRT TOWING COVER	Deformed	42.40 FL	*42.40 FL
50	2		*FRT BUMPER SIDE RETAINER	Necessary	137.40 FL	*137.40 FL
51	1		*FRT NUMBER PLATE BASE	Cracked	117.10 FL	*117.10 FL
52	1		*FRT SUPPORT PANEL	Distorted	1,072.70 FL	*867.90 FL
53	1		*FRT GRILLE	Cracked	551.40 FL	*551.40 FL
54	1		*FRT GRILLE EMBLEM	Necessary	72.10 FL	*72.10 FL
55	1		*FRT SUPPORT TOP GARNISH	Not Necessary	107.60 FL	*- FL
56	1		*BONNET	Dented	1,508.70 FL	*1,366.10 FL
57	2		*BONNET HINGE	Not Necessary	135.40 FL	*- FL
58	1		*FRT FENDER RH	Distorted	922.10 FL	*922.10 FL
59	1		*FRT FENDER COWLING RH	Torn	362.70 FL	*362.70 FL
60	1		*FRT FENDER SIGNAL LAMP RH	Not Necessary	66.10 FL	*- FL
61	1		*FRT FENDER COWLING LH	Missing	362.70 FL	*362.70 FL
62	1		*FRT DOOR RH	Deformed	1,043.70 FL	*1,043.70 FL
63	1		*FRT DOOR TOP HINGE RH	Not Necessary	75.10 FL	*- FL
64	1		*FRT DOOR BOTTOM HINGE RH	Not Necessary	85.60 FL	*- FL
65	1		*FRT DOOR PROTECTOR RH	Deformed	251.70 FL	*251.70 FL
66	1		*FRT DOOR RUBBER RH	Not Necessary	251.70 FL	*- FL
67	1		*FRT ROCKER PANEL GARNISH RH	Deformed	664.70 FL	*664.70 FL
68	1		*FRT WIPER WATER TANK	Deformed	176.70 FL	*176.70 FL
69	1		*FRONT WIPER WATER TANK MOTOR	Damaged	199.70 FL	*199.70 FL
70	1		*HEADLAMP RH	Smashed	1,921.80 FL	*1,921.80 FL
71	1		*HEAD LAMP BALAST RH	Missing	534.70 FL	*534.70 FL
72	1		*HEAD LAMP BULB (HID)	Smashed	363.10 FL	*363.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	43,067.90	23,124.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	9,895.30	5,458.60
Total Parts (\$\$)	33,172.60	17,665.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	100.00	80.00
2	TO SPRAY UNDERSEAL	New	150.00	0.00
3	TO REMOVE AND REFIT ABS PUMP	New	300.00	80.00
4	TO REMOVE AND REFIT UNDERCARRIAGE	New	700.00	600.00
5	TO REMOVE AND REFIT ENGINE	New	800.00	0.00
6	TO REMOVE AND REFIT ENGINE MOUNTING	New	300.00	0.00
7	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
8	TO REFILL AIRCON GAS	New	120.00	100.00
9	TO PERFORM DIAGNOSTIC TESTS & PROGRAMME ABS FAULT LIGHT	New	280.00	100.00
10	(FRONT) TO SPRAY PAINTING	New	2,200.00	1,400.00
11	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	2,600.00	1,400.00
12	TO CHECK WIRING	New	300.00	0.00
Gross Labour Cost (S\$)			7,970.00	3,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >