

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

Estimate No: EST1800193
Date: 26 Jun 2018

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Veh Reg No: SKJ8943T
Make/Model: TOYOTA HARRIER 2.4A
Chassis No: ACU300045458
Reg. Date: 27/04/2006
Your Ref No: SHC2635U

Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Vic

Estimate Repair Cost to Vehicle No: SKJ8943T

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT BUMPER <i>Distorted.</i>	801.70	✓
2	1 PC FRT BUMPER REINFORCEMENT <i>Bent</i>	908.60	✓ 549.10
3	1 PC FRT BUMPER SPONGE <i>crushed.</i>	145.60	✓
4	1 PC FRT FOG LAMP LH <i>at</i>	370.80	✓
5	1 PC FRT FOG LAMP RH <i>crushed.</i>	370.80	✓
6	2 PCS FRT TOWING COVER <i>Deformed.</i>	42.40	✓
7	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	137.40	✓
8	1 PC FRT NUMBER PLATE BASE <i>crushed.</i>	117.10	✓
9	1 PC FRT SUPPORT PANEL <i>Distorted.</i>	1,072.70	✓ 867.90
10	1 PC FRT GRILLE <i>crushed</i>	551.40	✓
11	1 PC FRT GRILLE EMBLEM <i>new</i>	72.10	✓
12	1 PC FRT SUPPORT TOP GARNISH <i>new new</i>	107.60	x
13	1 PC BONNET <i>Dented</i>	1,508.70	✓ 1366.10
14	2 PCS BONNET HINGE <i>new new</i>	135.40	x
15	1 PC FRT FENDER RH <i>Distorted</i>	922.10	✓
16	1 PC FRT FENDER COWLING RH <i>torn</i>	362.70	✓
17	1 PC FRT FENDER SIGNAL LAMP RH <i>new new</i>	66.10	x
18	1 PC FRT FENDER COWLING LH <i>missing</i>	362.70	✓
19	1 PC FRT DOOR <i>LH RH Dented</i>	1,043.70	✓
20	1 PC FRT DOOR TOP HINGE <i>LH RH</i>	75.10	x
21	1 PC FRT DOOR BOTTOM HINGE <i>LH RH</i>	85.60	x
22	1 PC FRT DOOR PROTECTOR <i>LH RH Deformed.</i>	251.70	✓
23	1 PC FRT DOOR RUBBER <i>LH RH new new</i>	251.70	x
24	1 PC FRT ROCKER PANEL GARNISH RH <i>Deformed</i>	664.70	✓
25	1 PC FRT WIPER WATER TANK <i>Deformed</i>	176.70	✓
26	1 PC FRONT WIPER WATER TANK MOTOR <i>Damaged</i>	199.70	✓
27	1 PC HEADLAMP RH <i>smashed.</i>	1,921.80	✓
28	1 PC HEAD LAMP BALAST RH <i>missing.</i>	534.70	✓
29	1 PC HEAD LAMP BULB (HID) <i>smashed.</i>	363.10	✓

1,000.00

1,000.00

1,000.00

1,000.00

1,000.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417833
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Estimate No: EST1800193
Date: 26 Jun 2018

Veh Reg No: SKJ8943T
Make/Model: TOYOTA HARRIER 2.4A
Chassis No: ACU300045458
Reg. Date: 27/04/2006
Your Ref No: SHC2635U

Estimate Repair Cost to Vehicle No: SKJ8943T

Quantity	Description	List Price	Amount
		S\$	S\$
30	1 PC HEAD LAMP BULB (HIGH BEAM) <i>smashed.</i>	70.60 ✓	
31	1 PC HEADLAMP LH <i>ut</i>	1,921.80 ✓	
32	1 PC RADIATOR <i>Ne new</i>	1,173.50 X.	
33	1 PC AIRCON CONDENSER <i>Bent</i>	1,702.90 ✓	1196.40
34	2 PCS AIRCON CONDENSER SIDE GARNISH <i>Defend</i>	155.20 ✓	
35	1 PC AIRCON CONDENSER ALUMINIUM PIPE <i>Ne new</i>	332.10 X.	
36	1 PC AIRCON DISCHARGE PIPE <i>Ne new</i>	561.70 X.	
37	1 PC FRT ABS PUMP <i>Crushed</i>	6,312.70 ✓	3978.50
38	1 PC FRT ABS PUMP WIRE HARNESS <i>Ne new</i>	446.90 X.	
39	1 PC FRT SHOCK ABSORBER RH	384.90 X.	
40	1 PC FRT KNUCKLE ARM RH	453.30 X.	
41	1 PC FRT LOWER ARM RH	422.90 X.	
42	1 PC FRT WHEEL HUB RH	222.50 X.	
43	1 PC FRT WHEEL HUB BEARING RH	162.90 X.	
44	1 PC FRT DRIVE SHAFT RH	1,536.90 X.	
45	1 PC FRT LINKAGE RH	122.60 X.	
46	1 PC FRT LOWER ARM BALL JOINT RH	224.10 X.	
47	1 PC FRT SPORTS RIM RH <i>ut</i>	2,835.50	800(SN)
48	1 PC FRT CROSSMEMBER <i>Bent</i>	2,315.50 ✓	
49	1 PC ENGINE MOUNTING FRT	173.30 X.	
50	1 PC ENGINE MOUNTING REAR	145.40 X.	
51	1 PC ENGINE MOUNTING LH	314.40 X.	
52	1 PC ENGINE MOUNTING RH	296.20 X.	
53	1 PC ENGINE UNDER COVER	130.70 X.	
54	1 PC FRT SHOCK ABSORBER LH	384.90 X.	
55	1 PC FRT KNUCKLE ARM LH	453.30 X.	
56	1 PC FRT LOWER ARM LH	422.90 X.	
57	1 PC FRT WHEEL HUB LH	222.50 X.	
58	1 PC FRT WHEEL HUB BEARING LH	162.90 X.	
59	1 PC FRT DRIVE SHAFT LH	1,536.90 X.	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Estimate No: EST1800193

Date: 26 Jun 2018

Veh Reg No: SKJ8943T

Make/Model: TOYOTA HARRIER 2.4A

Chasis No: ACU300045438

Reg. Date: 27/04/2006

Your Ref No: SHC2635U

Estimate Repair Cost to Vehicle No: SKJ8943T

Quantity	Description	List Price	Amount
60	1 PC FRT SPORTS RIM LH <i>Neu</i> 208344	2,835.60 <i>X</i>	SS
61	1 PC FRT SPORTS RIM COVER LH <i>Neu</i> 1562580	130.70 <i>X</i>	
62	1 PC FRT LOWER ARM BALL JOINT LH <i>Neu</i> 801:800	224.10 <i>X</i>	
		42,416.80	
	Less 25%	10,604.20	31,812.81
Special Net			
63	1 SET FRT BUMPER CLIPS <i>Neu</i>	40.00 <i>✓</i>	
64	1 SET FRT BUMPER SENSOR <i>Damaged</i>	250.00 <i>200</i>	
65	1 PC FRT NUMBER PLATE <i>Bank</i>	50.00 <i>✓</i>	
66	1 SET FRT FENDER COWLING CLIPS RH <i>3 neu</i>	40.00 <i>✓</i>	
67	1 SET FRT FENDER COWLING CLIPS LH	40.00 <i>✓</i>	
68	1 SET FRT ROCKER PANEL GARNISH RH CLIPS <i>Neu</i>	40.00 <i>✓</i>	
69	1 PC FRT TYRE RH <i>Not neu</i> 490	380.00 <i>X</i>	
70	1 SET ENGINE UNDER COVER CLIP <i>Neu</i>	40.00 <i>✓</i>	
71	1 PC FRT TYRE LH <i>Not neu</i>	380.00 <i>X</i>	
72	1 PC RADIATOR COOLANT <i>Neu</i>	100.00 <i>40</i>	
		1,360.00	1,360.00
Labour			
73	1 TOWING	100.00 <i>60</i>	
74	1 TO SPRAY UNDERSEAL	150.00 <i>X</i>	
75	1 TO REMOVE AND REFIT ABS PUMP	300.00 <i>80</i>	
76	1 TO REMOVE AND REFIT UNDERCARRIAGE	700.00 <i>600</i>	
77	1 TO REMOVE AND REFIT ENGINE <i>Neu</i>	800.00 <i>X</i>	
78	1 TO REMOVE AND REFIT ENGINE MOUNTING <i>Neu</i>	300.00 <i>X</i>	
79	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>80</i>	
80	1 TO REFILL AIRCON GAS	120.00 <i>100</i>	
81	1 TO PERFORM DIAGNOSTIC TESTS & PROGRAMME ABS FAULT LIGHT	280.00 <i>100</i>	
82	1 (FRONT) TO SPRAY PAINTING	2,200.00 <i>1400</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/06/2018
TP Veh Reg No: SHC2635U

Estimate No: EST1800193

Date: 26 Jun 2018

Veh Reg No: SKJ8943T

Make/Model: TOYOTA HARRIER 2.4A

Chasis No: ACU300045458

Reg. Date: 27/04/2006

Your Ref No: SHC2635U


Estimate Repair Cost to Vehicle No: SKJ8943T

Quantity	Description	List Price	Amount
		SS	SS
83	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,600.00 1400.	
84	1 TO CHECK WIRING 3820	300.00	
		7,970.00	7,970.00
	Total		SS 41,142.81
	Add GST @ 7%		2,880.00
	Total Amount Payable		SS 44,022.81

TOTAL: SINGAPORE DOLLAR FORTY FOUR THOUSAND TWENTY TWO AND CENTS EIGHTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling, total 20735.80
L/S 26/06/18- H/S 15.5K
18 Days. (Nett Value)

15.5K

18 Days