

Continued

ASS. REC. BY:

REF: CS/FGI 18011692/180322

Specialist's Name:

Surveyor:

Sathya

ASSIGNMENT (Office)

From (Person):

Ye Pei Li

of

FGI

Date/Time:

26/6/18 @ 4:19pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHF 163L

Insured:

SJB 2060J

at Workshop m/s

SMRT

Tel:

6866 2671

of

Go woodlands Ind. Park E4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/06/2018

CA / REV / REF. / REV 24 HRS

'up'

Date/Time:

9:03am @ 27/6/18

Person Contacted:

Shunji

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHF 163L - NA/CTI 18011559/24

D.O.A: 25/6/2018

SJB 2060J - X

28/06/18

@ 17:09 pm. revised PA to Pei Li via email.

ASSIGNMENT

From: Date: 27/6/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHF163L

at Workshop m/s SMRT

of 60 woodlands Ind. Park E 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bail. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHF 163 L Yr Regn: NOV / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry (Tax) / Prime Mover /

Truck / Trailer or

Make Toyota Prius 4 c.c. 1798

Colour maroon A/C: Insured / Std / NI / NA

Sp. Reading 82123 T/Radio: Insured / Std / NI / NA

Eng/No: 2ZRS100799

C/No: JTDKB3FU303573455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken (rear), Yokohama (front)

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/6/2018 D.O.I. 27/6/2018

Survey held at SMRT

Des. of Damages (Fr) / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

(£ 2,930.22 Red - 27%)

TAX/06/18/2113

Sat Ray
Pls see me.
(re-survey 17 photos photo)

Ergo

- SLH 4583Z

- SSB 2060 I

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

25/07/18

Typist

☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 7,088.15 P/P)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$) \$ + RS \$

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

Survey Fee: 350

Transportation:

Photos

Others

TOTAL

350

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 17 July 2018 5:54 PM
To: Sathya Sai (LKK Auto)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: RE: SHF163L

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sathya Sai (LKK Auto) [mailto:SathyaSai@lkkauto.com]
Sent: Tuesday, 17 July 2018 11:18 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: RE: SHF163L

Good Day,

Please refer to attachment for finalisation.

Thank you

Best Regards,
Sathya Sai | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9807 2012 | Email: SathyaSai@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 16 July, 2018 5:06 PM
To: Sathya Sai (LKK Auto)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: SHF163L

Hi Sathya,

Attached herewith the repair estimate of SHF 163L having Case No: TAX/06/18/2113.

There is no change to the approved amount of \$7,088.15 @ 7 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 16 July 2018 3:10 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 28 June 2018 5:09 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; assignments@lkkauto.com
Subject: RE: SJB2060J / TP : SHF163L/LKK / DOA : 25/06/2018
Attachments: SHF 163L - Preli Advise.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SHF 163L.

Kindly provide us the claim reference no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 27 June 2018 9:08 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: RE: SJB2060J / TP : SHF163L/LKK / DOA : 25/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 26 June 2018 4:19 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SJB2060J / TP : SHF163L/LKK / DOA : 25/06/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 26 June 2018 4:19 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SJB2060J / TP : SHF163L/LKK / DOA : 25/06/2018
Attachments: OI - 3RD VEH SJB2060J - SAS.pdf; SHF163L - SAS.pdf; 1ST VEH SLH4583Z - SAS.pdf; SHF163L - ESTIMATE.pdf; SHF163L - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SHANTI @ 6866 2671/2

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 28 June 2018

Our Ref: CS/EGII8011692/Vsd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHF 163L .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/06/2018 at the premises of M/s SMRT Automotive Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,074.37</u>
Revised Estimate Amount	: S\$ <u>4,245.91</u>
"Check" Items Amount	: S\$ <u>5,809.13</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Sathya Sai
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/06/2018 15:21
Date Of Accident	25/06/2018 08:50
Exact Location Of Accident	TPE TOWARDS AIRPORT (BEFORE PASIR IRS AVE 12)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF163L
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAY BEH HWA
NRIC No	S2014682F
Date Of Birth	26/08/1949
Occupation	OUTDOOR
Date Of Driving Pass	13/04/1972
Driving Experience	46 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG TPE TOWARDS AIRPORT (BEFORE PASIR RIS AVE 12) WITH ONE PASSENGER ON BOARD. A VEHICLE SLH4583Z WHICH WAS INFRONT OF MY TAXI CAME TO A HALT. I APPLIED MY BRAKE TO STOP AND MANAGED TO STOP IN TIME. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJB2060J HAD COLLIDED ONTO THE REAR OF MY TAXI AND THE IMPACT PUSHED MY TAXI FORWARD AND MY TAXI TOUCHED ONTO THE REAR OF THE FRONT VEHICLE SLH4583Z. WHEN I ALIGHTED I REALISED THAT IT WAS A CHAIN COLLISION INVOLVING 5 VEHICLES INCLUDING MINE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

Details of Witness 1

Name	TAN IK LOONG NICHOLAS
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJB2060J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver JJOE CAI
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLH4583Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)






DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SGC627T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

PAGE 15 AVE 12

25/6/2018



C  SLH 4583Z
 A  SHF 163L
 B  SJ8 2060J
 D  CNXNo
 E  SGC 607T

[illegible]

DECLARATION

I/We declare that foregoing particulars are true in every respect.



Policyholder's Signature _____

Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Name: _____

NRIC/FIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SMRT Accident Vehicle Repair Estimates

C-117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF163L
 Ref. No : TAX/06/18/2113
 Reg. Date : 01/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TAY BEH HWA
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 25/06/2018 08:50:00 AM
 Accident Reported Date / Time : 25/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096699
 Special Instruction to ARC, if any :
 SJB2060J
 Prepared Date : 25/06/2018 02:59:14 PM



Sathya Sai
27/6/2018

Sathya.Sai@lkkauto.com

5 days.

29/6/18.

- Part by Part Repair
- Question mark item photo
- Photo before paint

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303573455

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 1,854.00	0.00
Total Material Charges	: 10,018.37	10,018.37
Other Charges	: 850.00	0.00
TOTAL	: 14,074.37	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	0.00 5 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 26/06/2018 01:18:55 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/06/2018 01:18:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER CR ✓	1	495.50	25.00	371.62	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER NEC ✓	10	1.50	25.00	11.25	Replace	Replace	No
5211447190			BRACKET, FR BUMPER 2 ✓ BT	1	99.80	25.00	74.85	Replace	Replace	No
			NUMBER PLATE CUT ✓	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE BT ✓	1	25.00	0.00	25.00	Replace	Replace	No
7531047060			EMBLEM ASSY 8 X 10	1	87.10	25.00	65.32	Replace	Replace	No
5310147080			GRILLE SUB-ASSY X ✓	1	335.60	25.00	251.70	Replace	Replace	No
5261147140			ABSORBER, FR BUMPER X 10	1	70.30	25.00	52.72	Replace	Replace	No
5202147110			REINFORCEMENT FRONT UPPER 3 X 10	1	691.10	25.00	518.32	Replace	Replace	No
5261847090			ABSORBER, FR BUMPER LOWER 9 X 10	1	117.00	25.00	87.75	Replace	Replace	No
5213247010			REINFORCEMENT FRONT LOWER 2 X 10	1	238.50	25.00	178.87	Replace	Replace	No
5210347010			EXTENSION SUB-ASSY, LH X 10	1	116.30	25.00	87.22	Replace	Replace	No
5210247020			EXTENSION SUB-ASSY, RH X 10	1	116.30	25.00	87.22	Replace	Replace	No
5211647050			SUPPORT, FR BUMPER LH 8 X 10	1	82.30	25.00	61.72	Replace	Replace	No
5211547050			SUPPORT, FR BUMPER RH 7 X 10	1	76.90	25.00	57.67	Replace	Replace	No
5215947913			COVER, RR BUMPER ASSY 8 X 10	1	423.90	25.00	317.92	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER NEC ✓	10	1.50	25.00	11.25	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 8 X 10	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 8 X 10	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 8 X 10	2	3.80	25.00	5.70	Replace	Replace	No
5219147010			SEAL, RR BUMPER ARM, RH & LH 8 X 10	2	11.00	25.00	16.50	Replace	Replace	No
5259147010			SEAL, RR BUMPER, RH 7 X 10	1	85.20	25.00	63.90	Replace	Replace	No
5256547910			FILLER, RR BUMPER, RH X 10	1	119.90	25.00	89.92	Replace	Replace	No
			SENSOR REVERSE ✓ DM	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER NEC ✓	2	60.00	0.00	120.00	Replace	Replace	No
20234700			REAR BUMPER REINFORCEMENT BT ✓	1	318.80	25.00	239.10	Replace	Replace	No
24534700			GUARD, RR BUMPER, LOWER DIS ✓	1	558.30	25.00	418.72	Replace	Replace	No
24614700			PAD, RR BUMPER, CTR 8 X 10	1	2.20	25.00	1.65	Replace	Replace	No
15814700			LENS & BODY ASSY, RR BUMPER, RH X 10	3	486.80	10.00	1,314.36	Replace	Replace	No

Part Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
8158147010	LENS & BODY ASSY, RR BUMPER, RH	1 X ^{an}	486.80	10.00	438.12	Replace	Replace	No
8218347020	WIRE, LUGGAGE ROOM	1 K ^{NX}	143.50	10.00	129.15	Replace	Replace	No
8999730100	ANTENNA, ELECTRICAL KEY	1 2X ^{an}	60.30	10.00	54.27	Replace	Replace	No
6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1 2/0 ^t	929.60	25.00	697.20	Replace	Replace	No
7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1 2/0 ^t	891.20	25.00	668.40	Replace	Replace	No
6935047050	TAIL GATE LOCK ASSY, BACK DOOR	1 2X ^{an}	452.10	10.00	406.89	Replace	Replace	No
6932147010	TAIL GATE LOCK COVER, BACK DOOR	1 2X ^{an}	25.30	25.00	18.97	Replace	Replace	No
6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	1 2/0 ^t	360.70	25.00	270.52	Replace	Replace	No
6943052050	TAIL GATE STRIKER ASSY, BACK DOOR	1 X ^{an}	24.90	25.00	18.67	Replace	Replace	No
7540348010	EMBLEM SUB-ASSY, REAR	1 2/0 ^t	46.30	25.00	34.72	Replace	Replace	No
7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1 X ^{an}	52.30	25.00	39.22	Replace	Replace	No
7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1 X ^{an}	52.30	25.00	39.22	Replace	Replace	No
COMMO N	SMRT LOGO	1 X ^{an}	7.80	0.00	7.80	Replace	Replace	No
COMMO N	STICKER DECAL 6555 8888	1 X ^{an}	21.60	0.00	21.60	Replace	Replace	No
5830747030	END PANEL SUB-ASSY, BODY LOWER BACK	1 2/0 ^t	629.80	25.00	472.35	Replace	Replace	No
3471847030C0	END PANEL, COVER, DECK TRIM SERVICE HOLE	1 2/0 ^t	47.00	25.00	35.25	Replace	Replace	No
3471647130C0	END PANEL, COVER, DECK TRIM, REAR	1 2/0 ^t	122.80	25.00	92.10	Replace	Replace	No
COMMO N	SEALANT SIKAFLEX	1 X ^{an}	37.00	0.00	37.00	Replace	Replace	No
3835047010	REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	2 2/0 ^t	56.70	25.00	85.05	Replace	Replace	No
3831147110	SPARE TYRE PANEL, PAN, REAR FLOOR	1 2/0 ^t	564.80	25.00	423.60	Replace	Replace	No
384154710C2	BOARD, REAR FLOOR, NO.1	1 2/0 ^t	502.20	25.00	376.65	Replace	Replace	No
49974700	BOX, DECK FLOOR, LH	1 2/0 ^t	303.40	25.00	227.55	Replace	Replace	No
49954700	BOX, DECK FLOOR, RH	1 2/0 ^t	304.00	25.00	228.00	Replace	Replace	No
83984700	COVER, REAR FLOOR UNDER, RH	1 2/0 ^t	169.50	25.00	127.12	Replace	Replace	No
62594700	COVER, REAR FLOOR UNDER CENTER	1 2/0 ^t	222.60	25.00	166.95	Replace	Replace	No
04671706A0	CLIP, FLOOR UNDER COVER, NO.1	10 2/0 ^t	2.60	25.00	19.50	Replace	Replace	No

Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
90467170 27C0	CLIP, FLOOR UNDER COVER, NO.2 X 00	7 10	3.20	25.00	24.00	Replace	Replace	No
65637470 60	LINER, REAR FENDER, RH X 00	1	135.80	25.00	101.85	Replace	Replace	No
TOTAL MATERIALS						10,018.47	10,018.37	
TOTAL MATERIALS(Discounted)						10,018.37	10,018.37	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SHF163L		
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model :	PRIUS HYBRID 1.8 CVT		
Chassis No. :	JTDKB3FU303573455		
Propellant :	Petrol-Electric		
Engine No. :	2ZRS100799		
Motor No. :	1NMS100799		
Engine Capacity :	1798 cc		
Power Rating :	53.0 kW		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight :	1790 kg		
Unladen Weight :	1375 kg		
Year Of Manufacture :	2017		
Original Registration Date :	01 Nov 2017		
Lifespan Expiry Date :	31 Oct 2025		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$33,596.00		
COE Expiry Date :	31 Oct 2025		
Road Tax Expiry Date :	31 Oct 2018		
PARF Eligibility Expiry Date :	31 Oct 2025		
Inspection Due Date :	31 Oct 2018		
Intended Transfer Date :	28 Jun 2018		
CO2 Emission :	87.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$27,610.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK Print

Vsd3

3-7-18 / 12:57

3-7-18 / 16:57

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

27-6-18 / 16:57

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF163L
 Ref. No : TAX/06/18/2113
 Reg. Date : 01/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TAY BEH HWA
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 25/06/2018 08:50:00 AM
 Accident Reported Date / Time : 25/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sathya Sai
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle Issued? : No
 Accident Repair Job Card No : 000024096699
 Special Instruction to ARC, if any :
 SJB2060J - ERGO r/p
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR Sathya Sai (LKK)
 & Email : sathyasai@lkkauto.com HP: 98072012
 Prepared Date : 25/06/2018 02:59:14 PM



Recording Camera

Radio Antenna

1st witness2nd witness☐☐

Date

Date

27-6-18

82124

1/4 1/2 3/4
 1/4 1/2 3/4

QC 617/18 in. sep. p. 52

Supplementary

to the supplementary part 13/18

82185

LEE BUENG AUTO PTE LTD

Vehicle Return Date:

6-7-2018

Vehicle Return Time:

13:50

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303573455

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	1,260.00
Total Spray Painting Charges	: 1,854.00	880.00
Total Material Charges	: 9,056.89	4,538.15
Other Charges	: 1,030.00	410.00
TOTAL	: 13,461.89	7,088.15
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	7.00 ✓
Prepared / Adjusted By	:	SATHYA SAI (LKK)
Arc / Surveyor Sign Off Date	: 26/06/2018 01:18:55 PM	27/06/2018 04:57:12 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/06/2018 01:18:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1807-0330

Invoice No :

Quotation Date : 14/7

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	0.00 200
TO REPAIR REAR PORTION	1,014.00	0.00 200 1060
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY TAIL GATE	378.00	0.00 X 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 2X
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X 80
Total Spray Painting & Panel Beating	1,854.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 120
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	850.00	0.00

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	200.00 ✓
TO REPAIR REAR PORTION	1,183.00	1,060.00 ✓
Total Labour	1,521.00	1,260.00 ✓

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 ✓
TO REPSRAY REAR BUMPER	378.00	200.00 ✓
TO RESPRAY TAIL GATE	378.00	200.00 ✓
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 ✓
TO RESPRAY REAR PANEL	180.00	100.00 ✓
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	80.00 ✓
Total Spray Painting & Panel Beating	1,854.00	880.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	50.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	250.00	120.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	60.00 ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	180.00	100.00 ✓
Total Other Costs	1,030.00	410.00 ✓

bb05

1220140

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No ✓	CRK
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50 (15)	25.00	11.25	Replace	Replace	No ✓	NEC
5211447190			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Replace	No ✓	OT
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No ✓	CUT
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace S	No ✓	BT
7531047060			EMBLEM ASSY FRONT	0	87.10	25.00	0.00	Replace	Not given	No X	NN
5310147080			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace S	No ✓	CUT
5261147140			ABSORBER, FR BUMPER	0	70.30	25.00	0.00	Replace	Not given	No X	NN
5202147110			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.33	Replace	Check	No X	
5261847090			ABSORBER, FR BUMPER LOWER	1	117.00	25.00	87.75	Replace	Check	No X	
5213247010			REINFORCEMENT FRONT LOWER	1	238.50	25.00	178.88	Replace	Check	No X	
5210347010			EXTENSION SUB-ASSY, LH	0	116.30	25.00	0.00	Replace	Not given	No X	
5210247020			EXTENSION SUB-ASSY, RH	0	116.30	25.00	0.00	Replace	Not given	No X	NN
5211847050			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.73	Replace	Check	No X	
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.68	Replace	Check	No X	
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.95	Replace	Replace S	No ✓	CRK
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50 (15)	25.00	11.25	Replace	Replace	No ✓	NEC
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80 (760)	25.00	5.70	Replace	Check	No X	NN
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80 (760)	25.00	5.70	Replace	Check	No X	
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80 (760)	25.00	5.70	Replace	Check	No X	
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00 (22)	25.00	16.50	Replace	Check	No X	
5259147050			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Check	No X	
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.95	Replace	Replace S	No ✓	CUT
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓	DMG
			PIXEL STICKER	2	60.00 (120)	0.00	120.00	Replace	Replace	No ✓	NEC
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No ✓	BT
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No ✓	DIS
5246147010			PAD, RR BUMPER, CTR	1	2.20	25.00	1.65	Replace	Check	No X	NN
8158147010			LENS & BODY ASSY, RR BUMPER, RH	3	486.80 (1460.40)	10.00	1,314.36	Replace	Check	No X	
8158147010			LENS & BODY ASSY, RR BUMPER, RH	0	486.80	10.00	0.00	Replace	Not given	No X	

6112

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
8218347020			WIRE, LUGGAGE ROOM	0	143.50	10.00	0.00	Replace	Not given	No X	} NF
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Check	No X	
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace S	No ✓	DT
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No ✓	CRK
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Check	No X	} NN
6932147010			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.00	18.98	Replace	Check	No X	
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace	No ✓	WT
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	0	24.90	25.00	0.00	Replace	Not given	No X	NN
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.73	Replace	Replace S	No ✓	} NE
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.23	Replace	Replace S	No ✓	
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.23	Replace	Replace S	No ✓	
	COMMO N		SMRT LOGO	0	7.80	0.00	0.00	Replace	Not given	No X	} NN
	COMMO N		STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No X	
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace S	No ✓	DT
6471847080C0			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Check	No X	} NN
6471647130C0			END PANEL, COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Check	No X	
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No X	
5835047010			REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	2	56.70 (113.40)	25.00	85.05	Replace	Replace	No ✓	BT
5831147130			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Check	No X	} NN
5841547110C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Check	No X	
6499747060			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Check	No X	
6499547050			BOX, DECK FLOOR, RH	1	304.00	25.00	228.00	Replace	Check	No X	
5839847050			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.13	Replace	Check	No X	
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Check	No X	
9046717026A0			CLIP, FLOOR UNDER COVER, NO.1	10	2.60 (26)	25.00	19.50	Replace	Check	No X	
9046717027C0			CLIP, FLOOR UNDER COVER, NO.2	10	3.20 (32)	25.00	24.00	Replace	Check	No X	

6182.40

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6563747060			LINER, REAR FENDER, RH	0	135.80	25.00	0.00	Replace	Not given	No <i>X</i>
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <i>S</i>	No <i>/</i>
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace <i>S</i>	No <i>/</i>
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace <i>S</i>	No <i>/</i>
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>S</i>	No <i>/</i>
TOTAL MATERIALS							247	9,056.92	4,538.15	
TOTAL MATERIALS(Discounted)								9,056.89	4,538.15	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
5216947020		COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
7557147010		TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No
7557547051		TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace	No
	COMMON	SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						85.14			

4538.15 ✓
+ 1260.00 ✓
+ 1290.00 ✓

7088.15 ✓ e 7 days

confirmed




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18011692/Dsd3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 03-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 2060J	Veh. Inspected	SHF 163L	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1801209	Excess (\$)	0.00	
Assign From		Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU303573455	Colour	MAROON	
Odometer	82123	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2018	Inspection Date	27/06/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 163L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, FR BUMPER (DISC 25%)	CRACKED	495.60	371.62
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	BRACKET, FR BUMPER (DISC 25%)	DENTED	99.80	74.85
1	GRILLE SUB-ASSY (DISC 25%)	CUT	335.60	251.70
1	COVER, RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.92
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	FILLER, RR BUMPER, RH (DISC 25%)	CUT	119.90	89.92
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DISTORTED	558.30	418.72
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	DENTED	929.60	697.20
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	CRACKED	891.20	668.40
1	TAIL GATE WEATHERSTRIP, BACK DOOR (DISC 25%)	CUT	360.70	270.52
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	END PANEL SUB-ASSY, BODY LOWER BACK (DISC 25%)	DENTED	629.80	472.35
2	REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH @\$56.70 (DISC 25%)	BENT	113.40	85.05
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	CUT	14.80	11.10
1	TAIL GATE MOULDING GLASS, BACK DOOR (DISC 25%)	NECESSARY	29.70	22.27
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	19.70	14.77
1	NUMBER PLATE (SN)	CUT	35.00	35.00
1	NUMBER PLATE FRAME (SN)	BENT	25.00	25.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	EMBLEM ASSY FRONT	NOT NECESSARY	87.10	-
1	ABSORBER, FR BUMPER	NOT NECESSARY	70.30	-

Report Ref No. CS/EG118011692/Dsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REINFORCEMENT FRONT UPPER	NOT NECESSARY	691.10	-
1	ABSORBER, FR BUMPER LOWER	NOT NECESSARY	117.00	-
1	REINFORCEMENT FRONT LOWER	NOT NECESSARY	238.50	-
1	EXTENSION SUB-ASSY, LH	NOT NECESSARY	116.30	-
1	EXTENSION SUB-ASSY, RH	NOT NECESSARY	116.30	-
1	SUPPORT, FR BUMPER LH	NOT NECESSARY	82.30	-
1	SUPPORT, FR BUMPER RH	NOT NECESSARY	76.90	-
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	SEAL, RR BUMPER, RH	NOT NECESSARY	85.20	-
1	PAD, RR BUMPER, CTR	NOT NECESSARY	2.20	-
3	LENS & BODY ASSY, RR BUMPER, RH @\$486.80	NOT NECESSARY	1,460.40	-
1	LENS & BODY ASSY, RR BUMPER, RH	NOT NECESSARY	486.80	-
1	WIRE, LUGGAGE ROOM	NOT NECESSARY	143.50	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	TAIL GATE LOCK ASSY, BACK DOOR	NOT NECESSARY	452.10	-
1	TAIL GATE LOCK COVER, BACK DOOR	NOT NECESSARY	25.30	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	NOT NECESSARY	24.90	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	SPARE TYRE PANEL, PAN, REAR FLOOR	NOT NECESSARY	564.80	-
1	BOARD, REAR FLOOR, NO.1	NOT NECESSARY	502.20	-
1	BOX, DECK FLOOR, LH	NOT NECESSARY	303.40	-
1	BOX, DECK FLOOR, RH	NOT NECESSARY	304.00	-
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	COVER, REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
10	CLIP, FLOOR UNDER COVER, NO.1 @\$2.60	NOT NECESSARY	26.00	-
10	CLIP, FLOOR UNDER COVER, NO.2 @\$3.20	NOT NECESSARY	32.00	-
1	LINER, REAR FENDER, RH	NOT NECESSARY	135.80	-
1	END PANEL, COVER, DECK TRIM SERVICE HOLE	NOT NECESSARY	47.00	-
1	END PANEL, COVER, DECK TRIM, REAR	NOT NECESSARY	122.80	-

Report Ref No. CS/EG18011692/Dsd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
			12,796.50	4,538.15
	LABOUR			
	PANEL BEATING & BODY WORK.		1,521.00	1,260.00
	SPRAY PAINT.		1,854.00	880.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	50.00
	TO REMOVE AND REFIT WIRE HARNESS.		250.00	120.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	60.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	60.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.		180.00	100.00
			4,405.00	2,550.00
GRAND TOTAL			17,201.50	7,088.15

RECOMMENDED COST OF REPAIRS			7,088.15
------------------------------------	--	--	-----------------

Report Ref No. CS/EGI18011692/Dsd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.