

ASS. REC. BY:

REF: cs/FCI18011696/Klrds/72

Special Instruction:

Surveyor

CWS

Kalvin

ASSIGNMENT (Office)

From (Person):

May chuan

of

FCI

Date/Time:

26/6/18 @ 5:37pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 68744

Insured:

SHA 4370E

at Workshop m/s

Premier Automotive

Tel:

6544 6689

of

23 chungi south Ave 2 # 03-02

Policy No:

Claim No:

D18004995MFSH

Sum Insured:

Excess:

Make of Vch:

D.O.A.

24/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement

Date/Time:

9:43am @ 27/6/18

Person Contacted:

Vincent

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 68744 - NA/INC/18011063/h4

DOA: 18/06/2018

SHA 4370 E - cc3/AIG/17011562/M/wq3s2

DOA: 10/06/2017

(08/11/13)

Surveyor: Kalvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 68744 Yr Regn: 3 Oct / 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Tr~~ / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1635Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 304727 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAH M414ME54 69056Gen. Cond: Good / ~~Fair~~ / Poor / BurntSteering: In order / ~~Jammed~~ / Leaked / Burnt orBrake: In order / ~~Jammed~~ / Leaked / Burnt orModi: Nil / S/Rim / ~~STD~~ / Rim orTyre Size: F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 24/6/18 D.O.I. 27/6/18Survey held at Premis

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS R4

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/7/18 Librant P11 \$450 / 2 Pgs. FCZRed. 8 680, 63% 4.

RECEIVED 26 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Report Format: TPLump Sum / I.B.I: (\$ 400)

100

50

50

19

219



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004995MFSH

Our Ref: CS/FCI18011696/K1rd3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6874U .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.06.2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,080.00</u> .
Revised Estimate Amount	: S\$ <u>400.00</u> .
"Check" Items Amount	: S\$ <u>          </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:  
The vehicle sustained damages  
at n/s body.



Yours faithfully  
KALVIN  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	26-06-2018	Our Ref No.	D18004995MFSH
Accident Date	24-06-2018	Claim Type.	Third Party
Insured Vehicle	SHA4370E	Third Party Vehicle.	SHC6874U
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	VINCENT CHUA		
Contact No.	62148880/ 65446689	Fax No.	62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	03 Oct 2014 / 09:22:31	Receipt No.:	AACCK001-AX239-141003-000012
Asset Type:	Vehicle	Transaction Amount:	\$63,191.00
Asset ID:	SHC6874U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141003092231656853		
Vehicle No.:	SHC6874U		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	03 Oct 2014		
Original Registration Date:	03 Oct 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5469056		
Engine No.:	D4FDDH309745		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,613.00		
Minimum PARF Benefit:	\$7,267.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	03 Oct 2014 09:22:31		
COE No.:	2014100301001158E		
COE Expiry Date:	02 Oct 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,938.00		
Lifespan Expiry Date:	02 Oct 2022		
Owner ID Type:	Company		

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

27-Jun-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6874 U

### S/NETT

1 set	n/s door stickers ✓ <i>me</i>	\$	100.00
	Sundry <i>new</i>	\$	<del>50.00</del> 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> <i>Xnn</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s door, etc.	\$	<del>450.00</del> 100
	To putty and spray painting on front n/s door	\$	<del>200.00</del> 180
	To apply rustproofing on the repaired and replaced panels.	\$	<del>100.00</del> <i>Xnn</i>
		\$	<u>1,080.00</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*Kabri 11114*  
*M 27/6/18 0935h*  
*2h*  
*45*  
*After Rep photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts after resurvey
- Parts prices are subject to final quotation
- Third party survey is on a "without prejudice" basis
- No illegal modification allowed
- Supplementary work must be involved and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011696/K1rd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 4370E	Veh. Inspected	SHC 6874U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004995MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	26/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5469056	Colour	SILVER	
Odometer	304727	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/06/2018	Inspection Date	27/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6874U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	SET N/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			150.00	120.00
	<b>LABOUR</b>			
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT N/S DOOR, ETC.		450.00	100.00
	TO PUTTY AND SPRAY PAINTING ON FRONT N/S DOOR.		200.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	100.00	-
			930.00	280.00
	<b>GRAND TOTAL</b>		<b>1,080.00</b>	<b>400.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>400.00</b>

Report Ref No. CS/FCI18011696/K1rd3n2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**ADRIAN LING WAI PING****B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.