

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR CHEW YOONG KEONG

DATE: 26/06/2018

DOA : 07/06/2018

ESTIMATE REPAIR FOR VEHICLE NO. SKB 1189 S (HYUNDAI ELANTRA)

	Description	List Price
1 pc	Rear bumper <i>De / warped</i>	\$ 446.40
2 pcs	Bumper side retainer @S\$32.00 <i>an</i>	\$ 64.00 <i>X</i>
10 pcs	Bumper clips @S\$5.50 <i>me</i>	\$ 55.00
		\$ 565.40
	Less : 20%	\$ (113.08)
		\$ 452.32
	Special Nett Items	
	Labour charges for knocking & replacing parts.	\$ 200.00 <i>100</i>
	Spraypainting	\$ 300.00 <i>200</i>
	TOTAL :	\$ 952.32

701.4
401.2

701.12
560.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

W, + Approval
2/6/18
27/6/18
After repair
2 day.
Ms