



Kp

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

KOH INTERIOR DESIGN & FURNISHING

Estimate : ES006385

Attention : THE OWNER
Contact : 65636832 98159078

Not Attached
11 Sep @ Good
Assembly After Part
6 days

Date : 26/06/2018
Vehicle Num. : GBH1886M
Make/Model : TOYOTA PROACE COMFORT COMP
Chassis/Eng#: YARVBBHVBGZ104423/BH02002408E
Accident Date : 26/06/2018
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR DOOR L/H	2,169.00	2,169.00
2.	1	REAR DOOR GLASS MOULDING L/H	125.00	125.00
3.	1	REAR DOOR INNER TRIM L/H	365.00	365.00
4.	1	REAR DOOR INNER LOCK L/H	388.00	388.00
5.	1	TOYOTA LOGO	69.20	69.20
6.	1	TOYOTA EMBLEM	61.00	61.00
7.	1	TAIL LAMP L/H	682.00	682.00
8.	1	REAR DOOR R/H	2,155.00	2,155.00
9.	1	REAR DOOR VERTICAL EDGE RUBBER SEAL R/H	232.00	232.00
10.	1	REAR DOOR GLASS MOULDING R/H	125.00	125.00
11.	1	REAR DOOR INNER TRIM R/H	365.00	365.00
12.	1	REAR DOOR LOCK R/H	388.00	388.00
13.	1	PROACE EMBLEM	63.00	63.00
14.	1	REAR BUMPER	952.00	952.00
15.	2	REAR BUMPER BRACKET	138.00	276.00
16.	2	REAR BUMPER SIDE RETAINER	114.00	228.00
17.	6	REAR BUMPER CLIP	6.00	36.00
18.	1	REAR END PANEL	983.00	983.00
19.	1	REAR END PANEL RE-INFORCEMENT	865.00	865.00
20.	1	REAR BUMPER TOW COVER	36.00	36.00
21.	1	REAR DOOR SURROUND RUBBER SEAL	213.00	213.00
22.	1	ACCESSORIES CABINET DRAWER LOCK L/H	75.00	75.00

List TotalS\$:

25.00% Discount S\$:

10,851.20

2,712.80

8,138.40

1. 1 SPECIAL NETT ITEMS :
REAR DOOR GLASS SEALANT L/H

65.00 *Gas*

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Email : darren@completevms.com.sg ()
 Lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

KOH INTERIOR DESIGN & FURNISHING

Estimate : ES006385

Attention : THE OWNER
 Contact : 65636832 98159078

Date : 26/06/2018
 Vehicle Num. : GBH1886M
 Make/Model : TOYOTA PROACE COMFORT COMP
 Chassis/Eng# : YARVBBHVBGZ104423/BH02002408E
 Accident Date : 26/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR NUMBER PLATE <i>(Com type)</i>	<i>Na</i> 25.00	<i>✓</i>
3.	1	REAR DOOR GLASS SEALANT R/H	<i>Na</i> 65.00	<i>400</i>
4.	1	REVERSE SENSOR SET	<i>Na</i> 280.00	<i>2000</i>
5.	1	70 KM/H STICKER	<i>Na</i> 15.00	<i>✓</i>
6.	1	5 PAX STICKER	<i>Na</i> 15.00	<i>✓</i>
Special Nett Total S\$:				465.00
LABOUR :				
REMOVE & REINSTALL REAR DOOR GLASS L/H			150.00	<i>600</i>
REMOVE & REINSTALL REAR DOOR GLASS R/H			150.00	<i>600</i>
RUST PROOFING TREATMENT			100.00	<i>600</i>
TRANSFER SIDE DOOR COMPONENTS TO NEW DOOR L/H			120.00	<i>600</i>
TRANSFER SIDE DOOR COMPONENTS TO NEW DOOR R/H			120.00	<i>600</i>
SPRAY PAINT DAMAGED AREA AFFECTED			120.00	<i>600</i>
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS			<i>800</i> 1,100.00	
Labour Total S\$:			1,100.00	<i>550</i>
				2,840.00

SingDollars - Eleven Thousand Four Hundred Forty-Three & Cents Forty Only

Total S\$: 11,443.40
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun