

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHC 5790J

AAD1806-157

Not Authorized
11 Sep @ 2450hr

Vehicle No.:	SHC 5790J
Chassis No.:	VF1ABL15AUC280910
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	15.6.2018
Third Party Insurer :	Alh

PART	LIST
1 1 BUMPER COVER REAR	\$ <i>Bucina</i> 1,108.46 —
2 1 BUMPER LOWER REAR	\$ <i>nd</i> 768.84 —
3 1 BUMPER BRACKET CTR REAR	\$ <i>sn</i> 113.47 X
4 1 BUMPR BRACKET SIDE RH REAR	\$ <i>sn</i> 135.97 X
5 1 BUMPR RETAINER RH REAR	\$ <i>sn</i> 44.99 X
6 1 BUMPER REFLECTOR RH	\$ <i>cm</i> 43.61 —
7 1 BUMPR BRACKET SIDE LH REAR	\$ <i>sn</i> 135.97 X
8 1 BUMPR RETAINER LH REAR	\$ <i>sn</i> 44.99 X
9 1 BUMPER REFLECTOR LH	\$ <i>sn</i> 43.61 X
10 1 BUMPER BEAM REAR	\$ <i>sn</i> 777.52 X
11 1 BUMPER BEAM BRACKET LH REAR	\$ <i>n</i> 225.95 X
12 1 BUMPER BEAM BRACKET RH REAR	\$ <i>n</i> 225.95 X
13 1 BOOT REAR	\$ <i>n</i> 2,872.68 } X
14 1 BOOT FINISHER	\$ <i>sn</i> 470.06 }
15 1 BOOT WHEATERSTRIP	\$ <i>sn</i> 323.05 }
16 1 BOOT REFLECTOR LAMP LH	\$ <i>sn</i> 493.35 }
17 1 BOOT REFLECTOR LAMP RH	\$ <i>sn</i> 493.35 }
18 1 BOOT BADGE 'RENAULT'	\$ <i>nn</i> 225.36 }
19 1 BOOT BADGE	\$ <i>nn</i> 225.36 }
20 1 BOOT STRUT LH	\$ <i>sn</i> 276.08 }
21 1 BOOT STRUT RH	\$ <i>sn</i> 276.08 }
22 1 BOOT HINGE LH	\$ <i>n</i> 367.84 }
23 1 BOOT HINGE RH	\$ <i>n</i> 367.84 }
24 1 BOOT INNER TRIM	\$ <i>sn</i> 586.45 }
25 1 BOOT SWITCH	\$ <i>sn</i> 168.13 }
26 1 BOOT LOCK	\$ <i>n</i> 202.67 }
27 1 BOOT LOCK CATCH	\$ <i>n</i> 74.40 }
28 2 LICENCE PLATE LAMP	\$ <i>sn</i> 50.52 }
29 2 BOOT RUBBER PLUG	\$ <i>sn</i> 221.81 }

Trans-cab Auto Services Pte Ltd

AAD1806-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5790J

30	1 DOOR PANEL REAR LH	\$	<i>R</i>	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i>	671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i>	671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	
37	1 TAILLAMP RH	\$	<i>Sn</i>	552.55	
38	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	
39	1 TAILLAMP LH	\$	<i>Sn</i>	552.55	
40	1 TAILLAMP PANEL LH	\$	<i>R</i>	986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i>	404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	
45	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	
46	1 EXHAUST CAP REAR	\$	<i>R</i>	230.49	
47	1 FUEL FLAP L70Y	\$	<i>Sn</i>	343.57	

TOTAL	\$	39,057.17
10%	\$	3,905.72
	\$	35,151.45

Special Nett

1	1SET PARKING AID	\$	<i>Sn</i>	700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	✓
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>na</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	X
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5790J

14	1 BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00	}
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i> 35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i> 35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00	
19	1 TAILLAMP CLIP RH	\$	<i>na</i> 5.00	
20	1 TAILLAMP CLIP LH	\$	<i>na</i> 5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00	
22	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00	}
25	1 SPARE TYRE	\$	<i>sn</i> 330.00	

TOTAL \$ 2,225.02

TOTAL PARTS \$ 37,376.47

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1806-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5790J

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>m</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>↪</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>↪</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>↪</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	X
TOTAL	\$	12,540.00	

Over All Total	\$	49,916.47
-----------------------	-----------	------------------

(LUMP SUM)

Repair Days

~~20 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: