

SMRT Accident Vehicle Repair Estimates

G/A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5465D
 Ref. No : TAX/06/18/2106
 Reg. Date : 30/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LAU CHOON HOCK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 24/06/2018 07:45:00 PM
 Accident Reported Date / Time : 25/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 24/06/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096688
 Special Instruction to ARC, if any :
 TOWED \$40 / SJT5772Z
 Prepared Date : 25/06/2018 12:30:05 PM



Sathya Sai

26/6/2018

93072012

Sathya Sai @ lkkauto.com

- Part by Part repair
- Question mark item photo
- photo before paint

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal work to be carried out
- Supplemental work to be surveyed and is subject to final approval from Insurance Company

Acknowledged by: _____
 Signature: _____
 Date: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603575605

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,854.00	0.00
Total Material Charges :	4,571.15	4,571.15
Other Charges :	1,036.00	0.00
TOTAL :	8,475.15	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00 3 days
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	26/06/2018 08:43:22 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/06/2018 08:43:12 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY FUEL LID COVER	180.00	0.00 100
TO RESPRAY RIM	180.00	0.00 100
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 100
Total Spray Painting & Panel Beating	1,854.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 60
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE & REFIT FUEL TANK	120.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,036.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6700447210			PANEL SUB-ASSY, REAR DOOR, LH R	1	1,243.90	25.00	932.92	Replace	Replace	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH R	1	576.00	25.00	432.00	Replace	Replace	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH R	1	824.80	25.00	618.60	Replace	Replace	No
7735047050			LID ASSY, FUEL FILLER OPENING ✓scr	1	164.10	25.00	123.07	Replace	Replace	No
			TYRE X	1	126.74	0.00	126.74	Replace	Replace	No
4261147450			WHEEL, DISC ✓mt	1	1,555.10	25.00	1,166.32	Replace	Replace	No
6563847060			LINER, REAR FENDER, LH ?	1	135.80	25.00	101.85	Replace	Replace	No
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH ?	1	438.10	10.00	394.29	Replace	Replace	No
5215947913			COVER, RR BUMPER ASSY R	1	423.90	25.00	317.92	Replace	Replace	No
5256647900			FILLER, RR BUMPER, LH ✓scr	1	119.90	25.00	89.92	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH ?	1	111.50	25.00	83.62	Replace	Replace	No
5259247040			SEAL, RR BUMPER, LH ?	1	85.20	25.00	63.90	Replace	Replace	No
			PIXEL STICKER ✓NEL	2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS								4,571.18	4,571.15	
TOTAL MATERIALS(Discounted)								4,571.15	4,571.15	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									