

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8790 U

1 pc	Front bumper <i>x repair</i>	\$	531.00
1 pc	Front bumper o/s side retainer @ \$16.00 <i>x</i>	\$	16.00
1 pc	Front bumper o/s protector @ \$51.00 <i>x</i>	\$	51.00
1 pc	Front bumper emblem @ \$44.00 <i>x</i>	\$	44.00
1 pc	Front bumper o/s fog lamp cover @ \$66.00 <i>x</i>	\$	66.00
1 pc	Front o/s fender inner shield @ \$120.00 <i>x</i>	\$	120.00
		\$	828.00
	Less 10%	\$	82.80
		\$	745.20

S/NETT

1 set	Front bumper clips <i>x</i>	\$	48.00
1 set	Front o/s fender inner shield clips <i>x</i>	\$	28.00

Sundry

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~50.00~~
20

\$ ~~180.00~~ *x*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.

\$ ~~500.00~~
160

To putty and spray painting on front bumper, front o/s fender

\$ ~~500.00~~
180

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ *x*

\$ 2,171.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalwa Uday
26/6/18 1315hrs
2 R,
PIP
Ashar R...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____