



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR CENTRAL FOOD MANAGEMENT  10 ANSON RD #26-04 INTERNATIONAL PLAZA SINGAPORE 079903  Contact No Mobile: 87183170	Cust No/Name	/MR CENTRAL FOOD MANAGEMENT
	Reg No/Reg Date	SLS215E / 05/09/201
	Date In/Mileage	/ 0
	Chassis No	KNACC81CVJ5102842
	Engine No	G4LEHS231561
	Make/Model	KIA/NIRO 1.6 A G979
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	26/06/2018/ 11:12	TLC	442 / CocoLu	30992

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER, REAR BUMPER LOWER PANEL, REPAIR REAR END PANEL				550 1650.00
E PNT98000 TO SPRAY PAINT FOR REAR BUMPER, REAR END PANEL				420 1260.00
E PNT88000 TO REMOVE & INSTALL PARKING SENSOR				60 100.00
A 90000001 TO CHECK WIRING & ELECTRICAL SYSTEM				✓ 20.00
A 90000001 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				✓ 200.00
M SUNDRY Sundry				✓ 20.00
P COVER-RR BUMPER,UPR	1.00	423.00	00.00	de 423.00
M COVER-RR BUMPER LWR	1.00	392.00	00.00	de 392.00
M SKID PLATE-RR BUMPER	1.00	122.00	00.00	? 122.00
M PIECE-RR BUMPER SIDE,LH	1.00	16.00	00.00	de 16.00
M COVER-RR BUMPER SIDE UNDER,LH	1.00	27.00	00.00	? 27.00
M REFLECTOR/REFLEX ASSY-RR LH	1.00	104.00	00.00	? 104.00
M MOULDING ASSY-RR BUMPER SIDE,L	1.00	20.00	00.00	? 20.00
M SENSOR ASSY-PACK ASSIST SYSTEM	1.00	135.00	00.00	? 135.00
M BRACKET ASSY-RR BUMPER SIDE,LH	1.00	25.00	00.00	? 25.00
M BEAM-RR BUMPER	1.00	261.00	00.00	? 261.00
M BRACKET-RR RAIL LWR MTG	1.00	6.00	00.00	? 6.00
M BRACKET-RR BEAM UPR MTG,LH	1.00	6.00	00.00	? 6.00
M STAY-RR BUMPER LH	1.00	67.00	00.00	? 67.00
M ANTENNA ASSY-SMARTKEY	1.00	39.00	00.00	? 39.00

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

LKK Auto Consultants hence notify  
the Repairer of the following:

- Confirm & accepted by
- To repair before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Authorized signatory and company stamp

7% GST on

Nett	4,893.00
	342.51
<b>Total Payable</b>	<b>5,235.51</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.